

---

## CONTENTS

---

Alternators	1-40
Rotors	41-43
Stators	44-46
D.E. Brackets	47-53
S.R.E. Brackets	54-58
Covers	59-62
Brush Holders	63-64
Sliprings	65-68
Rectifiers	69-70
Diodes Trios	71-72
Rectifier Mounting Parts	73-74
Bearing Caps & Regulator Parts	75-78
Insulators	79-84
Mounting Bushing & Kits	85-87
Pulleys	88
Fans	89-90
Thru Bolts	91-92
Sundry Items	93-97
Vacuum Pumps & Generator Brackets & Component	98
Starters	99-100
Field Coils, Armatures & Clutches	101
C.E. Brackets	102-108
I.M. Brackets	109
D.E. Brackets	110-113
Solenoid Caps	114-132
Solenoid Contact & Kits	133-143
Drives & Parts	144
Gear Tracks	145
Shift Levers	146-148
Brush Holders	149-154
Terminals	155-159
Covers	160-161
Brake & Washer Kits	162
Starters Sundry Parts	163-167
Modified Type Alternator Brackets	168
Modified Type Starter Components	169

## LIST OF NUMBERS

Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page
AL 00001	144	AL 00066	85	AL 00130	96	AL 00196		AL 00261		AL 00321	126
AL 00002	144	AL 00067		AL 00131	86	AL 00197	141	AL 00262	122	AL 00322	137
AL 00003	162	AL 00068		AL 00132	88	AL 00198	61	AL 00263	124	AL 00323	125
AL 00004	82	AL 00069	82	AL 00133	167	AL 00199	59	AL 00264	124	AL 00324	121
AL 00005	158	AL 00070	79	AL 00134	96	AL 00200	61	AL 00265	87	AL 00325	137
AL 00006	158	AL 00071	79	AL 00135	-	AL 00201		AL 00266	141	AL 00326	138
AL 00007	134	AL 00072	96	AL 00136	166	AL 00202	64	AL 00267	129	AL 00327	138
AL 00008	141	AL 00073	96	AL 00137	92	AL 00203	78	AL 00268	137	AL 00328	135
AL 00009	141	AL 00074	82	AL 00138	157	AL 00204	82	AL 00269	137	AL 00329	138
AL 00010	82	AL 00075	91	AL 00139	157	AL 00205	86	AL 00270	114	AL 00330	125
AL 00011	81	AL 00076	87	AL 00140	148	AL 00206	86	AL 00271	139	AL 330/A	126
AL 00012	81	AL 00077	87	AL 00141	166	AL 00207	141	AL 00272	119	AL 330/B	138
AL 00013	81	AL 00078	86	AL 00142		AL 00208		AL 00273	120	AL 00331	150
AL 00014	145	AL 00079	87	AL 00143	159	AL 00209	160	AL 00274	120	AL 00332	114
AL 00015	166	AL 00080	87	AL 00144	159	AL 00210	89	AL 00275	120	AL 00333	125
AL 00016	166	AL 00081	87	AL 00145		AL 00211	89	AL 276/A	134	AL 00334	132
AL 00017	166	AL 00082	85	AL 00146		AL 00212		AL 276/B	134	AL 00335	121
AL 00018	81	AL 00083	85	AL 00147	60	AL 00213		AL 277/A	134	AL 00336	121
AL 00019	81	AL 00084	85	AL 00148	60	AL 00214		AL 277/B	134	AL 00337	121
AL 00020	89	AL 00085	85	AL 00149	88	AL 00215	124	AL 278/A	134	AL 00338	125
AL 00021		AL 00086	85	AL 00150		AL 00216	137	AL 278/B	134	AL 00339	115
AL 00022		AL 00087	79	AL 00151	148	AL 00217		AL 00279	139	AL 00340	115
AL 00023		AL 00088	82	AL 00152		AL 00218	124	AL 00280	139	AL 00341	125
AL 00024	163	AL 00089	79	AL 00153	66	AL 00219	124	AL 00281	139	AL 00342	131
AL 00025	83	AL 00090	63	AL 00154	77	AL 00220	-	AL 00282	139	AL 00343	121
AL 00026		AL 00091	167	AL 00155	77	AL 00221	-	AL 00283	133	AL 00344	115
AL 00027		AL 091/S	167	AL 00156		AL 00222		AL 00284	133	AL 00345	125
AL 00028	158	AL 091/C	167	AL 00157	162	AL 00223		AL 00285	133	AL 00346	125
AL 00029	158	AL 00092	158	AL 00158		AL 00224		AL 00286	114	AL 00347	115
AL 00030	158	AL 00093	63	AL 00159	79	AL 00225		AL 00287	114	AL 00348	115
AL 00031	144	AL 00094	63	AL 00160	146	AL 00226		AL 00288	114	AL 00349	115
AL 00032	144	AL 00095	63	AL 00161		AL 00227		AL 00289	114	AL 00350	115
AL 00033	145	AL 00096	79	AL 00162		AL 00228		AL 00290	114	AL 00351	115
AL 00034	145	AL 00097	80	AL 00163	79	AL 00229		AL 00291	130	AL 00352	115
AL 00035	85	AL 00098	64	AL 00164	80	AL 00230		AL 291/A	130	AL 00353	115
AL 00036		AL 00099	63	AL 00165	89	AL 00231	165	AL 00292	114	AL 00354	115
AL 00037	85	AL 00100	63	AL 00166	89	AL 00232	139	AL 00293	140	AL 00355	115
AL 00038	87	AL 00101	79	AL 00167		AL 00233		AL 00294	120	AL 00356	130
AL 00039	85	AL 00102	158	AL 00168		AL 00234	158	AL 00295	130	AL 00357	130
AL 00040	85	AL 00103	96	AL 00169	80	AL 00235	139	AL 00296	114	AL 00358	130
AL 00041	85	AL 00104	96	AL 00170		AL 00236		AL 00297	140	AL 358/A	130
AL 00042	85	AL 00105	161	AL 00171	166	AL 00237	127	AL 00298	132	AL 00359	130
AL 00043	87	AL 00106		AL 00172	80	AL 00238	122	AL 00299	120	AL 00360	130
AL 00044		AL 00107		AL 00173		AL 00239	129	AL 00300	137	AL 00361	130
AL 00045		AL 00108		AL 00174		AL 00240	129	AL 00301	124	AL 00362	124
AL 00046	83	AL 00109	162	AL 00175	88	AL 00241	139	AL 00302		AL 00363	124
AL 00047	83	AL 00110		AL 00176	86	AL 00242	114	AL 00303		AL 00364	131
AL 00048	75	AL 00111	63	AL 00177	136	AL 00243	114	AL 00304	119	AL 00365	132
AL 00049	167	AL 00112	74	AL 00178		AL 00244	136	AL 00305		AL 00366	121
AL 00050		AL 00113	91	AL 00179	163	AL 00245		AL 00306	98	AL 00367	133
AL 00051	166	AL 00114		AL 00180		AL 245/A	136	AL 00307	157	AL 00368	133
AL 00052		AL 00115	74	AL 00181		AL 00246	124	AL 00308	119	AL 00369	133
AL 00053	148	AL 00116	147	AL 00182	166	AL 00247	122	AL 00309	157	AL 00370	133
AL 054/A	81	AL 00117	163	AL 00183	76	AL 00248	140	AL 00310	136	AL 00371	133
AL 054/B	81	AL 00118	148	AL 00184	76	AL 00249	137	AL 00311	130	AL 00372	135
AL 00055	81	AL 00119	148	AL 00185	76	AL 00250	127	AL 311/A	130	AL 00373	140
AL 00056	161	AL 00120	91	AL 00186	98	AL 00251	129	AL 00312	124	AL 00374	140
AL 00057	161	AL 00121	148	AL 00187	147	AL 00252	127	AL 00313	114	AL 00375	138
AL 00058	162	AL 00122		AL 00188	77	AL 00253	129	AL 00314	125	AL 00376	116
AL 00059	150	AL 00123	66	AL 00189	75	AL 00254	129	AL 00315	126	AL 00377	123
AL 00060	82	AL 00124	79	AL 00190		AL 00255	121	AL 00316	137	AL 00378	123
AL 00061	82	AL 00125	141	AL 00191		AL 00256	141	AL 00317		AL 00379	120
AL 00062	146	AL 00126	88	AL 00192	163	AL 00257	141	AL 00318		AL 00380	131
AL 00063	147	AL 00127	80	AL 00193	76	AL 00258	80	AL 318/A	136	AL 00381	116
AL 00064	161	AL 00128		AL 00194	61	AL 00259	83	AL 00319		AL 00382	122
AL 00065	86	AL 00129	96	AL 00195		AL 00260	76	AL 00320	125	AL 00383	122

## LIST OF NUMBERS

Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page
AL 00384	122	AL 00450		AL 00515		AL 00581		AL 00647	75	AL 00713	59
AL 00385	132	AL 00451		AL 00516		AL 00582		AL 00648	47	AL 00714	50
AL 00386	125	AL 00452		AL 00517		AL 00583		AL 00649	73	AL 00715	56
AL 00387	116	AL 00453		AL 00518		AL 00584		AL 00650	87	AL 00716	
AL 00388	116	AL 00454		AL 00519		AL 00585		AL 00651		AL 00717	
AL 00389	131	AL 00455		AL 00520		AL 00586		AL 00652		AL 00718	
AL 00390	116	AL 00456		AL 00521		AL 00587	75	AL 00653		AL 00719	
AL 00391	116	AL 00457		AL 00522	137	AL 00588	75	AL 00654	91	AL 00720	47
AL 00392	116	AL 00458		AL 00523	165	AL 00589	77	AL 00655	73	AL 00721	
AL 00393	116	AL 00459		AL 00524	165	AL 00590	77	AL 00656	94	AL 00722	57
AL 00394	116	AL 00460		AL 00525		AL 00591	77	AL 00657	163	AL 00723	52
AL 00395	116	AL 00461		AL 00526	165	AL 00592	77	AL 00658	160	AL 00724	61
AL 00396	136	AL 00462		AL 00527	165	AL 00593	76	AL 00659	94	AL 00725	107
AL 00397	140	AL 00463		AL 00528	137	AL 00594	98	AL 00660	59	AL 00726	107
AL 00398	135	AL 00464		AL 00529		AL 00595	77	AL 00661	94	AL 00727	106
AL 00399	131	AL 00465		AL 00530		AL 00596	106	AL 00662	59	AL 00728	107
AL 00400	42	AL 00466		AL 00531		AL 00597	94	AL 00663	56	AL 00729	112
AL 00401	42	AL 00467		AL 00532		AL 00598	98	AL 00664	47	AL 00730	54
AL 00402	42	AL 00468		AL 00533		AL 00599	160	AL 00665	47	AL 00731	47
AL 00403	41	AL 00469		AL 00534		AL 00600	74	AL 00666	50	AL 00732	47
AL 00404	41	AL 00470		AL 00535		AL 00601	73	AL 00667	50	AL 00733	54
AL 00405	41	AL 00471		AL 00536		AL 00602	73	AL 00668	57	AL 00734	107
AL 00406	41	AL 00472		AL 00537		AL 00603		AL 00669	57	AL 00735	107
AL 00407		AL 00473		AL 00538		AL 00604		AL 00670	56	AL 00736	47
AL 00408		AL 00474	43	AL 00539		AL 00605		AL 00671	165	AL 00737	45
AL 00409		AL 00475		AL 00540		AL 00606		AL 00672	-	AL 00738	
AL 00410		AL 00476		AL 00541		AL 00607		AL 00673		AL 00739	
AL 00411	42	AL 00477		AL 00542		AL 00608		AL 00674		AL 00740	50
AL 00412		AL 00478		AL 00543		AL 00609		AL 00675		AL 00741	53
AL 00413		AL 00479		AL 00544		AL 00610		AL 00676	47	AL 00742	69
AL 00414		AL 00480		AL 00545		AL 00611	146	AL 00677	168	AL 00743	110
AL 00415	41	AL 00481		AL 00546		AL 00612	146	AL 00678	61	AL 00744	54
AL 00416		AL 00482		AL 00547		AL 00613	146	AL 00679		AL 00745	47
AL 00417		AL 00483		AL 00548		AL 00614	146	AL 00680		AL 00746	151
AL 00418		AL 00484		AL 00549		AL 00615	146	AL 00681		AL 00747	151
AL 00419		AL 00485		AL 00550		AL 00616	146	AL 00682		AL 00748	109
AL 00420	44	AL 00486	101	AL 00551		AL 00617	146	AL 00683		AL 00749	107
AL 00421		AL 00487	101	AL 00552		AL 00618	146	AL 00684		AL 00750	
AL 00422	41	AL 00488	101	AL 00553		AL 00619	160	AL 00685		AL 00751	
AL 00423		AL 00489	43	AL 00554		AL 00620		AL 00686		AL 00752	107
AL 00424		AL 00490	41	AL 00555	157	AL 00621	166	AL 00687		AL 00753	69
AL 00425		AL 00491	43	AL 00556	157	AL 00622		AL 00688		AL 00754	104
AL 00426		AL 00492	42	AL 00557	157	AL 00623		AL 00689	166	AL 00755	50
AL 00427		AL 00493		AL 00558	165	AL 00624		AL 00690	59	AL 00756	106
AL 00428		AL 00494		AL 00559		AL 00625		AL 00691	54	AL 00757	108
AL 00429	41	AL 00995		AL 00560		AL 00626		AL 00692	54	AL 00758	106
AL 00430		AL 00496		AL 00561		AL 00627		AL 00693	47	AL 00759	104
AL 00431	43	AL 00497		AL 00562		AL 00628		AL 00694	150	AL 00760	52
AL 00432	41	AL 00498	44	AL 00563		AL 00629	86	AL 00695	160	AL 00761	
AL 00433		AL 00499	44	AL 00564		AL 00630		AL 00696	168	AL 00762	47
AL 00434		AL 00500	138	AL 00565		AL 00631		AL 00697	54	AL 00763	47
AL 00435	42	AL 00501	138	AL 00566		AL 00632	74	AL 00698	54	AL 00764	45
AL 00436	42	AL 00502		AL 00567	165	AL 00633	86	AL 00699	50	AL 00765	69
AL 00437		AL 00503	138	AL 00568		AL 00634	50	AL 00700	108	AL 00766	
AL 00438		AL 00504	138	AL 00669		AL 00635	56	AL 00701	168	AL 00767	104
AL 00439		AL 00505		AL 00570		AL 00636	98	AL 00702		AL 00768	
AL 00440		AL 505/C		AL 00571		AL 00637		AL 00703	112	AL 00769	45
AL 00441		AL 00506	138	AL 00572		AL 00638		AL 00704	112	AL 00770	56
AL 00442		AL 00507		AL 00573		AL 00639		AL 00705	51	AL 00771	109
AL 00443		AL 00508	138	AL 00574		AL 00640	50	AL 00706	150	AL 00772	149
AL 00444		AL 00509		AL 00575		AL 00641		AL 00707		AL 00773	50
AL 00445		AL 00510		AL 00576		AL 00642	98	AL 00708	150	AL 00774	112
AL 00446		AL 00511		AL 00577		AL 00643	94	AL 00709		AL 00775	112
AL 00447		AL 00512		AL 00578		AL 00644	94	AL 00710	52	AL 00776	112
AL 00448		AL 00513		AL 00579		AL 00645	88	AL 00711	61	AL 00777	112
AL 00449		AL 00514		AL 00580		AL 00646	73	AL 00712	62	AL 00778	113

## LIST OF NUMBERS

Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page	Albi-No	Page
AL 00779		AL 00844	113	AL 00910	65	AL 00976		AL 01042		AL 01109	167
AL 00780	54	AL 00845	113	AL 00911	161	AL 00977		AL 01043		AL 01110	
AL 00781	113	AL 00846	112	AL 00912	65	AL 00978		AL 01044		AL 01111	
AL 00782	113	AL 00847		AL 00913	162	AL 00979		AL 01045		AL 01112	
AL 00783	48	AL 00848	44	AL 00914		AL 00980		AL 01046		AL 01113	
AL 00784	44	AL 00849	45	AL 00915	71	AL 00981		AL 01047	69	AL 01114	
AL 00785		AL 00850		AL 00916	71	AL 00982		AL 01048	70	AL 01115	167
AL 00786	112	AL 00851		AL 00917	71	AL 00983		AL 01049	26	AL 01116	167
AL 00787	104	AL 00852		AL 00918	71	AL 00984	65	AL 01050	27	AL 01117	
AL 00788	149	AL 00853	45	AL 00919		AL 00985	88	AL 01051	28	AL 01118	
AL 00789	56	AL 00854		AL 00920		AL 00986	152	AL 01052		AL 01119	
AL 00790	45	AL 00855		AL 00921	69	AL 00987	88	AL 01053	30	AL 01120	39
AL 00791	45	AL 00856	109	AL 00922	65	AL 00988	91	AL 01054	40	AL 01121	31
AL 00792	56	AL 00857	52	AL 00923	65	AL 00989	94	AL 01055	16	AL 01122	
AL 00793	44	AL 00858	57	AL 00924	65	AL 00990		AL 01056	7	AL 01123	39
AL 00794	44	AL 00859	106	AL 00925	67	AL 00991	94	AL 01057	15	AL 01124	
AL 00795	107	AL 00860	57	AL 00926	71	AL 00992	94	AL 01058	40	AL 01125	40
AL 00796	149	AL 00861	168	AL 00927	72	AL 00993	98	AL 01059	39	AL 01126	
AL 00797	151	AL 00862	61	AL 00928	68	AL 00994	89	AL 01060		AL 01127	34
AL 00798		AL 00863	168	AL 00929	68	AL 00995	89	AL 01061		AL 01128	35
AL 00799	112	AL 00864	51	AL 00930	67	AL 00996	89	AL 01062	14	AL 01129	36
AL 00800	112	AL 00865	54	AL 00931	77	AL 00997	75	AL 01063	69	AL 01130	
AL 00801	168	AL 00866		AL 00932	72	AL 00998	75	AL 01066		AL 01131	
AL 00802		AL 00867	48	AL 00933	151	AL 00999	71	AL 01065		AL 01132	
AL 00803	42	AL 00868	48	AL 00934	151	AL 01000	19	AL 01066		AL 01133	
AL 00804	44	AL 00869	54	AL 00935		AL 01001	20	AL 01067		AL 01134	
AL 00805	56	AL 00870	48	AL 00936	75	AL 01002	21	AL 01068		AL 01135	37
AL 00806	168	AL 00871	51	AL 00937		AL 01003		AL 01069		AL 01136	
AL 00807	113	AL 00872	51	AL 00938	67	AL 01004	22	AL 01070		AL 01137	
AL 00808	48	AL 00873	149	AL 00939	66	AL 01005		AL 01072		AL 01138	38
AL 00809	149	AL 00874	149	AL 00940	67	AL 01006		AL 01073		AL 01139	
AL 809/A	149	AL 00875	53	AL 00941	68	AL 01007	40	AL 01074		AL 01140	
AL 00810	51	AL 00876	111	AL 00942	68	AL 01008	71	AL 01075		AL 01141	38
AL 00811		AL 00877	111	AL 00943	151	AL 01009		AL 01076		AL 01142	
AL 00812		AL 00878	111	AL 00944	67	AL 01010		AL 01077		AL 01143	
AL 00813		AL 00879	111	AL 00945	67	AL 01011		AL 01078		AL 01144	
AL 00814	112	AL 00880		AL 00946		AL 01012	39	AL 01079		AL 01145	
AL 00815	104	AL 00881		AL 00947		AL 01013	33	AL 01080		AL 01146	
AL 00816	149	AL 00882	48	AL 00948	151	AL 01014		AL 01081		AL 01147	
AL 00817	149	AL 00883	55	AL 00949	151	AL 01015		AL 01082		AL 01148	
AL 00818	54	AL 00884	48	AL 00950	68	AL 01016		AL 01083		AL 01149	
AL 00819	48	AL 00885	55	AL 00951	152	AL 01017	40	AL 01084	69	AL 01150	38
AL 00820	54	AL 00886		AL 00952	74	AL 01018		AL 01085	70	AL 01151	
AL 00821	46	AL 00887		AL 00953		AL 01019		AL 01086		AL 01152	151
AL 00822		AL 00888	154	AL 00954		AL 01020		AL 01087		AL 01153	152
AL 00823		AL 00889		AL 00955	71	AL 01021		AL 01088	8	AL 01154	
AL 00824		AL 00890	160	AL 00956	148	AL 01022		AL 01089	11	AL 01155	
AL 00825		AL 00891	160	AL 00957	83	AL 01023	13	AL 01090	39	AL 01156	56
AL 00826	44	AL 00892	101	AL 00958	159	AL 01024	18	AL 01091	4	AL 01157	53
AL 00827	52	AL 00893		AL 00959	159	AL 01025		AL 01092	3	AL 01158	5
AL 00828	52	AL 00894		AL 00960	73	AL 01026	63	AL 01093		AL 01159	55
AL 00829	52	AL 00895		AL 00961	83	AL 01027		AL 01094		AL 01160	48
AL 00830	113	AL 00896		AL 00962	147	AL 01028	40	AL 01095		AL 01161	55
AL 00831	59	AL 00897		AL 00963	147	AL 01029		AL 01096		AL 01162	73
AL 00832	53	AL 00898	150	AL 00964	65	AL 01030		AL 01097		AL 01163	95
AL 00833	48	AL 00899	150	AL 00965	83	AL 01031		AL 01098		AL 01164	95
AL 00834	48	AL 00900	150	AL 00966	145	AL 01032		AL 01099	10	AL 01165	95
AL 00835	52	AL 00901	162	AL 00967	145	AL 01033	68	AL 01100	17	AL 01166	95
AL 00836	57	AL 00902	162	AL 00968	83	AL 01034		AL 01101	40	AL 01167	95
AL 00837		AL 00903	160	AL 00969	150	AL 01035		AL 01102	40	AL 01168	
AL 00838	113	AL 00904	65	AL 00970	74	AL 01036		AL 01103	2	AL 01169	55
AL 00839	145	AL 00905		AL 00971		AL 01037	32	AL 01104	9	AL 01170	84
AL 00840		AL 00906		AL 00972	68	AL 01038	23	AL 01105	40	AL 01171	
AL 00841	110	AL 00907		AL 00973	65	AL 01039	24	AL 01106		AL 01172	
AL 00842	113	AL 00908	66	AL 00974		AL 01040	25	AL 01107	12	AL 01173	67
AL 00843	58	AL 00909	68	AL 00975	83	AL 01041		AL 01108	46	AL 01174	67

## LIST OF NUMBERS

Albi-No	Page
AL 01175	-
AL 01176	-
AL 01177	-
AL 01178	-
AL 01179	-
AL 01180	-
AL 01181	95
AL 01182	95
AL 01183	73
AL 01184	94
AL 01185	94
AL 01186	89
AL 01187	77
AL 01188	95
AL 01189	95
AL 01190	6
AL 01191	55
AL 01192	48
AL 01193	57
AL 01194	57
AL 01195	163
AL 01196	163
AL 01197	163
AL 01198	163
AL 01199	73
AL 01200	98
AL 01201	148
AL 01202	75
AL 01203	80
AL 01204	65
AL 01205	141
AL 01206	142
AL 01207	142
AL 01208	142
AL 01209	142
AL 01210	142
AL 01211	142
AL 01212	142
AL 01213	141
AL 01214	141
AL 01215	142
AL 01216	142
AL 01217	142
AL 01218	-
AL 01219	-
AL 01220	164
AL 01221	94
AL 01222	96
AL 01223	164
AL 01224	144
AL 01225	-
AL 01226	61
AL 01227	61
AL 01228	62
AL 01229	-
AL 01230	62
AL 01231	-
AL 01232	58
AL 01233	53
AL 01234	
AL 01235	
AL 01236	88
AL 01237	84
AL 01238	104
AL 01239	104
AL 01240	147

Albi-No	Page
AL 01241	109
AL 01242	77
AL 01243	76
AL 01244	76
AL 01246	-
AL 01247	62
AL 01248	87
AL 01249	91
AL 01250	91
AL 01251	67
AL 01252	88
AL 01253	
AL 01254	86
AL 01255	86
AL 01256	98
AL 01257	156
AL 01258	62
AL 01259	152
AL 01260	142
AL 01261	142
AL 01262	143
AL 01263	143
AL 01264	143
AL 01265	143
AL 01266	143
AL 01267	141
AL 01268	74
AL 01269	143
AL 01270	-
AL 01271	156
AL 01272	164
AL 01273	164
AL 01274	-
AL 01275	49
AL 01276	164
AL 01277	110
AL 01278	110
AL 01279	164
AL 01280	96
AL 01281	155
AL 01282	155
AL 01283	156
AL 01284	156
AL 01285	168
AL 01286	164
AL 01287	164
AL 01288	164
AL 01289	89
AL 01290	53
AL 01291	144
AL 01292	144
AL 01293	144
AL 01294	144
AL 01295	156
AL 01296	102
AL 01297	102
AL 01298	102
AL 01299	102
AL 01300	102
AL 01301	102
AL 01302	102
AL 01303	102
AL 01304	102
AL 01305	144
AL 01306	155
AL 01307	38

Albi-No	Page
AL 01308	101
AL 01309	
AL 01310	
AL 01311	150
AL 01312	150
AL 01313	-
AL 01314	151
AL 01315	151
AL 01316	151
AL 01317	155
AL 01318	160
AL 01320	110
AL 01321	110
AL 01322	110
AL 01323	110
AL 01324	155
AL 01325	155
AL 01326	106
AL 01327	106
AL 01328	156
AL 01329	91
AL 01332	88
AL 01333	88
AL 01334	156
AL 01335	155
AL 01336	
AL 01337	155
AL 01338	-
AL 01339	108
AL 01340	108
AL 01341	108
AL 01342	108
AL 01343	108
AL 01344	68
AL 01345	68
AL 01346	156
AL 01347	110
AL 01348	145
AL 01349	38
AL 01350	103
AL 01351	103
AL 01352	103
AL 01353	103
AL 01354	103
AL 01355	104
AL 01356	103
AL 01357	103
AL 01358	78
AL 01359	103
AL 01360	103
AL 01361	78
AL 01362	55
AL 01363	104
AL 01364	89
AL 01365	1
AL 01366	76
AL 01367	46
AL 01368	1
AL 01369	38
AL 01370	49
AL 01371	38
AL 01372	75
AL 01373	
AL 01374	76
AL 01375	49
AL 01376	1

Albi-No	Page
AL 01377	66
AL 01378	1
AL 01379	76
AL 01380	29
AL 01381	49
AL 01382	92
AL 01383	78
AL 01384	156
AL 01385	143
AL 01386	49
AL 01387	55
AL 01388	78
AL 01389	149
AL 01390	143
AL 01391	149
AL 01392	
AL 01393	95
AL 01394	
AL 01395	78
AL 01396	166
AL 01397	74
AL 01398	74
AL 01399	74
AL 01400	98
AL 01401	98
AL 01402	98
AL 01403	-
AL 01404	-
AL 01405	
AL 01406	165
AL 01407	165
AL 01408	
AL 01409	
AL 01410	167
AL 01411	93
AL 01412	93
AL 01413	93
AL 01414	
AL 01415	
AL 01416	
AL 01417	
AL 01418	
AL 01419	
AL 01420	
AL 01421	
AL 01422	
AL 01423	
AL 01424	
AL 01425	
AL 01426	
AL 01427	
AL 01428	
AL 01429	
AL 01430	
AL 01431	
AL 01432	
AL 01433	
AL 01434	
AL 01435	
AL 01436	
AL 01437	
AL 01438	
AL 01439	
AL 01440	
AL 01441	
AL 01442	

Albi-No	Page
AL 01443	
AL 01444	
AL 01445	
AL 01446	
AL 01447	
AL 01448	
AL 01449	
AL 01450	
AL 01451	
AL 01452	
AL 01453	
AL 01454	
AL 01455	
AL 01456	
AL 01457	
AL 01458	
AL 01459	
AL 01460	
AL 01461	
AL 01462	
AL 01463	
AL 01464	
AL 01465	
AL 01466	
AL 01467	
AL 01468	
AL 01469	
AL 01470	
AL 01471	
AL 01472	
AL 01473	
AL 01474	
AL 01475	
AL 01476	
AL 01477	
AL 01478	
AL 01479	
AL 01480	
AL 01481	
AL 01482	
AL 01483	
AL 01484	
AL 01485	
AL 01486	
AL 01487	
AL 01488	
AL 01489	
AL 01490	
AL 01491	
AL 01492	
AL 01493	
AL 01494	
AL 01495	
AL 01496	
AL 01497	
AL 01498	
AL 01499	90
AL 01500	-
AL 01501	-
AL 01502	-
AL 01503	55
AL 01504	55
AL 01505	55
AL 01506	-
AL 01507	-
AL 01508	156
AL 01509	49

## LIST OF NUMBERS


Albi-No	Page
AL 01510	69
AL 01511	167
AL 01512	49
AL 01513	49
AL 01514	-
AL 01515	-
AL 01516	-
AL 01517	168
AL 01518	-
AL 01519	140
AL 01520	93
AL 01521	93
AL 01522	93
AL 01523	92
AL 01524	92
AL 01525	92
AL 01526	92
AL 01527	49
AL 01528	55
AL 01529	93
AL 01530	88
AL 01531	143
AL 01532	91
AL 01533	91
AL 01534	140
AL 01535	93
AL 01536	93
AL 01537	71
AL 01538	93
AL 01539	
AL 01540	111
AL 01541	111
AL 01542	111
AL 01543	111
AL 01544	111
AL 01545	111
AL 01546	111
AL 01547	163
AL 01548	163
AL 01549	89
AL 01550	146
AL 01551	105
AL 01552	
AL 01553	90
AL 01554	
AL 01555	78
AL 01556	105
AL 01557	49
AL 01558	145
AL 01559	76
AL 01560	105
AL 01561	105
AL 01562	51
AL 01563	169
AL 01564	1
AL 01565	90
AL 01566	105
AL 01567	105
AL 01568	
AL 01569	105
AL 01570	165
AL 01571	164
AL 01572	164
AL 01573	113
AL 01574	59
AL 01575	96

Albi-No	Page
AL 01576	96
AL 01577	96
AL 01578	93
AL 01579	
AL 01580	153
AL 01581	
AL 01582	
AL 01583	90
AL 01584	105
AL 01585	1
AL 01586	90
AL 01587	-
AL 01588	90
AL 01589	90
AL 01590	111
AL 01591	1
AL 01592	97
AL 01593	109
AL 01594	1
AL 01595	109
AL 01596	113
AL 01597	
AL 01598	53
AL 01599	
AL 01600	99
AL 01601	
AL 01602	156
AL 01603	100
AL 01604	97
AL 01605	97
AL 01606	97
AL 01607	97
AL 01608	97
AL 01609	
AL 01610	49
AL 01611	56
AL 01612	75
AL 01613	
AL 01614	
AL 01615	
AL 01616	
AL 01617	
AL 01618	
AL 01619	
AL 01620	
AL 01621	
AL 01622	86
AL 01623	
AL 01624	97
AL 01625	
AL 01626	
AL 01627	113
AL 01628	
AL 01629	
AL 01630	
AL 01631	
AL 01632	
AL 01633	
AL 01634	
AL 01635	
AL 01636	105
AL 01637	105
AL 01638	
AL 01639	
AL 01640	
AL 01648	49

Albi-No	Page
AL 01653	90
AL 01655	90
AL 01656	90
AL 01657	90
AL 01664	90
AL 03000	116
AL 03001	116
AL 03002	117
AL 03003	117
AL 03004	125
AL 03005	125
AL 03006	126
AL 03007	126
AL 03008	120
AL 03009	120
AL 03010	121
AL 03011	120
AL 03012	127
AL 03013	135
AL 03014	139
AL 03015	117
AL 03016	119
AL 03017	119
AL 03018	122
AL 03019	127
AL 03019/A	127
AL 03020	129
AL 03021	129
AL 03022	121
AL 03023	-
AL 03024	122
AL 03025	123
AL 03026	123
AL 03027	129
AL 03028	126
AL 03029	126
AL 03030	136
AL 03031	
AL 03032	120
AL 03033	126
AL 03034	128
AL 03035	122
AL 03036	123
AL 03037	120
AL 03038	120
AL 03039	123
AL 03040	128
AL 03041	128
AL 03042	128
AL 03043	128
AL 03044	128
AL 03045	119
AL 03046	135
AL 03047	128
AL 03048	128
AL 03049	131
AL 03050	123
AL 03050/A	123
AL 03051	117
AL 03052	129
AL 03053	123
AL 03054	139
AL 03055	126


Albi-No	Page
AL 03056	-
AL 03057	135
AL 03058	133
AL 03059	143
AL 03060	119
AL 03061	117
AL 03062	129
AL 03063	117
AL 03064	117
AL 03065	126
AL 03066	117
AL 03067	131
AL 03068	131
AL 03069	139
AL 03070	135
AL 03071	140
AL 03072	133
AL 03073	128
AL 03074	128
AL 03075	131
AL 03076	117
AL 03077	133
AL 03078	136
AL 03079	121
AL 03080	121
AL 03081	121
AL 03082	143
AL 03083	123
AL 03084	117
AL 03085	117
AL 03086	119
AL 03087	119
AL 03088	-
AL 03089	-
AL 03090	127
AL 03091	127
AL 03092	138
AL 03093	131
AL 03094	140
AL 03095	-
AL 03096	-
AL 03097	-
AL 03098	133
AL 03099	-
AL 03100	-
AL 03101	123
AL 03102	124
AL 03103	117
AL 03104	118
AL 03105	
AL 03106	
AL 03107	
AL 03108	
AL 03109	118
AL 03110	126
AL 03111	118
AL 03112	118
AL 03113	128
AL 03114	134
AL 03115	126
AL 03116	
AL 03117	118
AL 03118	118
AL 03119	118
AL 03120	
AL 03121	118

Albi-No	Page
AL 03122	122
AL 03123	118
AL 03124	118
AL 03125	128
AL 03126	139
AL 03129	118
AL 03130	118
AL 05472	84
AL 05473	84
AL 07252	169
AL 08112	101
AL 08114	101
AL 08205	148
AL 8625	152
AL 8626	152
AL 8627	153
AL 8628	153
AL 8629	152
AL 8630	152
AL 8631	152
AL 8632	152
AL 8634	152
AL 8635	153
AL 8636	153
AL 8637	152
AL 8638	153
AL 8639	154
AL 8640	154
AL 8641	154
AL 8642	154
AL 8643	
AL 8644	150
AL 8645	153
AL 8649	154
AL 8666	
AL 8667	153
AL 8668	154
AL 8669	153
AL 8670	153
AL 8674	153
AL 8675	154
AL 8686	153
AL 8689	154
AL 08715	108
AL 08716	108
AL 08717	108
AL 09301	109
AL 09338	108
AL 09358	75
AL 09404	108
AL 09415	109
AL 09415/D	109
AL 09480	109
BSX172-173	165




### AL 1365

Replacing Bosch 0120 468131  
Servicing Scania  
24v 65 Amp Without Fan & Pulley




### AL 1368

Replacing Bosch 0120 468135, 144  
Servicing Iveco, Volvo, Daf, Mercedes  
28v 80 Amp Without Fan & Pulley




### AL 1376

Replacing Bosch 0120 468 053, -107, -113  
Servicing Iveco, MAN, Mercedes  
24 V. 80 Amp Without Fan & Pulley




### AL 1378

Replacing Bosch 0120 468143, 145  
Servicing Mercedes Benz, Actros  
28v 100 Amp.




### AL 1564

Replacing Bosch 0120 689...  
Servicing Iveco, Daf  
28v 140 Amp




### AL 1585

Replacing Bosch 0120 489 702  
Servicing Volvo, SCANIA, MARINE  
24V. 40 Amp




### AL 1591

Replacing Bosch 0120489643  
Servicing Volvo Trucks, Berliet, Volvo,  
Penta  
28v 45 Amp




### AL 1594

Replacing Bosch 0120468037, 114  
Servicing Volvo Trucks 24 V. 80 Amp



Albi Number: AL 1103  
Replacing Bosch 0120689535  
Replacing Delco Remy: 19025330 (T1)  
**POWER**  
28 Volt 140 Amper



Item	Description	Albi No.	Replacing	Remarks
1	Cover	AL 660	1125500 023	
2	Stud for fixing cover	AL 597	2912212 207	
3	B + B - & D + Terminal Kit	AL 1162	1127011 083	
4	Gasket for Regulator	AL 203	1121015 009	
5	S.R.E.Bracket	AL 885	1125887 013	
6	Through Bolt	AL 654	1123429 125	M6 x 105 mm
7	Gasket for Rectifier	AL 655	1121015 011	
8	Rectifier	AL 742	1127320 973	
9	Stator	AL 853	1125047 007	
10	S.R.E. Roller Bearing	AL 1163	1900910 024	
11	Seal	AL 659	1120283 000	
12	Spacer Ring	AL 1164	1120200 015	
13	Slipring	AL 1204	1124304 018	
14	Rotor wire separator	AL 992	-	
15	Rotor	AL 803	1124037 004	
16	Retainer	AL 1165	2916600 016	
17	Support ring	AL 1166	1120114 002	
18	Bearing Plate	AL 998	1120033 009	
19	D.E. Roller Bearing	AL 1188	2120905 000	
20	D.E. Bracket	AL 884	1125827 013	
21	Alternator Repair Kit	AL 644	1127011 171	
22	Fan	AL 211	1126610 052	
23	Pulley	AL 645	2126600 030	
24	Screw for Regulator	AL 1181	1123433 007	
25	Screw for Capacitor	AL 1182	2912452 191	
26	Screw for Rectifier	AL 1183	1123433 005	
27	Regulator	AL 1168	1197311 315	

**Servicing**


**MERCEDES-BENZ**

0303, 0400, 0403, 0404, 0405, 0408,


**DRÖGMÖLLER**

E280, E280H, E290, E290H, E300, E300H, E310, E320, E320L,  
E330, E330H, E330K, E420, E430, E440






Albi Number: AL 1092  
Replacing Bosch 0120689520, 533  
Replacing Delco Remy: 19025333, 334 (T1)  
**POWER**  
28 Volt 120 Amper



Item	Description	Albi No.	Replacing	Remarks
1	Cover	AL 660	1125500 023	
2	Stud for fixing cover	AL 597	2912212 207	
3	B + B - & D + Terminal Kit	AL 1162	1127011 083	
4	Gasket for Regulator	AL 203	1121015 009	
5	S.R.E.Bracket	AL 885	1125887 013	
6	Through Bolt	AL 654	1123429 125	M6 x 105 mm
7	Gasket for Rectifier	AL 655	1121015 011	
8	Rectifier	AL 742	1127320 550	
9	Stator	AL 853	1125047 005	
10	S.R.E. Roller Bearing	AL 1163	1900910 024	
11	Seal	AL 659	1120283 000	
12	Spacer Ring	AL 1164	1120200 015	
13	Slipring	AL 1204	1124304 018	
14	Rotor wire separator	AL 992	-	
15	Rotor	AL 803	1124037 002	
16	Retainer	AL 1165	2916600 016	
17	Support ring	AL 1166	1120114 002	
18	Bearing Plate	AL 998	1120033 009	
19	D.E. Roller Bearing	AL 1188	2120905 000	
20	D.E. Bracket	AL 884	1125827 013	
21	Alternator Repair Kit	AL 644	1127011 171	
22	Fan	AL 211	1126610 052	
23	Pulley	AL 645	2126600 030	
24	Screw for Regulator	AL 1181	1123433 007	
25	Screw for Capacitor	AL 1182	2912452 191	
26	Screw for Rectifier	AL 1183	1123433 005	
27	Regulator	AL 1168	1197311 315	

**Servicing**

MAN  
FR292, FRH292/362, R292, SÜ242, SG242, SL202  
OTOMARSAN  
0302  
MERCEDES-BENZ  
0303, 408  
IKARUS  
260.71, 266.71, 280.69-200 series




Albi Number: AL 1091

Replacing Bosch 0120689503, 508, 512, 516, 523

Replacing Delco Remy: DRA 1600

**POWER**


**28 Volt 105 Amper**




Item	Description	Albi No.	Replacing	Remarks
1	Cover	AL 660	1125500 023	
2	Stud for fixing cover	AL 597	2912212 207	
3	B + B - & D + Terminal Kit	AL 1162	1127011 072	
4	Gasket for Regulator	AL 203	1121015 009	
5	S.R.E.Bracket	AL 883	1125887 003	
6	Through Bolt	AL 654	1123429 125	M6 x 105 mm
7	Gasket for Rectifier	AL 655	1121015 011	
8	Rectifier	AL 742	1127320 547	
9	Stator	AL 848	1125047 003	
10	S.R.E. Roller Bearing	AL 1163	1900910 024	
11	Seal	AL 659	1120283 000	
12	Spacer Ring	AL 1164	1120200 015	
13	Slipring	AL 1204	1124304 018	
14	Rotor wire separator	AL 992	-	
15	Rotor	AL 432	1124037 002	
16	Retainer	AL 1165	2916600 016	
17	Support ring	AL 1166	1120114 002	
18	Bearing Plate	AL 997	2120516 011	
19	D.E. Roller Bearing	AL 1167	1900900 361	
20	D.E. Bracket	AL 882	1125827 003	
21	Alternator Repair Kit	AL 643	1127011 064	
22	Fan	AL 211	1126610 052	
23	Pulley	AL 645	2126600 030	
24	Screw for Regulator	AL 1181	1123433 007	
25	Screw for Capacitor	AL 1182	2912452 191	
26	Screw for Rectifier	AL 1183	1123433 005	
27	Regulator	AL 1168	1197311 315	
28	S.R.E. Oiler	AL 1184	1127402 001	
29	D.E. Oiler	AL 1185	1127402 000	

**Servicing**

MERCEDES-BENZ, DRÖGMOLLER, MAN, OTOMARSAN  
DAF, KHD, VANHOLL, KASSBOHRER, SCANIA, IVECO



Albi Number: AL 1158  
Replacing Bosch 0120689566  
Replacing Delco Remy: 19025330 (T1)  
**POWER**  
28 Volt 140 Amper




Item	Description	Albi No.	Replacing	Remarks
1	Cover	AL 660	1125500 023	
2	Stud for fixing cover	AL 597	2912212 207	
3	B + B - & D + Terminal Kit	AL 1162	1127011 083	
4	Gasket for Regulator	AL 203	1121015 009	
5	S.R.E.Bracket	AL 1169	1125887 019	
6	Through Bolt	AL 654	1123429 125	M6 x 105 mm
7	Gasket for Rectifier	AL 655	1121015 011	
8	Rectifier	AL 742	1127320 973	
9	Stator	AL 853	1125047 007	
10	S.R.E. Roller Bearing	AL 1163	1900910 024	
11	Seal	AL 659	1120283 000	
12	Spacer Ring	AL 1164	1120200 015	
13	Slipring	AL 1204	1124304 018	
14	Rotor wire separator	AL 992	-	
15	Rotor	AL 803	1124037 004	
16	Retainer	AL 1165	2916600 016	
17	Support ring	AL 1166	1120114 002	
18	Bearing Plate	AL 998	1120033 009	
19	D.E. Roller Bearing	AL 1188	2120905 000	
20	D.E. Bracket	AL 884	1125827 013	
21	Alternator Repair Kit	AL 644	1127011 171	
22	Fan	AL 211	1126610 052	
23	Pulley	AL 645	2126600 030	
24	Screw for Regulator	AL 1181	1123433 007	
25	Screw for Capacitor	AL 1182	2912452 191	
26	Screw for Rectifier	AL 1183	1123433 005	
27	Regulator	AL 1168	1197311 315	


**Servicing**

RENAULT

FR1



Albi Number: AL 1190  
Replacing Bosch 0120689538  
**POWER**  
28 Volt 120 Amper



Item	Description	Albi No.	Replacing	Remarks
1	Cover	AL 660	1125500 023	
2	Stud for fixing cover	AL 597	2912212 207	
3	B + B - & D + Terminal Kit	AL 1162	1127011 083	
4	Gasket for Regulator	AL 203	1121015 009	
5	S.R.E.Bracket	AL 1191	1125887 023	
6	Through Bolt	AL 654	1123429 125	M6 x 105 mm
7	Gasket for Rectifier	AL 655	1121015 011	
8	Rectifier	AL 742	1127320 547	
9	Stator	AL 853	1125047 005	
10	S.R.E. Roller Bearing	AL 1163	1900910 024	
11	Seal	AL 659	1120283 000	
12	Spacer Ring	AL 1164	1120200 015	
13	Slipping	AL 1204	1124304 018	
14	Rotor wire separator	AL 992	-	
15	Rotor	AL 803	1124037 004	
16	Retainer	AL 1165	2916600 016	
17	Support ring	AL 1166	1120114 002	
18	Bearing Plate	AL 998	1120033 009	
19	D.E. Roller Bearing	AL 1188	2120905 000	
20	D.E. Bracket	AL 1192	1125887 023	
21	Alternator Repair Kit	AL 644	1127011 171	
22	Fan	AL 211	1126610 052	
23	Pulley	AL 645	2126600 030	
24	Screw for Regulator	AL 1181	1123433 007	
25	Screw for Capacitor	AL 1182	2912452 191	
26	Screw for Rectifier	AL 1183	1123433 005	
27	Regulator	AL -	1197311 320	

### Servicing

IVECO


370.24 - 370.25 - 370.25L - 370.30 - 370.35

EUROCLASS


380.35

EUROCLASS HD

380.38



Albi Number: AL 1056  
Replacing Bosch 0120469521  
Replacing Delco Remy DRA 4430  
**POWER**  
24 Volt 55 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket.	AL 744	1125885 019	
2	Stator	AL 794	1125045 107	
3	D.E. Bracket	AL 1648	1125825 264	
4	Rotor	AL 404	1124035 021	
5	Rectifier	AL 1063	1127320 543	
6	Regulator	AL 1020	0192053 006	
7	Gasket	AL 203	1121015 003	
8	Slipring	AL 922	1124303 001	
9	Thru Bolt	AL 988	1123429 102	
10	Bearing Plate	AL 48	1121038 018	
11	Repair Kit	AL 1221	1127011 020	
12	Fan	AL 210	-	Ø17 Aliminium
13	Pulley	AL 985	-	Ø17 12.5 Belt
14	B + Insulator	AL 159	-	
15	Protective Cap	AL 1268	1120524 005	

**Servicing**

**FORD CARGO**

1317, 1320, 1517, 1520, 2220, 3220,

**IVECO**


110.16..., 110.17, 120-16..., 120-17..., 120-19..., 150.16..., 160.16..., 160.17..., 160.23..., 160.30..., 168M14  
FL, 168M16 FL, 170 D11, D 12, D15, D17, 170.23..., 170.25..., 170.34..., 180-23..., 180-25..., 180.34..., 190.13...,  
190.32 ..., 190.36 ..., 220.32..., 220.36..., 260.25..., 260.30..., 260.32..., 260.34..., 300.25..., 300.32..., 300.36...,  
340.34 ..., 75.13 ..., 80.13..., 80.16..., 90.16...

**IKARUS**


K-Series

**STEYR**

Pinzgauer Turbo Diesel



Albi Number: AL 1088  
Replacing: Bosch 0120469549  
Replacing Delco Remy: DRA4420  
**POWER**  
24 Volt 55 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 692	1125 885 036	
2	Stator	AL 794	1125 045 105	
3	D.E. Bracket	AL 693	1125 825 036	
4	Rotor	AL 404	1125 035 178	
5	Rectifier	AL 1063	1127 320 390	
6	Regulator	AL 1020/H	1197 311 304	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 48	1121 038 018	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	-	
12	Pulley	AL 989	-	
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	

**Servicing**

**IVECO**

110.14, 110.17, 145.17, 115.17, 120-15-17, 135.17, 159-D2, 165.24..., 170.20-26-35, 1755.17, 180.26, 190.20-26-32  
-35-38-42-48, 190.42-48, TurboStar, 22.30-38, 240?36..., -38..., -48..., 260.35...-36...-38...-48... 330.35..., Gamma 'Z'  
50-8 - 60-8

**FIAT ALLIS**


FD7, 30C, FL7, 7B, FR 9B, 9C, 10B, 10C, 35, 130, 160, 220, 65B, FH400

**LORRAINE (PLAXTON)**

240 CS 11, LS 11

**FIAT - HITACHI (N,H, GEO TECH)**

FH 400




Albi Number: AL 1104

Replacing: Bosch 0120469569, 643

Replacing Delco Remy: DRA 2720

**POWER**

**24 Volt 55 Amper**



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1159	1125 885 143	
2	Stator	AL 794	1125 045 107	
3	D.E. Bracket	AL 676	1125 825 043	
4	Rotor	AL 404	1124 035 177	
5	Rectifier	AL 1084	1127 320 517	
6	Regulator	AL 1020/H	1197 311 304	
7	Slipring	AL 922	1124 303 001	
8	Repair Kit	AL 1221	1127 011 020	
9	Bearing Plate	AL 48	1121 038 018	
10	Thru Bolt	AL 988	1123 429 102	
11	Fan	AL 210	-	
12	Pulley	AL 1332	-	O.D. 105mm. Single
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	


**Servicing**

**SCANIA**


BK112 CLB (DS11.15 B), (DSC11.01 B) ... BR112, CR112 ... CR145-TX... F82 CL... G82, M 16-Ton 4x2 Rigid, G92... G112... K112 CLB... K113 CLB... P82 4x2 Rigid (DS8)...P82 Rigid, Tipper, P82 6x4 Tipper, P82 8x4 Tipper, P82 8x4 Truck P82 M 4x2 Rigid, Tipper... P82 MA 4x2 RS Tractor Unit... P92 30 Ton 8x4 Tipper, Truck... P92 HB 24 Ton 6x2 Rigid, Tipper.. P92 HB 32 Ton 6x2 Drawbar.. P92 M 24 Ton 6x4 Tipper.. P92 M 32 Ton 4x2, 6x4, Drawbar.. P92 M 38 Ton 6x2 Tractor Unit.. P92 M 38 Ton 8x4 Tipper, P92 MA 32 Ton 4x2 Tractor Unit, P92 MA 38 Ton 4x2 Tractor Unit, P93 HL-250 6x2 RZ Rigid, Tipper, P93 M-210 17 Ton, 4x2 LR Rigid, Drawbar.. P93 M-250 17 Ton 6x4 LR Tipper, P93 MK-280 8x4 RZ Tipper, Truck.. P93-280 6x2 Rigid, Tipper.. P93-280 6x4 Tipper.. P112 M 32 Ton 4x2, 6x2 Drawbar, P112 M 38 Ton 6x2 Tractor Unit.. P112 M 47 Ton 4x2, 6x2 Drawbar.. P112 M 47 Ton 6x2 Tractor Unit.. P112 MA 16 Ton 4x2 Tractor Unit.. P112 MA 47 Ton 4x2 Tractor Unit.. P112 MA 4x2 RS Tractor Unit.. P113 4x2, 6x2 Tractor Unit.. P113 MA-320 4x2, 6x2, R Tractor Unit.. P113 MA-320 6x4 R Tractor Unit.. P113 MA-360 6x2 R Tractor Unit.. P113 MK-320 8x4 RZ Tipper.. P113 ML-320 4x2 R, RA Drawbar.. P113 ML-320 6x2 RA, RZ Drawbar.. P113 MV-320 4x2 Drawbar.. R112 H 32, 51 Ton 4x2 Drawbar.. R112 M 51 Ton 6x2 Tractor Unit.. R112 MA 4x2 RS Tractor Unit.. R112 MA 51 Ton 4x2 Tractor Unit.. R113 HL-360 6x4 RZ Tractor Unit.. R113 MA-360 6x2 R, RA Tractor Unit.. R113 MA-360 6x2 RZ Tractor Unit.. R113 MV-320 6x2 RB Drawbar.. R113-320 4x2, 6x2 Tractor Unit.. R113-350 6x2 Tractor Unit.. R143 4x2, 6x2 Tractor Unit.. R143 EL-500 6x4 RZ Tractor Unit.. R143 MA-400 4x2 R Tractor Unit.. R143 MA-470 4x2 R Tractor Unit - S82 CL, HR.. T82 (DN8. 01).. T82 (DS8, 06).. T82 (DS18.01).. T92.. T112 . T142.

**IVECO FIAT**

1234, 1236, 1334, 1434, 1436, 2334, 2434



Albi Number: AL 1099  
Replacing: Bosch 0120469518  
Replacing Delco Remy: DRA 0520  
**POWER**  
24 Volt 55 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 744	1125 885 143	
2	Stator	AL 794	1125 045 105	
3	D.E. Bracket	AL 648	1125 825 009	
4	Rotor	AL 404	1124 035 057	
5	Rectifier	AL 1063	1127 320 390	
6	Regulator	AL 1020/H	1197 311 301	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 647	1120 136 000	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	-	
12	Pulley	AL 989	-	
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	

**Servicing**

**MAN**

19.2..., 19.3..., 19.4..., 22.280, 22.330, HOCLN, 24.2..., 24.3..., 24.4..., 32.2..., 32.3..., 33.2..., 33.3..., 35.2..., 35.3..., 40.3..., 40.4..., 41.2..., 41.3..., 48.2..., 48.3..., 8.170 FOC, 9.170 FOC,

**MERCEDES-BENZ**

1217..., 1222..., 1422..., 3250..., 3850..., L 608 D, L 613 D / Mot. OM, 352/360/401/422


**KAELBLE GEMEINDER**

K 33, KV 33, KK 50, SL 12C


**DAF**

65, Trucks






Albi Number: AL 1089  
Replacing: Bosch 0120488206  
**POWER**  
24 Volt 45 Amper




Item	Description	Albi No.	Replacing	Remarks
1 —	S.R.E.Bracket	AL 697	1125 884 493	
2 —	Stator	AL 499	1125 045 088	
3 —	D.E. Bracket	AL 870	1125 824 575	
4 —	Rotor	AL 492	1124 034 677	
5 —	Rectifier	—	1127 320 934	
6 —	Regulator	AL 1020/H	1197 311 304	
7 —	Slipring	AL 922	1124 303 001	
8 —	Thru Bolt	AL 988	1123 429 102	
9 —	Repair Kit	AL 1221	1127 011 020	
10 —	Fan	AL 210	—	
11 —	Pulley	AL 989	—	
12 —	Bearing Plate	AL 48	1121 038 018	
13 —	B + Insulator	AL 159	—	
14 —	Protective Cap	AL 1268	1120524005	

**Servicing**

CUMMINS  
CASE,  
J.I. CASE,  
CASE - INTERNATIONAL,  
JOHN DEERE,  
KOMATSU



Albi Number: AL 1107  
Replacing: Bosch 0120489731  
Replacing Delco Remy: DRA 1320  
**POWER**  
24 Volt 35 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 730	1125 884 529	
2	Stator	AL 826	1125 045 047	
3	D.E. Bracket	AL 736	1125 824 340	
4	Rotor	AL 406	1124 034 176	
5	Rectifier	AL 753	1127 011 095	
6	Regulator	AL 1020/H	1197 311 301	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 647	1120 136 000	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	—	
12	Pulley	AL 985	—	
13	B + Insulator	AL 159	—	
14	Protective Cap	AL 1268	1120524005	

**Servicing**

IVECO


140-19 AH, 160-19 AH, 190-29A, 240-29 AP, 260-25 AH, AN 330-36 AH

MAGIRUS DEUTZ


320 M, Trucks

STEYR (STEYR - DAIMLER - PUCH AG)

12 M18 Agriculture



Albi Number: AL 1023  
Replacing: Bosch 0120400791  
Replacing Delco Remy: DRA 1260  
**POWER**  
24 Volt 27 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 780	1125 884 079	
2	Stator	AL 420	1125 045 018	
3	D.E. Bracket	AL 783	1125 824 108	
4	Rotor	AL 422	1124 034 015	
5	Rectifier	AL 921	1125 715 489	
6	Diode Trios	AL 915	1121 099 007	
7	Brush Holder	AL 230	1124 336 057	
8	Thru Bolt	AL 75	1123 429 133	M5x100 mm
9	Slipring	AL 912	1124 304 007	
10	Bearing Plate	AL 48	1121 038 018	
11	Fan	AL 166	1126 610 078	
12	Pulley	AL 175	-	12.7 Belt Ø17mm double
13	Repair Kit	AL 1221	1127 011 020	

**Servicing**

**MAN TRUCKS**

11.136 U, 13.136 U, 13.168-215 F, 13.168-216 H, 13.192 U, 14.168 F, FK, FS, 14.192 F, FK, FS, 14.192 FL, FLS, 14.192 U, UL, 15t H, 15.136-192 F, 15.200 F, FK, FL, FLS, FS, 15.240 F, FK, FS, 15.240 FL, FLS, 16tH, 16.168 F, FK, FS, 16.192 F, FK, FS, 16.192 FL, FLS, 16.200 F, FK, 16.232 FD, 16.232 FD-320F, 16.320 U, UK, 320 UL, 19.168-321 H, HA, 19.186-291 F, 19.240 UK, 29.240-361 U, UL, 19.320-390 F, 20.192-361 D, F, 22t H Series, 22.192-361 F, 22.240.22.320 UNL, 26.240-321 DH, 26.240-365 D, DF, 30, 32. 232-321, 33.331-365, 38.320 DF, 40.365-440 D Series.

**RVI**

EPG 5510, HM 15, B, HM 17, B, HM 19, B, HM 26, B, HM 26C-T/D-T

**MAGIRUS-DEUTZ**

M130, M160, M170, M232, M256, M270, M310, M340 Series

**KHD TRUCKS**

M110, M120, M130, M160, M170D, M230, M270, M290, M310, M340

**MERCEDES-BENZ TRUCKS**

0309 D

**IVECO FORD**

120, 150-16 Series

**POCLAIN**

MC 100, MCL 84, RC 200, RC 491

**WESERHÜTTE**


W160, 180, 270

**KHD Engines**


BF6L 912, 913/F1L, F2L, F3L, F4L, F5L, F6L Series

**MWM Diesel**

D232-12, D232-6, D232-8, D233 V6, V12, TBD233 V12, TD232-12, TD232-6, TD232-8, TD233 V6, V12



Albi Number: AL 1062  
Replacing: Bosch 0120489710  
Replacing Delco Remy: DRA 1270  
**POWER**  
12 Volt 55 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 733	1125 884 527	
2	Stator	AL 804	1125 045 012	
3	D.E. Bracket	AL 731	1125 824 590	
4	Rotor	AL 405	1124 034 155	
5	Rectifier	AL 753	1127 320 598	
6	Regulator	AL 1029	1197 311 030	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 48	1121 038 018	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	-	
12	Pulley	AL 989	-	
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	
15	Gasket	AL 203	1121015003	

**Servicing**

**ABG**

Alexander 126, 128, Puma 168, 177, 178

**CASE**

3000 Tractor 3964, 3980 Yumbo Combine H 60 B Payloader

**CLAAS**

Dominator 76, 86, 96 Combine

**IVECO FIAT**

75.9 A, 80.9 A, 80.13 A, 16 A.. 90.9, 90.13 A, 110.16 A.. 110.13 A.. 130.13 A, 130.16 A

**MERCEDES-UNIMOG**

U600, U650, U800, U900

**NEW HOLLAND**


8060, 8070, 8080 Combine

**SCHLÜTER**


Profi 2000 TVL... Super 1300 VL, 1600 TVL... Super 2000TVL

**MAGIRUS DEUTZ**

M90, M130, M160




Albi Number: AL 1057  
Replacing: Bosch 0120488205  
**POWER**  
12 Volt 65 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 697	1125 884 493	
2	Stator	AL 498	1125 045 063	
3	D.E. Bracket	AL 870	1125 824 575	
4	Rotor	AL 490	1124 034 341	
5	Rectifier	AL -	1127 320 666	
6	Regulator	AL 1029/H	1197 311 005	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 48	1121 038 018	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	-	
12	Pulley	AL 989	-	
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	

**Servicing**

CUMMINS Engines,  
ATLAS COPCO,  
J.I. CASE,  
INTERNATIONAL,  
IRRIGATOR,  
OSHKOSH,  
SWEEPMASTER  
JOHN DEERE 650 G Dozer  
THERMOKING,  
TAYLOR Forklift



Albi Number: AL 1055  
Replacing: Bosch 0120469522  
Replacing Delco Remy: DRA 2710  
**POWER**  
12 Volt 90 Amper

Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 744	1125 885 019	
2	Stator	AL 793	1125 045 133	
3	D.E. Bracket	AL 745	1125 825 031	
4	Rotor	AL 403	1125 035 064	
5	Rectifier	AL 1063	1127 320 390	
6	Regulator	AL 1029/H	1197 311 005	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 48	1121 038 018	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	-	
12	Pulley	AL 989	-	
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	

**Servicing**

**VOLVO**


B 6F, B 6FA, F 7, F 10, F 406, F 407, F 408, F 409, F 610 -F, 617 S, F 88T, F 89T, FB 88T, FB 89T, N10 Trucks

**VOLVO**

BM 2650, 2654

**VALMET**

2005, 2105



Albi Number: AL 1100

Replacing: Bosch 0120469526

Replacing Delco Remy: DRA 3090


**POWER**

12 Volt 90 Amper


Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 744	1125 885 143	
2	Stator	AL 793	1125 045 133	
3	D.E. Bracket	AL 648	1125 825 009	
4	Rotor	AL 403	1124 035 065	
5	Rectifier	AL 1063	1127 320 390	
6	Regulator	AL 1029/H	1197 311 005	
7	Slipring	AL 922	1124 303 001	
8	Thru Bolt	AL 988	1123 429 102	
9	Bearing Plate	AL 647	1120 136 000	
10	Repair Kit	AL 1221	1127 011 020	
11	Fan	AL 210	-	
12	Pulley	AL 989	-	
13	B + Insulator	AL 159	-	
14	Protective Cap	AL 1268	1120524005	

**Servicing**

MERCEDES BENZ  
0309 D  
CLAAS  
Dominator 106  
JAGUAR  
675, 680, 865 SL



Albi Number: AL 1024  
Replacing: Bosch 0120400700  
Replacing Delco Remy: DRA 0190  
**POWER**  
12 Volt 35 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 780	1125 884 244	
2	Stator	AL 784	1125 045 010	
3	D.E. Bracket	AL 783	1125 824 145	
4	Rotor	AL 415	1124 034 025	
5	Rectifier	AL 921	1125 715 163	
6	Diode Trios	AL 915	1121 099 007	
7	Brush Holder	AL 230	1124 336 057	
8	Thru Bolt	AL 75	1123 429 133	(M 5x100 mm)
9	Slipring	AL 912	1124 304 007	
10	Bearing Plate	AL 48	1121 038 018	
11	Fan	AL 166	1126 610 078	
12	Pulley	AL 175	-	12,7 Belt Ø17m double
13	Repair Kit	AL 1221	1127 011 020	

**Servicing**

**MERCEDES BENZ TRUCKS**

Unimog U54/403, U66/403, U80/413, L 307, L 406 DG, L 408 G, O 309 B, O 309 D, 207 L, L 1813, L 1819, L 408 DG, L 508 DG, L 608 D, LP 1013, LP, LPK, LPKF 709, O 309 D, 8t LP, LPS, 9t L, LS, 9t LP, LPS, 1013 A, 1013 K, AK, 1013 KO, 1013 S, 1017 A, 1017 K, AK, 1017 S, AS, 11t L, LS, 11tLP, LPS, 12 Series, 13tL, LS, 13t LP, LPS, 15t L, LS, 15t LP, LPS, 16t LP, LPSL Series

**SAVIEM**

SG4 Super Galion, SM6A, SM6C, SM7, SM8


**MAN Engines**

712.01.01, 597, 597-02, 797-10, 597.02

**HANOMAG HENSCHEL**

F130 K, AK, L, S, F150 K, L, F40, 45 B, F 46.55 KA Diesel, F20, 25, 30, 35, 36, 40 Diesel






Albi Number: AL 1000

Replacing: Fiat/Marelli 4152101/63303100

Replacing Delco Remy: 19025037

**POWER**

**12 Volt 42 Amper**



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E:Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 737	74995281	
3	D.E. Bracket	AL 714	74965511	Without Bearing
4	Rotor	AL 400	74995571	
5	Rectifier	AL 765	74999091	
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	74877551	
8	Thru Bolt	AL 113	74967690	
9	Slipping	AL 910	-	O.D. 32 mm
10	Bearing Plate Kit	AL 185	-	Plate Hole Ø15 mm
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	-	
13	Battery Terminal Kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Rotor Nut	AL 73		12x1.25 mm
16	Fan	AL 165	74877100	Ø15 mm
17	Pulley	AL 132	74991600	Cast Iron
18	Key	AL 130	10205720	3x5x14,5 mm
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	

**Servicing**

FIAT

480-480 DT, 480 V, 540, 540 DT, 600, 616, 619, 640, 640 DT, 684, 697

FIAT ALLIS - SIMIT

4 FLAC, FL 4 D, TL, TL 5 H

OM CARRELLI


B 120, B 125, BIM 20, 25, BL 10, BM 10, BM 12, BM 15, D1 120, D1 125, DIL 10, 15, DIM 20, DIM 30, DIM 35 B, DM 15

FIAT


124, 125, 130, 132

SEAT

124, 131E, 132, Panda, 35, 40, 45



Albi Number: AL 1001  
Replacing: Fiat/Marelli 4222697/63304800  
Replacing Delco Remy: 19025034  
**POWER**  
12 Volt 42 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 737	74995281	
3	D.E. Bracket	AL 755	74966731	Without Bearing
4	Rotor	AL 401	74995641	
5	Rectifier	AL 765	74999091	
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	74877551	
8	Thru Bolt	AL 113	74967690	
9	Slipring	AL 910	-	O.D. 32 mm
10	Bearing Plate Kit	AL 193	-	Plate Hole Ø17 mm
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	-	
13	Batery Terminal Kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Rotor Nut	AL 72	-	14x1,5 mm
16	Fan	AL 166	74987100	Ø17 mm
17	Pulley	AL 126	74997110	Cast Iron
18	Key	AL 103	10205810	4x6,5x15 mm
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	


**Sevicing**

**FIAT**


250 - 250 DT - 300 - 300 F - 300 FN - 300 N - 300 V - 350 - 350 DT - 355 - 355 C - 400 - 400 DT - 450 DAL - 450 DT - 455 - 455 C - 455 CF - 455 CM - 480 - 480 V - 500 - 500 DAL - 500 DT - 500 DTS - 505 C - 540 - 540 DT - 550 - 550 DT-555 -600 - 600 DT - 605 C -650 DT - 655 -750 - 750 DT - 805 C - 850 - 850 DTS - 850 S - 1000 - 1000 DT - 1300 - 1300 DT-1300 DTS - 1300 S

**OM CARRELLI**

BI 30 - BI 30 B - BI 35 - DI 30 - DI 35 - DI 40 - DI 65 - DIM 25 - DIM 25 BD - DM 12 - DM 12 CD



Albi Number: AL 1002  
Replacing: Fiat/Marelli 63304000  
Replacing Delco Remy: 19025040  
**POWER**  
24 Volt 26 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 764	74999371	
3	D.E. Bracket	AL 755	74966731	Without Bearing
4	Rotor	AL 402	74999421	
5	Rectifier	AL 765	74999091	
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	74877551	
8	Thru Bolt	AL 113	74967690	
9	Slipring	AL 910	-	O.D. 32 mm
10	Bearing Plate Kit	AL 193	-	Plate Hole Ø17
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	-	
13	Batery Terminal Kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Rotor Nut	AL 72	-	14x1,5 mm
16	Fan	AL 166	74987100	Ø17 mm
17	Pulley	AL 126	74997110	
18	Key	AL 103	10205810	4x6,5x15 mm
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	

### Servicing

#### FIAT

40/35-40 NC-50 NC-55 NC- 80 NC-NR-90 NC-100 NC- EC 110 NC-NR-NT-PC-130 NC-NT-NR- 150 NC 17-NC 20-NR 20-NT 20-159 NC 17-NC 20-160 NT-NC-170 NC-NT-190 NC 26-NT 26-NC 33NT 33-190 PAC 20-300 PC-PT-329 A Bus 241 TN, Campagnola C Diesel 616 N2-616 N2/4-N3-N3/4 619 N-T-N1-N1P-T1-T1P 625 N2-N3-645 N2-N3/4 650 N2-N3-655 N-N1 662 N2-N2P-T-N3-N3P 672 N-673 N-T-TR 682 N3-N4-T3-T4-683 N-T 684 N-T-NP-TP-690 N2-N3-N4-T2-691 N-NS-693 N1-T1 697 N-NP-T-TP Trucks

#### FIAT ALLIS

5(mot. CN3 V.13)-7C-8-8B-9-10-10B-12-14B-18-20-FL6 (mot. CO3/60 V.12)-FL 8C-FL9-FL 9B-FR 9-9B-FL 10-10B-FL 12-FR 12B-FR 12C-FL 14-FL 14B-FL 20-FL 20B-PL 40-PL 60 ecc.

#### FIAT

80 C - 90 C - 100 C - 120 C Tractors

#### OM

40-40/55-50-55-65-70-75-80-90-N 100-120 C-N-L-130 R-T-150 ecc.-Cerbiatto-Daino-Leoncino-4x4 NF Leoncino AL5 Bus-Lupetto-Orsetto-Tigrotto 4x4 - M5K-Tigrotto


AI 5- AI 5I Bus

OM Carrelli


DI 120

SIMIT

S 9 - SL 9 - S 11 - SL 11 - S 15 - S 60 (mot. CN3) - S 70 - SR 70 - S 90 (mot. CO3) - S 90 (mot. CP3) - S 105 B



Albi Number: AL 1004  
Replacing: Fiat/Marelli 63304100  
Replacing Delco Remy: 19025036  
**POWER**  
24 Volt 26 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 764	74999371	
3	D.E. Bracket	AL 714	74965511	Without Bearing
4	Rotor	AL 411	74965261	
5	Rectifier	AL 765	74999091	
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	74877551	
8	Thru Bolt	AL 113	74967690	
9	Slipring	AL 910	-	
10	Bearing Plate Kit	AL 193	-	
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	-	
13	Battery Terminal Kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Rotor Nut	AL 72	-	
16	Fan	AL 166	74987100	
17	Pulley	AL 126	74997110	
18	Key	AL 103	10205710	
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	

**Servicing**

**CASE IH**

INTERNATIONAL HARVESTER (CASE IH)

4200 Series

**IVECO**

100 NT, 110 AT Bus, 110 NC, NR, NT, P, PC, R, 343 Bus, 50 A Bus, 616 N3, 625 N3, 645 N3, 650 N3, 655 N1, 662 N3 Bus

**FIAT**


40/35 NC - 40 NC - 50 NC - 55 NC - 80 NC - NR - 90 NC - 100 NC - EC - 110 NC - NT - NR - PC - 616 N3 - N3/4

**OM**


40/35 - 110 - R - T - P - AI Bus

**SIMIT**

S60 (mot. 8045)



Albi Number: AL 1038  
Replaces: Fiat/Marelli 63393215  
**POWER**  
12 Volt 42 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 737	74995281	
3	D.E. Bracket	AL 714	74965511	Without Bearing
4	Rotor	AL 400	74995571	
5	Rectifier	AL 765	74999091	With Positive Diodes
6	Diode Trio	AL 1008	—	
7	Brush Holder	AL 100	74877551	
8	Thru-Bolt	AL -113/H	—	M5x114 mm
9	Slipring	AL 910	—	O.D. 32 mm
10	Bearing Plate Kit	AL 185	—	Plate Hole Ø15 mm
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	—	
13	Battery Terminal Kit	AL 112	—	
14	Bushing Kit	AL 131	—	
15	Rotor Nut	AL 73	—	12x1.25 mm
16	Fan	AL 165	74877100	Ø15 mm
17	Pulley	AL 132	74991600	Cast Iron
18	Key	AL 130	10205720	3x5x14.5 mm
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	
21	Regulator	AL 1043	—	

### Servicing

#### FIAT

480 - 480 DT, 480 V, 540, 540 DT, 600, 616, 619, 640, 640 DT, 684, 697

#### FIAT ALLIS - SIMIT

4 FLAC, FL 4 D, TL, TL 5 H

#### OM CARRELLI


B 120, B 125, BIM 20, 25, BL 10, BM 10, BM 12, BM 15, DI 120, DI 125, DIL 10, 15, DIM 20, DIM 30, DIM 35 B, DM 15

#### FIAT

124, 125, 130, 132

#### SEAT

124, 131E, 132, Panda, 35, 40, 45




Albi Number: AL 1039

Replaces: Fiat/Marelli 63399901

POWER

12 Volt 42 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 737	74995281	
3	D.E. Bracket	AL 755	74966731	Without Bearing
4	Rotor	AL 401	74995641	
5	Rectifier	AL 765	74999091	
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	74877551	
8	Thru Bolt	AL 113/H	-	M 5x114 mm
9	Slipring	AL 910	-	O.D. 32 mm
10	Bearing Plate Kit	AL 193	-	Plate Hole Ø17
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	-	
13	Battery Terminal Kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Rotor Nut	AL 72	-	14x1.5 mm
16	Fan	AL 166	74987100	Ø17 mm
17	Pulley	AL 126	74997110	Cast Iron
18	Key	AL 103	10205810	4x6.5x15 mm
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	
21	Regulator	AL 1043		


### Servicing

#### FIAT


250 - 250 DT - 300 - 300 F - 300 FN - 300 N - 300 V - 350 - 350 DT - 355 - 355 C - 400 - 400 DT - 450 DAL - 450 DT - 455 - 455 C - 455 CF - 455 CM - 480 - 480 V - 500 - 500 DAL - 500 DT - 500 DTS - 505 C - 540 - 540 DT - 550 - 550 DT - 555 - 600 - 600 DT - 605 C - 650 DT - 655 - 750 - 750 DT - 805 C 850 - 850 DT - 850 DTS - 850 S - 1000 - 1000 DT - 1300 - 1300 DT - 1300 DTS - 1300 S

#### OM CARRELLI

BI 30 - BI 30 B - BI 35 - DI 30 - DI 35 - DI 40 - DI 65 - DIM 25 - DIM 25 BD - DM 12 - DM 12 CD



Albi Number: AL 1040  
Replaces: Fiat/Marelli 63399921  
**POWER**  
24 Volt 26 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	74990571	With Negative Diodes
2	Stator	AL 764	74999371	
3	D.E. Bracket	AL 755	74966731	Without Bearing
4	Rotor	AL 402	74999421	
5	Rectifier	AL 765	74999091	
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	74877551	
8	Thru Bolt	AL 113	-	M 5x114 mm
9	Slipring	AL 910	-	O.D. 32 mm
10	Bearing Plate Kit	AL 193	-	Plate Hole Ø17
11	Connection	AL 127	74990390	
12	Rectifier Fixing Kits	AL 115	-	
13	Battery Terminal Kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Rotor Nut	AL 72	-	14x1.5 mm
16	Fan	AL 166	74987100	Ø17 mm
17	Pulley	AL 126	74997110	
18	Key	AL 103	10205810	4x6.5x15 mm
19	Positive Diode	AL 145	74990381	
20	Negative Diode	AL 146	74990371	
21	Regulator	AL 1044	-	

### Servicing

#### FIAT

40/35-40 NC-50 NC-55 NC-80 NC-NR-90 NC-100 NC-EC-110 NC-NR-NT-PC-130 NC-NT-NR-150 NC 17-NC 20-NR 20-NT 20-159 NC 17-NC 20-160 NT-NC-170 NC-NT-190 NC 26-NT 26-NC 33-NT 33-190 PAC 20-300 PC-PT-329 A Bus-241 TN, Campagnola C Diesel-616 N2-616N 2/4-N3-N3/4-619 N-T-N1-N1P-T1-T1P-625 N2-N3-645 N2-N3/4-650 N2-N3-655 N-N1-662 N2-N2P-T-N3-N3P-672 N-673 N-T-TR-682 N3-N4-T3-T4683 N-T-684 N-T-NP-TP-690 N2-N3-N4-T2-691 N-NS-693 N1-T1-697 N-NP-T-TP-Trucks

#### FIAT ALLIS

5 (mot. CN3 V.13) - 7C - 8 - 8B - 9 - 10 - 10B - 12 - 14B - 18 - 20 - FL 6 (mot. CO3/60 V.12) - FL 8C - FL 9 - FL 9B - FR 9 - 9B - FL 10 - 10B - FL 12 - FR 12 - FR 12B - FR 12C - FL 14 - FL 14B - FL 20 - FL 20B - PL 40 - PL 60 ecc.

#### FIAT

80 C - 90 C - 100 C - 120 C - Tractor

#### OM


40 - 40/55 - 50 - 55 - 65 - 70 - 75 - 80 - 90 - N 100 - 120 C - N - L - 130 R - T - 150 ecc. - Cerbiatto - Daino - Leoncino 4x4 NF - Leoncino AL5 Bus - Lupetto - Orsetto - Tigrotto 4x4 - M5K - Tigrotto Al 5 - Al 5I Bus

#### OM Carrelli


#### DI 120

#### SIMIT

S 9 - SL 9 - S 11 - SL 11 - S 15 - S 60 (mot. CN3) - S 70 - SR 70 - S 90 (mot. CO3) - S 90 (mot. CP3) - S 105 B



Albi Number: AL 1049  
Replacing: Fiat / Marelli 63305100  
Replacing Delco Remy: 19025045  
**POWER**  
12 Volt 45 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 792	74876501	
2	Stator	AL 737	74995281	
3	D.E. Bracket	AL 714	74965511	Without Bearing
4	Rotor	AL 400	74995571	
5	Rectifier	AL 1046	74878691	
6	Brush Holder	AL 99	74876641	
7	Regulator	AL 1041	64808140	
8	Thru Bolt	AL 113	74967690	
9	Slipring	AL 910	-	
10	Bearing Plate Kit	AL 185	-	
11	Fan	AL 165	74877100	
12	Pulley	AL 132	74991600	
13	Rotor Nut	AL 73	-	
14	Cover	AL 147	9934954	
15	Diode Trio	AL 999	-	
16	Key	AL 130	10205720	

**Servicing**

**FIAT**

131 Berlina, Familiare, Lusso Special, Confort Lusso, Panorama (1300 - 1600 cc) Supermirafiori Bialbero (1300 - 1600 cc) F.L. 132 Restyling - Restyling Pesante (2000 cc) Argenta all models

**SEAT**


Ibiza 1.7 Diesel, Malaga 1.7 Diesel, Ritmo 65, 75, CLX, Ronda, Crono, 2000, 65, 75 - 124 2000 Especial - 131 + 1400, 1600, 2000, Supermirafiori 132 1600

**LANCIA**

Beta Berlina (1300 - 1400 cc) Beta Coupe (1300 cc)

**POLSKI FIAT**






Albi Number: AL 1050

Replacing: Fiat / Marelli 63305206

Replacing Delco Remy: 19025046

**POWER**

**12 Volt 45 Amper**



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 792	74876501	
2	Stator	AL 737	74995281	
3	D.E. Bracket	AL 755	74966731	Without Bearing
4	Rotor	AL 401	74995641	
5	Rectifier	AL 1046	74878691	
6	Brush Holder	AL 99	74876641	
7	Regulator	AL 1041	64808140	
8	Thru Bolt	AL 113	74967690	
9	Slipring	AL 910	-	
10	Bearing Plate Kit	AL 193	-	
11	Fan	AL 166	74987100	
12	Pulley	AL 126	74997110	
13	Rotor Nut	AL 72	-	
14	Cover	AL 147	9934954	
15	Diode Trio	AL 999	-	
16	Key	AL 103	10205810	

**Servicing**

**ALFA ROMEO**

30 AR8 - 32 AR8 - 35 AR8 - 40 AR8

**FIAT**

580 - DT - 680 - DT - 780 DT - 855 C - 880.5 - 880.DT5 - 955 C - C Super - 980 - 980 DT

**IVECO**

28.8 - 30.8 - 32.8 - 35.8 - 40.8 - 30.8 Bus - 35.8 Bus

**UNIC**

30U8 - 32U8 - 35U8 - 40U8

**HUERLIMANN SCHWEIZ**


H 351 - H 358 - H 358.4 - H 361 - H 361xF - H 410 S

**LAMBORGHINI**


1156 - 1106 DT - 2 RM, - 1306 DT Turbo - 1356 DT - 1506 - 1556 - 1706 Turbo - 956 - 2 RM, - 956 DT

**SAME**

Centauro 70 - 75, Explorer 55, 65C, 75, 85, Galaxy 170, Hercules 60, Jaguar 95, 10Q, Laser 90, 110, 130, 150, Leopard 85, 90 - Mercury 85, Export, Panther 95, Tiger Six 105, Tridend 130, Buffalo 130, Centurion 75, Corsaro 70 Synchro, Drago 120, Taurus 60



Albi Number: AL 1051  
Replacing: Fiat / Marelli 63306000  
Replacing Delco Remy: 19025044  
**POWER**  
24 Volt 30 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 792	74876501	
2	Stator	AL 764	74999371	
3	D.E. Bracket	AL 755	74966731	Without Bearing
4	Rotor	AL 402	74999421	
5	Rectifier	AL 1046	74878691	
6	Brush Holder	AL 99	74876641	
7	Regulator	AL 1042	64808141	
8	Thru Bolt	AL 113	74967690	
9	Slipring	AL 910	-	
10	Bearing Plate Kit	AL 193	-	
11	Fan	AL 166	74987100	
12	Pulley	AL 126	74997110	
13	Rotor Nut	AL 72	-	
14	Cover	AL 147	9934954	
15	Diode Trio	AL 999	-	
16	Key	AL 103	10205810	

**Servicing**

**IVECO**

50.8-50.9-55.8-55.9-55.10-60.10-70.10-75.10-80.13-80.14-80.16-80.17-90.13-95.14-100.13-109.14-110.14-110.14P(4x4)-140.14-150.14-150.17-159.17-160.26-170.26-170.35-170-25AH, 170-34AH, 180-23AH, 25AH, 34AH, 180E 52-190.26-190.26H-190.30-190.35-190.35H, 190-25H-260-25-330.25-190.30P-190.33-190.36 PT-190.42-220.36 PT-220.32 P-220.38 PT-240.30-240.38-240.E52-260.25 AHB-260.30 AH-280.E23T-300 PC-300.32 AH, 34 AH-320.32 AH-330.26 H-330.30 H-330.35 H-400.E52-619 N1P-619T1P-684 N, NP, TP-690 N4-693 N1/T1/-697 N-T-TP

**UNIC**


55 U8-60 U8-60 U10-70 U10-70 U13-75 U10-79 U10-80 U13-90 U13-100 U13-120 U13-120 U14-140 U17-140 U20-140 U20R - 140 U20T - 159 U17-159 U20-159 U20R-159 U20T-170 U20-170 U26-170 U26T-170 U35-170 U35T-190 U20-190 U26-190 U35T

**FIAT**

40/50/60/65/70/75/80/90/100/130/150/160/170/180/220/240/260/300/330/NC/NR/NT

**FIAT ALLIS - SIMIT**

7 D-8-8B-10B-10C-10 CTA-14C-14 CTA-150 CB-161B-FL 9-FLB 9B-FL 10-FL 10B-FL 10C-FL 14C-FL 4L




Albi Number: AL 1380

Replacing: Fiat / Marelli 63320025

Replacing Delco Remy: 19025057

POWER

28 Volt 30 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 789	83602341	
2	Stator	AL 769	83602541	
3	D.E. Bracket	AL 634	83602361	Without Bearing
4	Rotor	AL 436	83602321	
5	Slipring	AL 904	—	
6	Rectifier	AL 1047	63621501	
7	Diode Trio	AL 999	—	
8	Regulator	AL 1061	79707441	
9	Cover	AL 148	85560011	
10	Bushing	AL 78	—	
11	Thru Bolt	AL 120	—	
12	Bearing Plate Kit	AL 1242	—	
13	Fan	AL 996	—	
14	Pulley	AL 178	—	
15	Rotor Nut	AL 72	—	

**Servicing**

**UNIC**

55 UB,60 U8,65 U10,70 U10,75 U10,79 U10,80 U13,90 U13,A55U,100 U13,100 U14,120 U13,120 U14,140 U14,  
159 U17,170 U26,170 U26T,170 U35,190 U26,190 U26T,190 U35,190 U35T


**IVECO**

50.8,50.9,55.8,55.9,55.10,60.8,60.10,65.10,70.10,75.10,79.10,79.13,79.14,80.13,80.14,80.16,90.13,95.14,100.13,  
109.14,110.14,115.17,120.14,135.14,140.14,150.14,159.17,160.26,170.26,170.35,190.26,190.30,190.35,190.38,  
220.35,220.38,240.38,260.35H,330.26 H,330.30 H,330.35 H,Nuove Gamme


Vecchie Gamme 300 PC/300 PT/329/619 N1P/619 T1-T1P/684 N-NP-T-TP/690 N4/693 N1-T1/OM 160/170/190 NC

**FIAT ALLIS - SIMIT**

7 D/8/ 8B / 9 / 10B / 10C / 10 CTA / 14B / 14 C / 20 / FL 4L / FL 6 / FL 9 / FR 20 / FR 7 / PC 14B / PC 20 / SIS / S90



Albi Number: AL 1053  
Replacing: Fiat / Marelli 63321008  
Replacing Delco Remy: 19025056  
**POWER**  
12 Volt 55 Amper



Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 789	83602341	
2	Stator	AL 790	83601541	
3	D.E. Bracket	AL 773	83600941	Without Bearing
4	Rotor	AL 435	83600011	O.D 28 mm
5	Slipring	AL 904	-	
6	Rectifier	AL 1047	63621501	
7	Diode Trio	AL 999	-	
8	Regulator	AL 1027	79707481	
9	Cover	AL 148	85560011	
10	Bushing	AL 78	-	21Dx12.2dx25h
11	Thru Bolt	AL 120	-	M 6 x 80 mm
12	Bearing Plate Kit	AL 1242	-	
13	Fan	AL 996	-	
14	Pulley	AL 178	-	
15	Rotor Nut	AL 72	-	14x1.5 mm

**Sevicing**

**IVECO FIAT**

Daily, Grinta 30.9 - 35.9 Restyling, Ducato

**FIAT**

124 Berlina - Familiare - Special - 131 L - Panorama - CL - CL Panorama (1300 - 1600 cc) - 132 Restyling - Argenta (1600 - 2000 cc) - Duna DS - DS Week-end (1697 cc) - Ritmo L - CL Diesel (1697 cc) - Ritmo 100 S - 105 Diesel (1697 - 1714 - 1929 cc) - F.L. 85 TC (1585 cc) - Tipo 1.7 Diesel - Digit - Regeta DS (1697 - 1714 - 1929 cc) - Week-end - Regeta 100 S (2 ACT 1600 cc) - Week-end - UNO DS (1697 cc) - Turbo DS (1367 cc) - Nuovo Ducato Diesel (1930 cc) - Talento Diesel (1930 cc)

**SEAT**

Ronda - Ibiza - Malaga DS (1714 cc) - Ronda (1200 - 1430 cc) 131 Supermirafiori (1430 cc) - 132 (1600 - 1800 cc)

**LANCIA**


Delta, HF Turbo (1600 cc) - Prisma Diesel (1929 cc) - R/86, Trevi

**MURAT**


1600 Kartal, Şahin, Doğan

**OTOSAN FORD**

Taurus 1.6, 2.0




Albi Number: AL 1121  
Replacing: Fiat Marelli 63395571  
AA125R  
POWER  
12 Volt 55 Amper




Item	Description	Albi No.	Replacing	Remarks
1	S.R.E. Bracket	AL 635	83600040	
2	Stator	AL 790	83601541	
3	D.E. Bracket	AL 872	83634401	Without Bearing
4	Rotor	AL 474	83643801	
5	Slipring	AL 973	-	O.D 28 mm
6	Rectifier	AL 1047	83635701	
7	Diode Trio	AL 999	-	
8	Regulator	AL 1094	83635101	
9	Cover	AL 148	85560011	
10	Bushing	AL 78	-	21D x 12.2dx25h
11	Thru Bolt	AL 120	-	M6 x 80 mm
12	Bearing Plate	AL 1187	-	
13	Fan	AL 996	83639410	
14	Pulley	AL 178	-	
15	Rotor Nut	AL 72	-	14x1.5 mm
16	Oil Seal	AL 1256	83643611	
17	Vacuum Pump	AL 1200	83635201	

**Servicing**

FORD TRANSIT  
III 190 2,5 Di, 190 2,5 Di Turbo



Albi Number: AL 1037  
Replacing: Lada 21053701000  
**POWER**  
12 Volt 42 Amper




Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	21013701300	With Negative Diodes
2	Stator	AL 737	21013701100	
3	D.E. Bracket	AL 705	21013701400	Without Bearing
4	Rotor	AL 400	21013701200	
5	Rectifier	AL 765	-	With Positive Diodes
6	Diode Trio	AL 1008	-	
7	Brush Holder	AL 100	21013701470	
8	Thru Bolt	AL 113	-	
9	Slipring	AL 910	-	O.D 32 mm
10	Bearing Plate Kit	AL 193	-	
11	Connection	AL 127	-	
12	Rectifier fixing kits	AL 115	-	
13	Battery terminal kit	AL 112	-	
14	Bushing Kit	AL 131	-	
15	Fan & Pulley	AL 1186	21013701051	Ø 15 mm
16	Key	AL 130	-	3x5x14,5 mm
17	Nut	AL 73	-	12x1,25 mm

### Servicing

LADA

Niva 1600 4WD, Riva 1200, 1300, 1500, 1600




Albi Number: AL 1013  
Replacing: Lada 21053701005  
**POWER**  
12 Volt 42 Amper

Item	Description	Albi No.	Replacing	Remarks
1	S.R.E.Bracket	AL 1156	21013701300	With Negative Diodes
2	Stator	AL 737	21013701100	
3	D.E. Bracket	AL 705	21013701400	Without Bearing
4	Rotor	AL 400	21013701200	
5	Rectifier	AL 765	-	With Positive Diodes
6	Diode Trio	AL 1008	-	
7	Thru Bolt	AL 113	-	
8	Slipring	AL 910	-	
9	Bearing Plate Kit	AL 193	-	O.D 32 mm
10	Connection	AL 127	-	
11	Rectifier fixing kits	AL 115	-	
12	Battery terminal kit	AL 112	-	
13	Bushing Kit	AL 131	-	
14	Fan & Pulley	AL 1186	21013701051	Ø 15 mm
15	Key	AL 130	-	3x5x14,5 mm
16	Nut	AL 73	-	12x1,25 mm
17	Regulator	AL 1066	21053701500	

### Servicing

LADA

Niva 1600 4WD, Riva 1200, 1300, 1500, 1600, 2105, 2107



Albi Number: AL 1127


Replacing: Lucas A127, 24156

POWER

12 Volt 55 Amper

Left Hand Fixing

Without Fan & Pulley




Item	Description	Albi No.	Replacing	Remarks
1	D.E.Bracket	AL 835	54205169	Without Bearing
2	Stator	AL 821	UIB 100	
3	Rotor	AL 431	UEB 100	
4	Slipring	AL 939	-	
5	Rectifier	-	UBB 137	
6	B + Insulator Kit	AL 1170		
7	S.R.E. Bracket	AL 836	54206507	Without Bearing
8	Regulator	-	UCB 150	
9	Bushing	AL 65	54207056	
10	Thrubolt	AL 137	60600864	
11	Rotor Nut	AL 1222	-	
12	Terminal	AL 46	-	

**Servicing**


**FORD**

Escort III 1.6 D, 35, 55 Van,  
Fiesta II 1.3, 1.4, 1.6 D, III 1.4, 1.6 S, Van,  
Granada III 2.5 TD,  
Orion 1.6 D,  
Sierra 1.6, 1.8, 2.0, 2.3 D






Albi Number: AL 1128  
Replacing: Lucas A127, 24230  
**POWER**  
12 Volt 70 Amper  
Left Hand Fixing  
Without Fan & Pulley




Item	Description	Albi No.	Replacing	Remarks
1	D.E.Bracket	AL 835	54205169	Without Bearing
2	Stator	AL 1108	54208681	
3	Rotor	AL 489	54206860	
4	Slipring	AL 939	-	
5	Rectifier	-	UBB 140	
6	B + Insulator Kit	AL 1170	-	
7	S:R.E. Bracket	AL 858	54206470	Without Bearing
8	Regulator	-	UCB 150	
9	Terminal	AL 968	60601042	
10	Seal	AL 993	-	
11	Bushing	AL 65	54207056	
12	Thrubolt	AL 137	60600864	
13	Rotor Nut	AL 1222	-	
14	Vacuum Pomp	AL 1200	-	

**Servicing**

FORD  
Transit III 80, 100, 100 LWB, 120, 130, 150, 160, 190, 2.5, Di



Albi Number: AL 1129  
Replacing: Lucas A127, 54022425  
**POWER**  
12 Volt 55 Amper  
Right Hand Fixing  
Without Fan & Pulley




Item	Description	Albi No.	Replacing	Remarks
1	D.E.Bracket	AL 835	54205169	Without Bearing
2	Stator	AL 821	UIB 100	
3	Rotor	AL 491	UEB 104	
4	Slipring	AL 939	—	
5	Rectifier	—	UBB 140	
6	B + Insulator Kit	AL 1170	—	
7	S.R.E. Bracket	AL 858	54206470	Without Bearing
8	Regulator	—	UCB 150	
9	Terminal	AL 957		
10	Seal	AL 993		
11	Vacuumpomp	AL 1200		
12	Bushing	AL 65	54207056	
13	Thrubolt	AL 137	60600864	
14	Nut	AL 1222	—	


**Servicing**

FORD

Transit III 80, 100, 100 LWB, 120, 130, 150, 190, 2.5, Di



Albi Number: AL 1135  
Replacing: Lucas A127, 24208  
**POWER**  
12 Volt 55 Amper  
Left Hand Fixing  
Without Fan & Pulley



Item	Description	Albi No.	Replacing	Remarks
1	D.E.Bracket	AL 857	54205168	Without Bearing
2	Stator	AL 821	UIB 100	
3	Rotor	AL 431	UEB 100	
4	Slipring	AL 939	-	
5	Rectifier	-	UBB 137	
6	B + Insulator Kit	AL 1170	-	
7	S.R.E. Bracket	AL 836	54206507	Without Bearing
8	Regulator	-	UCB 150	
9	Bushing	AL 65	54207056	
10	Thrubolt	AL 137	60600864	
11	Nut	AL 1222	-	
12	Terminal	AL 46	-	

**Servicing**

**MASSEY FERGUSON**

MF154F, S, 243C, 240.3, 254, 254C, 350, 355, 360, 365, 375, 383, 390,  
398, 399, 698, 1014, 1114, 1134 Tractors

**ROVER**

Maestro 1.3, 2.0 D, Van 500, 700, MG Metro, Montego

**LDV**

200, 2.0t, 2.2t, 2.3t, 2.4t, 2.5t, 2.6t, 2.8t, Sherpa II, 200, 230, 250, 255, 280 Di Diesel


**JCB**

2 DX, 3CX, 3D, 406, 410, 412, 415, 420, 430 Loaders

520-2, 520-4, 525 B, 540 B Loadalls


811, 812, 814, 817, 818, 820 Power Slide Excavators

926, 930 Forklifts




**AL 1138**

Replacing Lucas A127 24158  
 Servicing JCB, Rover  
 12v 65 Amp, Right Hand Fixing  
 Without Fan & Pulley




**AL 1141**

Replacing Lucas A127 24298  
 Servicing Ford, Rover  
 12v 55 Amp, Right Hand Fixing  
 Without Fan & Pulley




**AL 1150**

Replacing Lucas A127 24316  
 Servicing Landrover  
 12v 55 Amp, Left Hand Fixing  
 Without Fan, Pulley & Pump




**AL 1307**

Replacing Bosch 0120689541  
 Servicing MAN  
 28v 140 Amp




**AL 1349**

Replacing Bosch 0120689516  
 Servicing IVECO FIAT 315 +8, 18  
 LORRAINE (PLAXTON) 240 C5, 300 LS  
 ORLANDI Domino, Poker 370, 12, 35  
 28v 100 Amp




**AL 1369**

Replacing Bosch 0120689511  
 Servicing SCANIA  
 28v 120 Amp




**AL 1371**

Replacing Bosch Modified Type  
 Servicing Special Applications  
 28v 180 Amp




### AL 1090

Replacing Bosch 0120 689 515  
Servicing Mercedes Benz, Otomarsan  
28 V. 95 Amp.




### AL 1012

Replacing Turkish Marelli 63393051  
Servicing AA125R 28 v 30 Amp.  
Iveco, Unic (Same AL 1380 Alternator  
D.E. Bracket used Al 773 D.E. Bracket)  
Without Fan & Pulley




### AL 1120

Replacing Turkish Marelli 63395562  
Servicing AA125R 12 v 55 Amp.  
Peugeot J9 Minibus  
Without Fan & Pulley




### AL 1123

Replacing Turkish Marelli 63395569  
Servicing AA125R 12 v 55 Amp.  
Massey Ferguson MF240/MF255/MF285  
Without Fan & Pulley




### AL 1059

Replacing Bosch Modified Type  
Servicing 12v 55 Amp.  
Magirus Deutz, Mercedes Benz




**AL 1017**

Replacing Bosch Modified type  
 Servicing 24 V80 Amp.  
 Volvo Trucks




**AL 1058**

Replacing Bosch Modified type  
 Servicing 24 V35 Amp.  
 Man Trucks




**AL 1007**

Replacing Bosch Modified type  
 Servicing 24 V 70 Amp.  
 Special for Airconditions




**AL 1028**

Replacing Bosch Modified type  
 Servicing 12 V 110 Amp.  
 Fiat, Setra, Daf, Trucks




**AL 1101**

Replacing Bosch Modified type  
 Servicing 24 V 35 Amp.  
 Mercedes Benz Trucks




**AL 1105**

Replacing Bosch Modified type  
 Servicing 24 V 70 Amp.  
 Scania (Single Pulley )




**AL 1054**

Replacing Bosch Modified type  
 Servicing 24 V 35 Amp.  
 Iveco, Magirus Deutz



**AL 1102**


Replacing Bosch Modified type  
 Servicing 24 V 55 Amp.  
 Daf Trucks



**AL 1125**

Replacing Bosch Modified type  
 Servicing 24 V 70 Amp.  
 Scania ( Double Pulley )


12v 90 Amp



**AL 403**

Replacing Bosch 1124 035 064  
 Servicing 0120 469 522  
 Volvo Trucks


24v 35 Amp



**AL 406**

Replacing Bosch 1124 034 176  
 Servicing 0120 489 224, -320, -731,  
 -827, -944


24v 120 Amp



**AL 429**

Replacing Bosch 1124 037 002  
 Servicing 0120 689 520, -522, -526, -528  
 -531, -533, -534, -540, -543, -545


24v 55 Amp



**AL 404**

Replacing Bosch 1124 035 057, 059  
 Servicing 0120 469 523, -549, -569, -634,  
 -673, -679, -693, -763, -798, -807


12v 35 Amp



**AL 415**

Replacing Bosch 1124 034 025  
 Servicing 0120 400 639, -645, -700, -729,  
 -736, -788, -874, -904


24v 95 Amp



**AL 432**

Replacing Bosch 1124 037 000  
 Servicing 0120 689 503, -504, -505, -506,  
 -507, -508, -510, -512, -514, -515, -516,  
 -524, -525


12v 55 Amp



**AL 405**

Replacing Bosch 1124 034 155  
 Servicing 0120 489 022, -704, -710, -725,  
 902, -994, -995, -996


24v 27 Amp



**AL 422**

Replacing Bosch 1124 034 015  
 Servicing 0120 400 642, -666, -694,  
 -699, -774, -791, -805, -826, -884, -891


12v 65 Amp



**AL 490**

Replacing Bosch 1124 034 341  
 Servicing 0120 488 205


24v 45 Amp



**AL 492**

Replacing Bosch 1124 034 677  
 Servicing 0120 488 206, -234, -252, -253,  
 -266, -283, -288, -294


12v 42 Amp



**AL 400**

Replacing Fiat / Marelli 4300244, 749 955 71  
 Servicing 4152612, 4306041, 4474904,  
 633 031 00


24v 26 Amp



**AL 411**

Replacing Fiat / Marelli 74965261  
 Servicing 63304100


24v 140 Amp



**AL 803**

Replacing Bosch 1124 037 004  
 Servicing 0120 689 527, -530, -535, -541,  
 -546, 548, -549


12v 42 Amp



**AL 401**

Replacing Fiat / Marelli 4278945, 749 956 41  
 Servicing 4222697, 633 048 00


12v 55 Amp



**AL 435**

Replacing Fiat / Marelli 836 000 11  
 Servicing 633 210 00, -01, -03, -04, -05,  
 -08, -11


24v 26 Amp



**AL 402**

Replacing Fiat / Marelli 4278890, 749 994 21  
 Servicing 4474902, 633 040 87

24v 30 Amp




**AL 436**

Replacing Fiat Marelli 8190466, 836 023 21  
 Servicing AA 125 R, 633 200 25,  
 633 210 45, -46, -47, -48, -49, -50, -52,  
 -55, -63




12v 55 Amp



**AL 474**

Replacing Fiat / Marelli 83643801  
Servicing 943358060  
Ford Transit


12v 55 Amp



**AL 431**

Replacing Lucas UEB 100  
Servicing 24145, 24156, 24157, 24158,  
24200, 24208, 24214, 24215, 24236, 24260,  
24261, 24262, 24271, 24272, 24273, 24276,  
24277, 24278, 24295, 24296, 24298, 24300,  
24303, 24332, 24408


12v 70 Amp



**AL 489**

Replacing Lucas 54206860  
Servicing 24230, 24264, 24293, 24374,  
24396, 24399, 24402


12v 55 Amp



**AL 491**

Replacing Lucas 54206600, UEB104  
Servicing A127, 24188, 24316,  
54022130, -425, -54022459, -495, -564, -575  
-689, -690, -694


24v 27 Amp



**AL 420**

Replacing Bosch 1125 045 018  
Servicing 0120 400 640, -642, -664, -666,  
-685, -690, -694, -699, -715, -732, -773, -774  
-790, -791, -799, -805, -826, -830, -843, -846,  
-878, -846, -878, -884, -888, -891, -940


12v 35 Amp



**AL 784**

Replacing Bosch 1125 045 010  
Servicing 0120 400 602, -603, -605, -608,  
-609, -611, -615, -621, -623, -625, -631, -639,  
-645, -653, -655, -657, -659, -661, -663, -670  
675, -678, -698, -700, -701

12v 55 Amp



**AL 804**

Replacing Bosch 1125 045 012  
Servicing 0120 400 722, -723, -733, -743,  
-747, -772, -782, -783, -806, -807, -809,  
-810, -853, -859, -869, -873, -885, -899, -909,  
-922, -928, -943, 0120 488 003, -114


12v 65 Amp



**AL 498**

Replacing Bosch 1125 045 043, -063  
Servicing 0120 400 725, -945,  
0120 488 001, 0120 489 003, -004, -005,  
-007, -017, -021, -024, -029, -031, -037,  
040, -058, -063, -064, -077, -080, -081


12v 90 Amp



**AL 793**

Replacing Bosch 1125 045 102, -130, -137,  
Servicing 0120 450 003, 0120 469 506,  
-507, -515, -522, -526, -532, -534, -535, -546,  
-547, -548, -556, -557, -558, -566, -584, -589,  
-591, -607, -620, -642, -683, -685, -695, -745,  
746, -721, -749, -754

24v 35 Amp



**AL 826**

Replacing Bosch 1125 045 047,  
Servicing 0120 400 617, -695, -708, -720,  
-784, -887, -0120 489 053, -192, -224, -230,  
-320, -684, -702, -731, -827, -944,  
9120 144 102, -103, -104, -105, -107, -109


24v 45 Amp



**AL 499**

Replacing Bosch 1125 045 088  
Servicing 0120 488 206  
CASE, CUMMINS


24v 55 Amp



**AL 794**

Replacing Bosch 1125 045 105  
Servicing 0120 469 509, -518, -527, -549  
-562, -634, -673, -679, -761


24v 95 Amp



**AL 848**

Replacing Bosch 1125 047 001, -003  
Servicing 0120 689 503, -504, -505, -506,  
-507, -508, -510, -514, -516, -517, -523,  
-524, -525


24v 120 Amp



**AL 849**

Replacing Bosch 1125 047 004, -005  
Servicing 0120 689 511, -513, -517, -518,  
-520, -522, -526, -528, -531, -533, 534, -538  
-539, -540, -543, -545, -550

12v 42 Amp



**AL 737**

Replacing Fiat Marelli 4149593, 749 852 81  
Servicing 4149590, 4152101, 4152612,  
4181511, 4205498, 4222697, 4474904


12v 55 Amp



**AL 790**

Replacing Fiat Marelli 836 015 41  
Servicing 633 200 30, 633 210 03,  
-05, -08, -11, -60


24v 140 Amp



**AL 853**

Replacing Bosch 1125 047 007  
Servicing 0120 689 527, -530, -535, -541,  
-546, -548, -549

24v 26 Amp



**AL 764**

Replacing Fiat Marelli 4150782, 749 993 71  
Servicing 4150779, 4152610, 4220357,  
4223787, -4278696, 4474592, 4474902

12v 42 Amp



**AL 791**

Replacing Fiat Marelli 4305655, 749 653 21  
Servicing 4306041, 4475303


24v 30 Amp



**AL 769**

Replacing Fiat Marelli 836 025 41  
Servicing 633 083 00, 633 200 25

A127, 12v 55 Amp



**AL 821**

Replacing Lucas 54205305, UIB 100  
Servicing 24145, 24156, 24157, 24188,  
24200, 24208, 24214, 24215, 24236, 24260,  
24261, 24262, 24271, 24272, 24273, 24276  
24277, 24278, 24289, 24295, 24296, 24298,  
24300, 24303, 24316, 24332, 24408


A127, 12v 65 Amp



**AL 1108**


Replacing Lucas UIB 101, 54205306  
Servicing 24158, 24161, 24202, 24209,  
24220, 24221, 24224, 24228, 24255, 24258,  
24232, 24240, 24241, 24242, 24245, 24255,  
24279, 24286, 24287, 24290, 24291, 24297,  
24301, 24302, 24304, 24348, 24350, 24352,  
24356, 24374, 24380, 24392, 24396, 24398,  
24399, 24402, 24403, 24409, 24411, 24418

24v 125 Amp




**AL 1367**

Replacing Delco Remy 19025459  
Servicing 19025304, 305  
VG 921, 921/1  
24v 125 Amp.  
IKARUS (Buses)  
SPECIAL APPLICATIONS




**AL 648**

Replacing Bosch 1125 825 009  
Servicing 0120 469 506, -509,  
-518, -526, -540




**AL 693**

Replacing Bosch 1125 825 036  
Servicing 0120 469 549, -679, -849




**AL 736**

Replacing Bosch 1125 824 340  
Servicing 0120 489 731




**AL 664**

Replacing Bosch 1125 825 133  
Servicing 0120 469 015, -790, -822, -823,  
-832, -839, -888, -889, -908, -953, -975, -998




**AL 720**

Replacing Bosch 1125 824 247  
Servicing 0120 400 837, -863  
0120 489 566, -584




**AL 745**

Replacing Bosch 1125 825 031  
Servicing 0120 469 522, -523




**AL 665**

Replacing Bosch 1125 825 113  
Servicing 0120 469 689, -690, -709, -831




**AL 731**

Replacing Bosch 1125 824 590  
Servicing 0120 488 224, 0120 489 707,  
-710, -730




**AL 762**

Replacing Bosch 1125 824 528  
Servicing 0120 484 005, -006, -013, -014,  
0120 489 025, -026, -078, -184, -254,  
-274, -275, -276, -279, -298, -299, -310,  
-311, 0120 489 312, -322, -355, -359




**AL 676**

Replacing Bosch 1125 825 043  
Servicing 0120 469 569, -643, -762, -900




**AL 732**

Replacing Bosch 1125 824 317  
Servicing 0120 489 723, -724, -727, -728




**AL 763**

Replacing Bosch 1125 825 078, -176  
Servicing 0120 469 581, -582, -586, -587,  
-600, -604, -605, -632, -633, -635, -636, -638  
-654, -697, -698, -699, -700, -702, -703, -704  
-729, -730, -731, -732, -733




**AL 783**

Replacing Bosch 1125 824 194  
 Servicing 0120 400 645, -666, -732, -805




**AL 834**

Replacing Bosch 1125 824 550, -415  
 Servicing 0120 489 228, -229, -362, -363, -367, -368, -436, -437, -439, -440, -443, -444




**AL 882**

Replacing Bosch 1125 827 009  
 Servicing 0120 689 515, -532




**AL 808**

Replacing Bosch 1125 824 212, -593  
 Servicing 0120 400 859, -0120 489 033, -034, -035, -055, 061, -388, -470, -527 -556, -683, -623, -733, -786, -828, -878, -902, -918, -931, -932, -933, -994, -995 -996, 9120 144 270




**AL 867**

Replacing Bosch 1125 824 382  
 Servicing 0120 489 944




**AL 884**

Replacing Bosch 1125 827 013  
 Servicing 0120 689 520, -522, -527, -530 -533, -534, -535, -540, -541




**AL 819**

Replacing Bosch 1125 823 007  
 Servicing 0120 300 533, -552, -564, -579, 0120 339 574, -526, -531, -538, -542 9120 143 222




**AL 868**

Replacing Bosch 1125 824 363  
 Servicing 0120 489 853




**AL 1160**

Replacing Bosch 1125 825 354  
 Servicing 0120 468 131  
 Scania




**AL 833**

Replacing Bosch 1125 825 018  
 Servicing 0120 450 009, 0120 469 568, -628, -664, -668, -751, -792




**AL 870**

Replacing Bosch 1125 824 466, -575  
 Servicing 0120 484 011, 0120 488 205 -293, 0120 489 475




**AL 1192**

Replacing Bosch 1125 827 020  
 Servicing 0120 689 538  
 IVECO, EUROCLASS




**AL 1275**

Replacing Bosch 1125 825 352  
Servicing 0120 468 127, -128, -134  
Ford (40v 50/90 Amp)




**AL 1509**

Replacing Bosch 9121335540  
Servicing 6033 GB 3010, 0120468143, 145  
Mercedes Actros 28v 100 Amp.




**AL 1557**

Replacing Bosch 1125 824 432  
Servicing 0120 489 315,-316  
Mercedes Benz Bus & Trucks




**AL 1370**

Replacing Bosch 1125 824 298  
Servicing 0120 489 060, 643  
Volvo



**AL 1512**


Replacing Bosch 1125 824 583  
Servicing 0120 489 192, 702  
Scania, Renault, Pegaso



**AL 1381**


Replacing Bosch 1125 825 215  
Servicing 0120 468 057,-058,-059,-060  
Mercedes Benz

(N)




**AL 1375**

Replacing Bosch 1125 825 358  
Servicing 0120 468 135, 144  
6033 GB 3021 Volvo (28v 80 Amp)



**AL 1513**


Replacing Bosch 1125825365  
Servicing 0120469115, 116  
Mercedes Actros 28v 80 Amp.



**AL 1610**


Replacing Bosch 1125 825 222,-305,-325,-507  
Servicing 0120 465 003,-015,-016,-017,-021,  
-022,-023,-038,-039,-040,-049,-067,-075,-080,  
0123 500 001, 0123 510 001,-012,-018

(N)




**AL 1386**

Replacing Bosch 1125825218  
Servicing 0120469524, 525, 579  
580, 583, 584, 772 Unimog



**AL 1527**


Replacing Bosch 1125 825 346,-260  
Servicing 0120 468 037,-114  
Volvo Trucks



**AL 1648**


Replacing Bosch 1125 825 264  
Servicing 0120 469 521  
Ford, Steyr, Iveco

(N)




**AL 634**

Replacing Fiat / Marelli 836 023 61, 8190465  
 Servicing AA 125R, 633 200 15, -21, -23,  
 -25, 633 210 19, -20, -22, -28, -35, -36, -37,  
 -40, -41, -42, -45, -46, -47, -48, -49, -50, -52,  
 -55, -63  
 Without Bearing




**AL 667**

Replacing Fiat / Marelli 836 069 21  
 Servicing AA125R, 633 200 48, -55, -82,  
 -83, 633 201 32 633 210 91, -98,  
 633 211 08, -50, -51, -56, -57  
 Without Bearing




**AL 740**

Replacing Turkish / Marelli 836 024 020  
 Servicing AA125R,  
 633 955 62  
 Peugeot J9 Minibus  
 Without Bearing




**AL 640**

Replacing Fiat / Marelli 836 380 02  
 Servicing AA125R  
 633 955 64  
 Without Bearing




**AL 699**

Replacing Turkish/ Marelli 836 024 010  
 Servicing AA125R 633 925 32  
 Renault R9 / R11 / R12 / R19  
 Without Bearing




**AL 755**

Replacing Fiat / Marelli 749 667 31,  
 Servicing 633 040 00, 633 045 00,  
 633 048 00  
 Without Bearing




**AL 666**

Replacing Fiat / Marelli 836 380 04 .  
 Servicing AA125R  
 633 955 69, 633 955 74  
 Without Bearing



**AL 714**


Replacing Fiat / Marelli 749 655 11,  
 Servicing A12M124, 633 031 00, -10, -90  
 633 032 00, -90, 633 033 00, -80, -90,  
 633 035 00, -11, -81, 633 037 80  
 633 041 00, -20  
 Without Bearing



**AL 773**


Replacing Fiat / Marelli 836 009 41,  
 Servicing AA125R, 633 200 07, -08, -31,  
 633 210 08, -09, -10, -11, -29, -61, -71  
 Without Bearing






**AL 810**

Replacing Fiat / Marelli 749 914 71  
 Servicing 633 999 22  
 Without Bearing




**AL 872**

Replacing Fiat Marelli 836 344 01  
 Servicing 633 955 71  
 Without Bearing




**AL 705**

Replacing Lada 2101-3701400  
 Servicing 2101-3701000  
 Without Bearing




**AL 864**

Replacing Fiat / Marelli 836 007 21,  
 Servicing AA 125R, 633 200 04, -05, -10  
 -28, -56, -91, 633 210 03, -04, -05, -13  
 -15, -58, 633 211 09, -59  
 Without Bearing



**AL 1562**


Replacing Fiat / Marelli 836 113 91,  
 Servicing A115i, 633 212 52, -83,  
 633 213 96, 633 216 08, -09, -25  
 Without Bearing



**AL 871**

Replacing Fiat Marelli 836 019 31,  
 Servicing AA 125R, 633 210 19, -35, -49, -55  
 Without Bearing


A127



**AL 710**

Replacing Lucas UNT 257  
 Servicing 619 201 52  
 Without Bearing


A115



**AL 827**

Replacing Lucas UNT 100  
 Servicing 619 200 12, -22  
 Without Bearing


A127



**AL 835**

Replacing Lucas 54205169  
 Servicing A127 L/H  
 24157, 24158, 24199, 24202, 24206, 24215,  
 24216, 24220, 24233, 24235, 24245, 24249,  
 24256, 24273, 24274, 24277, 24294, 24298,  
 24318, 24327, 24387, 24400, 24407  
 Without Bearing


ACR



**AL 723**

Replacing Lucas 54200544  
 Servicing ACR 17-18  
 R.H. mtg.  
 Without Bearing


A115



**AL 828**

Replacing Lucas UNT 105  
 Servicing 619 200 13, -14, -43  
 Without Bearing


A127



**AL 857**

Replacing Lucas 54205168  
 Servicing A127 R/H  
 24145, 24156, 24161, 24169, 24188, 24198,  
 24200, 24207, 24217, 24221, 242223, 24224,  
 24228, 24230, 24231, 24236, 24240, 24257,  
 24260, 24261, 24262, 24264, 24271, 24276,  
 24288, 24293, 24295, 24299, 24308, 24316,  
 24334, 24348, 24350, 24374, 24384, 24385,  
 24406, 24408


ACR



**AL 760**

Replacing Lucas 54200542  
 Servicing ACR 15-16  
 R.H. mtg.  
 Without Bearing


A115



**AL 829**


Replacing Lucas UNT 104  
 Servicing 619 200 17  
 Without Bearing

A127




**AL 875**

Replacing Lucas  
 Servicing A127  
 Right and left hand  
 W/o thread  
 Without Bearing



**AL 1233**


Replacing Paris Rhone 101512  
 Servicing A14N3T, 28T, 29M, -30M, 31T, 32T  
 Without Bearing



**AL 741**

Replacing Nippondenso 021401-3670  
 Servicing 100211-1000, -1001, -1010,  
 -1011, -1020, -1021, -1040, -1041, -1060  
 -1061, -1140, -1141, -1170, -1171, -2020,  
 -2021, -2070, -2071, -2170, -2470, -2480  
 Without Bearing


ACR



**AL 1157**


Replacing Lucas 54219275  
 Servicing ACR  
 L.H. mtg.  
 Without Bearing

(N)




**AL 1598**

Replacing Delphi  
 Servicing 10480403/LT744  
 Mercedes Benz




**AL 832**

Replacing Mando Melroe  
 Servicing AR 150AA, -BA, -CC  
 Without Bearing




**AL 1290**

Replacing Delco Remy 19025480  
 Servicing 19025300, 301, 302, 303, 304,  
 305, 306, 307, 308, 309  
 VG 911, 911/1, 911/2, 916, 921, 921/1, 926,  
 931, 936, 941  
 IKARUS (Buses)  
 SPECIAL APPLICATIONS




**AL 691**

Replacing Bosch 1125 884 359  
 Servicing 0120 489 723,  
 -724, -725, -726, -727, -728, -757




**AL 730**

Replacing Bosch 1125 884 529  
 Servicing 0120 489 192, -230, -303, -643  
 -684, -702, -731, -827, -944




**AL 818**

Replacing Bosch 1125 883 056  
 Servicing 0120 300 552, -562, -575, -576,  
 -577, -578, -579, -580, -585, -586, -589, -590,  
 0120 339 511, -512, -513, -514, -521, -531,  
 -532, -535, -536, -537, -538, -542




**AL 692**

Replacing Bosch 1125 885 036  
 Servicing 0120 469 010, -022, -023, -026,  
 -027, -031, -549, -634, -673, -849, -890,  
 -978, -999




**AL 733**

Replacing Bosch 1125 884 359, -527  
 Servicing 0120 488 133, -136, -153,  
 0120 489 023, -032, -033, -034, -035, -055,  
 -221, -231, -284, -388, -707, -710, -733, -757,  
 -886, -902, -994, -995, -996




**AL 820**

Replacing Bosch 1125 884 398  
 Servicing 0120 489 510, -536, -551, -568  
 -587, -588, -589, -590, -592, -593, -617




**AL 697**

Replacing Bosch 1125 884 493  
 Servicing 0120 484 001, -011,  
 0120 488 134, -205, -0120 489 365, -366  
 -370, -371, -375, -379, -381, -425, -430,  
 -431, -438, -441, -445, -448, -449




**AL 744**

Replacing Bosch 1125 885 019, -157  
 Servicing 0120 469 522, -523, -749, -798




**AL 865**

Replacing Bosch 1125 885 070  
 Servicing 0120 469 672, -697, -698, -699,  
 -700, -702, -703, -704, -705, -707, -708,  
 -714, -716, -718, -720




**AL 698**

Replacing Bosch 1125 885 077  
 Servicing 0120 469 015, -689, -690, -709,  
 -790, -822, -823, -831, -832, -839, -888  
 -889, -903, -908, -953, -975, -998




**AL 780**

Replacing Bosch 1125 884 079  
 Servicing 0120 400 639, 640, -645, -666  
 -780, -791, -805, -826, -843




**AL 869**

Replacing Bosch 1125 885 052  
 Servicing 0120 469 581, -582, -586, -587,  
 -588, -589, -590, -591, -594, -595, -600, -603,  
 -611, -620, -641, -642, -644, -645, -667, -684  
 -695, -944, -945, -949, -950




**AL 883**

Replacing Bosch 1125 887 003  
 Servicing 0120 689 503, -506, -508, -512  
 -513, -515, -532




**AL 1169**

Replacing Bosch 1125 887 019  
 Servicing 0120 689 522, -527, -540, -541,  
 -543, -548, -549, -552, -561, -562, -563,  
 -566, -569




**AL 1504**

Replacing Bosch 1125 885 270  
 Servicing 0120 469 115, 116, 117  
 Mercedes Actros (28v 80 Amp)




**AL 885**

Replacing Bosch 1125 887 013  
 Servicing 0120 689 520, -523, -526, -530,  
 -533, -534, -535, -546




**AL 1191**

Replacing Bosch 1125 887 023  
 Servicing 0120 689 538  
 IVECO




**AL 1505**

Replacing Bosch 9121 335 952  
 Servicing 0120 468 143, 145  
 Mercedes Actros (28v 100 Amp)




**AL 1159**

Replacing Bosch 1125 885 143, -154  
 Servicing 0120 469 008, -019, -024, -025  
 -030, -038, -039, -518, -519, -520, -521, -526  
 -532, -540, -562, -569, -580, -585, -592, -630,  
 -643, -652, -653, -692, -753, -761, -762, -763,  
 -772, -773, -807, -843, -851, -853, -855, -891




**AL 1362**

Replacing Bosch 1125 885 230  
 Servicing 0120 468 135, 144, Volvo




**AL 1387**

Replacing Bosch  
 Servicing Similar 11258870019 bracked used  
 special mounting bushing  
 MAN Trucks




**AL 1161**

Replacing Bosch 6033 GD1 016  
 Servicing 0120 468131  
 Scania



**AL 1503**


Replacing Bosch 1125 885 264  
 Servicing 0120 469 101, 103  
 Mercedes Benz 28v 55 Amp.



**AL 1528**


Replacing Bosch 1125 885 139  
 Servicing 0120 468 037, -114  
 Volvo Trucks

(N)



**AL 1611**

Replacing Bosch 1125 885 217,-235  
 Servicing 0120 465 003,-004,-013,-014,  
 -015,-016,-017,-018




**AL 789**

Replacing Fiat / Marelli 836 023 41,  
 Servicing AA 125R 633 200 08,-21,-23,  
 25, 633 210 09,-10,-11,-29,-35,-36,-37,-40,-41,  
 -42,-45,-46,-47,-48,-49,-50,-52,-55,-63,-71




**AL 805**

Replacing Fiat / Marelli 749 905 51  
 Servicing A12M 124  
 Complete unit with rectifier, connction &  
 Negative diodes




**AL 770**

Replacing Fiat / Marelli 836 000 61  
 Servicing AA 125R, 633 200 01,  
 633 200 02, 633 210 00, 633 211 13




**AL 792**

Replacing Fiat / Marelli 748 765 01  
 Servicing AA 125, 633 050 00,  
 633 052 06, 633 053 00, 633 054 00,  
 633 054 05,-06,-24, 633 055 06,  
 633 074 30




**AL 1156**

Replacing Fiat / Marelli 749 905 71  
 Servicing A12M 124  
 With 3 negative diodes




**AL 715**

Replacing Fiat / Marelli 749 905 51  
 Servicing A 12M-124 633 040 00,-01,-87  
 633 041 00



**AL 663**

Replacing Fiat / Marelli 836 349 01  
 Servicing Ford Transit  
 Early Model




**AL 670**

Replacing Fiat / Marelli 836 032 11, 9940859  
 Servicing AA 125R, 633 200 04,-06,-10,-28,  
 633 210 03,-04,-05,-06,-07,-13,-15,-58

**AL 635**

Replacing Fiat / Marelli 836 400 04  
 Servicing AA 125R 943 358 060  
 Ford Transit M15 - 190 V


A127



**AL 668**

Replacing Lucas UQT 255  
Servicing 619 201 51, -52  
BMC Profesyonel  
Without Bearing


A127



**AL 836**

Replacing Lucas 542 065 07  
Servicing 24145, 24157, 24158, 24161,  
24169, 24198, 24199, 24200, 24206, 24207,  
24208, 24209, 24215, 24216, 24217, 24220,  
24221, 24223, 24228, 24231, 24232, 24233  
24240, 24241, 24242, 24245, 24249, 24257,  
24260, 24261, 24272, 24276, 24290, 24294,  
24298, 24299, 24308, 24318, 24334, 24348,  
24350, 24351, 24352, 24356, 24382, 24392,  
24398, 24406


A127



**AL 858**

Replacing Lucas 542 064 70  
Servicing 24188, 24230, 24264, 24293,  
24316, 24374, 24396, 24399, 24402  
Without Bearing


A127



**AL 669**

Replacing Lucas UQT 252  
Servicing 619 200 68,  
BMC Leyland Van  
Without Bearing


A127



**AL 1194**

Replacing Lucas 542 064 70  
Servicing Same AL 858  
With Needle Bearing


A127



**AL 1193**

Replacing Lucas 542 06 507  
Servicing Same AL 836  
24145, 24157, 24158, 24161,  
24169, 24198, 24199, 24200, 24206, 24207,  
24208, 24209, 24215, 24216, 24217, 24220,  
24221, 24223, 24228, 24231, 24232, 24233  
24240, 24241, 24242, 24245, 24249, 24257,  
24260, 24261, 24272, 24276, 24290, 24294,  
24298, 24299, 24308, 24318, 24334, 24348,  
24350, 24351, 24352, 24356, 24382, 24392,  
24398, 24406  
Bracket with Needle Bearing


A127



**AL 722**


Replacing Lucas 542 007 81  
Servicing ACR 15-16-17-18

A127




**AL 860**

Replacing Lucas 542 065 08  
Servicing 24242  
Without Bearing



**AL 843**


Replacing Mitsubishi  
Servicing A2T26391, -27011  
Citroen, Peugeot



**AL 1232**


Replacing Paris Rhone 101523  
Servicing A14 N3T, -28T, -29T, -30M, -31T  
-32T





**AL 660**

Replacing Bosch 1125 500 023  
Servicing 0120 689 503,-506,-508,-512,  
-513,-515,-520,-523,-526,-530,-532,-533,  
-534,-535,-546



(N)

**AL 1574**

Replacing Bosch FOOM 126 603, FOOM 146 639  
Servicing 0124 225 012, 0124 315 001,-002,  
-003,-004,-005,-006,-007,-008,-010,-011,-012,-013,  
-014,-018,-022, 0124 320 002, 0124 325 001,-002,-003




**AL 199**

Replacing Ducellier 669 481  
Servicing 7527, 7530, 7541, 7549, 7550, 7551,  
7557, 7558, 7564, 7576, 7577, 7578, 7591, 7595,  
7596, 7597, 7599, 513001, 514006, 514007, 514008



**AL 662**

Replacing Bosch 1125 500 117,-190,-623  
Servicing 0120 485 022,-012,-022  
0123 310 008,-041, 0123 315 005,  
0123 320 010,-011,-029,-039,-040,-041,  
-044,-045,-046,-047,-049,-051,-057,-060,  
-061,-062,-065, 0123 325 007




**AL 713**

Replacing Ducellier 691094  
Servicing 516008B, 516009A, B




**AL 690**

Replacing Bosch 1125 500 128  
Servicing 0120 485 034,-036,-038,-039,-043




**AL 831**

Replacing Femsa 26431 - 1  
Servicing Ford Blue S.R.E.




**AL 147**

Replacing Fiat Marelli 9934954  
Servicing AA125, 633 051 00, -01, -02,  
-20, -22, -30, -31, 633 052 06, -26, -36, -46  
633 060 00, -10, -20, -30, -40, -50, -60, -70,  
-79, -80, -89, -90, -99




**AL 148**

Replacing Fiat Marelli 855 600 11  
Servicing AA125, 633 210 57,




**AL 724**

Replacing Lucas 542 035 54  
 Servicing A133, 24101, 24102, 24150,  
 24173, 24176




**AL 1227**

Replacing Lucas 542 090 19  
 Servicing A127, 540 224 43, -549




**AL 200**

Replacing Paris Rhone 590565  
 Servicing A13N50, -65, -112, -114, -120,  
 -125, -127, -128, -150, -156, -157, -158,  
 -159, -160, -161, -162, -164, -171, -172  
 -173




**AL 862**

Replacing Lucas A127, 162022  
 Servicing 24220




**AL 194**

Replacing Motorola European 2940303 A  
 Servicing 2940303, 2940304,  
 2940305 A, 2940308




**AL 678**

Replacing Paris Rhone 590716  
 Servicing A13E19, 2518017




**AL 1226**

Replacing Lucas  
 Servicing A127i, 540 224 59, -498




**AL 198**

Replacing Motorola European 541-080  
 Servicing 9AR2726G, -2727, -2727G,  
 -2839, -2839G, -2896, -2896G, -2926




**AL 711**

Replacing Paris Rhone 100995  
 Servicing A14N4, -9, -10, -13, -14, -19, -22  
 -23, -35, -36, -37, -39, -40, -42, -50, -51, -53  
 -54, -55, -56, -59, -63, -65




**AL 712**

Replacing Paris Rhone 100845  
Servicing A13N




**AL 1247**

Replacing Paris Rhone 590566  
Servicing A14N73, -75



**AL 1228**

Replacing Paris Rhone 592942, 2519621,  
Servicing A11VI11, -23, -24, -25  
A13VI46, -49  
Alternator w/internal fan




**AL 1258**

Replacing 592946, 2519836  
Servicing A11VI10, -16, -17, -18,  
A13VI30, -48




**AL 1230**

Replacing Paris Rhone 592944  
Servicing A13VI11, -14, -16, -17, 20, -21,  
-23, -25, -32, -34, -35, -45, -47




**AL 90**

Replacing Bosch 2124 330 006  
 Servicing 0120 600 515,  
 -519, -521, -522, -527, -530, -531, -534, -540  
 -541, -542, -547, -556, -558, -560, -565, -566  
 -567, -570, -571, -574, -580, -581




**AL 111**

Replacing Bosch 1194 336 53  
 Servicing 0120 450 019, -020, -022, -023,  
 -024, -025, -026, -027, -028, -029, Chrysler




**AL 95**

Replacing Fiat /Marelli 748 775 51  
 Servicing 4376714, 4382200, 4383251,  
 633 005 15, 633 050 00, 633 053 00




**AL 93**

Replacing Bosch 1194 336 035  
 Servicing 0120 400 944, 945  
 Chrysler, Dodge, Plymouth




**AL 1026**

Replacing Bosch 1194 336 010  
 Servicing 0120 300 540, -551, -559




**AL 99**

Replacing Fiat /Marelli 748 766 41  
 Servicing 4379899




**AL 94**

Replacing Bosch 1194 336 038  
 Servicing 0120 450 012, -014, -016, -017




**AL 100**

Replacing Fiat /Marelli 748 775 51  
 Servicing 4152101, 4152510, 4152612,  
 4166213, 4174625, 4176178, 4178618,  
 4180304, 4264156, 633 040 02,  
 633 044 00, -01



**AL 98**

Replacing Lucas 54203529  
Servicing A115, A133  
W/o brushes



**AL 202**

Replacing Mando Melroe  
Servicing AR 150BA




**AL 912**

Replacing Bosch 1124 304 007  
 O.D. 32 mm, Shaft 17 mm,  
 Servicing 0120400...  
 0120489...



**AL 1204**

Replacing Bosch 1124 304 018  
 Servicing 0120 689...  
 O.D. 32.7 mm, Shaft 20 mm,




**AL 904**

Replacing Fiat / Marelli  
 Servicing 633054.. 633071..  
 633074.. O.D. 28 mm.




**AL 922**

Replacing Bosch 1124 303 001  
 O.D. 28 mm, Shaft 17 mm,  
 Servicing 0120300... 0120339...  
 0120469... 0120489...




**AL 910**

Replacing Fiat / Marelli  
 Servicing 633030.. 633040..  
 633048.. O.D. 32 mm.




**AL 923**

Replacing Bosch  
 Servicing O.D. 30 mm.  
 0120339...




**AL 924**

Replacing Ducellier  
 Servicing 516001, 02  
 O.D. 30mm Shaft 17 mm.




**AL 964**

Replacing Fiat / Marelli  
 Servicing 633202... 633212... 633216...  
 Internal Fan Alternators






**AL 984**

Replacing Bosch  
 Servicing 0120 465..., 485  
 O.D. 14 mm,  
 Alternators w/internal fan



**AL 973**

Replacing Fiat/Marelli  
 Servicing 633210...  
 O.D. 28 mm.






**AL 123**

Replacing Lucas / Marelli  
**Servicing:**

A115i, A127i Alternators  
 63320000, 03, 04, 27, 38  
 63321200, 04, 05, 33, 34  
 63321246, 53, 99  
 63321313, 32  
 63321406, 19

FIAT: Brava, Bravo, Marea, Palio, Siena,  
 Weekend, Punto, 126 Bis, Tempra, Tipo,  
 Uno, Fiorino


RENAULT: R5/R9/R11/R19/R21  
 Clio  
 ALFA ROMEO, LANCIA, FORD,  
 AUTOBIANCHI



**AL 1377**


Replacing Lucas / Marelli  
**Servicing:**

Special product for Rebuilders




**AL 153**

Replacing Lucas UAB 101  
 Servicing A115, A133



**AL 908**


Replacing Lucas 54217372, UAB104  
 Servicing ACR  
 Stalled type, w/clip



**AL 939**

Replacing Lucas  
 Servicing 0A127, 24145, 24156, 24157,  
 24158, 24161, 24169, 24198, 24199, 24200,  
 24203, 24206, 24207, 24208





**AL 940**

Replacing Leece Neville 57462  
 Servicing 65/130 Amp.  
 Alternators




**AL 1251**

Replacing Nippondenso  
 Servicing Same AL 925  
 but with 2 Leaders




**AL 938**

Replacing Motorola European 512-055  
 O.D. 26 mm, Shaft 13.3 mm,  
 Servicing 9AR 2672, 2990




**AL 930**

Replacing Mando Melroe  
 Servicing AR 150BA




**AL 1173**

Replacing Mitsubishi  
 O.D. 46 mm, Shaft 25.60 mm,  
 L 30.50




**AL 944**

Replacing Motorola European 512-004  
 O.O. 32 mm, Shaft 17 mm,  
 Servicing VW



**AL 1174**

Replacing Hitachi  
 O.D. 35 mm, Shaft 17 mm,  
 L 27.80




**AL 945**

Replacing 512-003  
 O.O. 32 mm, Shaft 19 mm,  
 Servicing 9AR 2500 K




**AL 925**

Replacing Nippondenso  
 Servicing Internal Fan  
 Alternators




**AL 909**

Replacing Paris Rhone  
 Servicing A13N., A14N.,  
 O.D. 30 mm, Shaft 17 mm,




**AL 950**

Replacing Paris Rhone  
 Servicing A13N.. A14N..  
 O.D. 30 mm, Shaft 17 mm.




**AL 1344**

Replacing Paris Rhone  
 Servicing A13N.. A14N..  
 Insulator for slipring 1 mm.




**AL 928**

Replacing Paris Rhone  
 Servicing A13N., A14N.,  
 O.D. 30 mm, Shaft 15 mm,



**AL 972**

Replacing Paris Rhone 2523992  
 Servicing A13N1M, -35M, -147M, -148M,  
 -149M  
 O.D. 29.5 mm, Shaft 17,




**AL 1345**

Replacing Paris Rhone  
 Servicing A13N.. A14N..  
 Insulator for slipring 0.50 mm.




**AL 929**

Replacing Paris Rhone 34100328  
 Servicing A13 M11  
 O.D. 36 mm, Shaft 17 mm,




**AL 1033**

Replacing Paris Rhone / Valeo  
 Servicing A11Vi..., A13Vi...  
 O.D. 14.9 mm, Shaft 6.6 / 8.85 mm L 48.3 mm




**AL 941**

Replacing Paris Rhone 49100327  
 Servicing A11R1, A11M6  
 O.D. 30 mm, Shaft 15 mm.




**AL 942**

Replacing Sev Marchall  
 Servicing 71665002,  
 O.D. 34.5 mm.




**AL 742**

Replacing Bosch 1127 320 547, -550, -571, -973,  
 Servicing 0120 689 503, -504, -505, -506, -507, -508, -510, -511, -512, -513, -514, -515 -516, -517, -518, -520, -521, -522  
 W/terminal W  
 140 Amp.




**AL 921**

Replacing Bosch 1125715489  
 Servicing 0120 400 600, -605, -611, -620, -629, -631, -632, -633, -634, -643, -644, -650, -665, -702, -708, -714, -716, -717, -721, -725, -726, -752, -787, -793, -794, -848, -895




**AL 765**

Replacing Fiat/Marelli 4474546, 749 990 91  
 Servicing A124, 4306041, 4475303, 633 010 00, 633 033 80, 633 041 00, 633 048 00




**AL 753**

Replacing Bosch 1127 011 095  
 Servicing 0120 489 728, -730, -827, -886, -944




**AL 1084**

Replacing Bosch 1127 320 603  
 Servicing 0120 469 549  
 634, 691, 890  
 (11 Diodes)




**AL 1047**

Replacing Fiat/Marelli RDD15, 636 215 01, -03  
 Servicing AA125R, 633 210 00, -01, -03, -04, -05, -06, -07, -08, -09, -10, -11, -13, -41, -58 -60, -61, -67, -80, -95, 633 211 03




**AL 1063**

Replacing Bosch 1127 320 390  
 Servicing 0120 469 522, -523, -526, -540, -749, -798  
 90Amp. 17 diodes




**AL 1510**

Replacing Bosch 1127 320 397, -503  
 Servicing 0122 469 001, -002, -003, -004, -005




**AL 1085**

Replacing Mando Melroe  
Servicing AR150-AA, -BA, -CA, -CC  
Kubota, Bobcat




**AL 1048**

Replacing Sev 702 50003, -50403,  
Servicing 702 20402, -25002, -25102,  
-29002, -29102, -29402, -29502, -29602,  
-29702, -30002, -30102, 30202,  
-30303, -30402, -30502




**AL 915**

Replacing 1121 099 007  
 Servicing 0120 400 600, -605, -611, -620,  
 -629, -631, -632, -633, -634, -643, -644, -650  
 -665, -702, -708, -714, -716, -717, -721, -725,  
 -726, -752, -787, -793, -794, -848, -895




**AL 1008**

Replacing Fiat/Marelli 74961091  
 Servicing 63304100  
 63304800




**AL 916**

Replacing Paris Rhone 100721  
 Servicing A12R25, -33, -34, -44, -52, -53




**AL 955**

Replacing Ducellier 669303  
 Servicing 514010, 516055




**AL 1537**

Replacing Fiat / Marelli 74961091  
 Servicing 63321011,  
 7565265




**AL 917**

Replacing Paris Rhone 92425  
 Servicing A11R4, A12R9, -12,  
 -16, -17, -23, -27, -28, -48, -59




**AL 999**

Replacing Fiat/Marelli 74878691  
 Servicing 633210...  
 633211...




**AL 926**

Replacing Motorola MO1-120, 128  
 Servicing 043903023A



**AL 918**


Replacing Paris Rhone 97207  
 Servicing A11R3, -56



**AL 927**

Replacing 95106

Servicing A13R83, -84, -85, -86, -87, -88,  
-89, -90, -98, -117, -121, -124, -127, -129,  
-131, -133, -134, -140, -143, -169, -170,  
-173, -175, -176, -179, -183, -184, -187, -219,  
-223, -261, -265




**AL 932**

Replacing Paris Rhone 99520

Servicing A14R35, -41



**AL 601**  
 Replacing Bosch  
 Servicing Rectifier  
 Mounting stud B+Terminal  
 M8x51.5 mm




**AL 646**  
 Replacing Bosch  
 Servicing Part of  
 rectifier 1127 320 547  
 (AL 1162)

**AL 1183**  
 Replacing Bosch 1123 433 005  
 Servicing 0120 689 503, -504, -505, -506,  
 -507, -508, -510, -511, -512, -513, -514, -515  
 -516, -517, -518, -520, -521, -522  
 Screw for Rectifier




**AL 602**  
 Replacing Bosch  
 Servicing Rectifier  
 Mounting stud B+ terminal  
 M8 x 48 mm




**AL 1162**  
 Replacing Bosch 1127 011 083  
 Servicing 0120 689 511, -513, -515, -516,,  
 -517, -518, -520, -522, -523, -526, -527,  
 -528, -530, -531, -533, -534, -535, -538  
 B+, B- and D+ insulator  
 Terminal Kit



**AL 960**  
 Replacing Bosch  
 Servicing Insulation Kit  
 for 1127 320 545, -651,-677




**AL 649**  
 Replacing Bosch  
 Servicing Rectifier  
 Mounting Stud for  
 1127 320 316, -345, -569



**AL 655**  
 Replacing Bosch 1121 015 011  
 Servicing 0120 689 502, -503, -504, -505  
 -506, -507, -508, -510, -511, -512, -513, -514,  
 -515, -516, -517, -518, -520, -521  
 Gasket for rectifier



**AL 1199**  
 Replacing Bosch  
 Servicing B+Terminal  
 Stud for 127 320 651,  
 -677, -712, -735, -914 Rectifiers




**AL 1268**

Replacing Bosch 1120 524 005  
 Servicing Rectifier  
 Protective cap for  
 0120689... Alternators



**AL 600**

Replacing Fiat/Marelli  
 Servicing A125R  
 Screw for rectifiers part of  
 636 215 01




**AL 952**

Replacing Hitachi L190-1350, 23163-V4360  
 Servicing LR170-721B, LR190-702C,  
 -704B, -708C, -711  
 Disc




**AL 1397**

Replacing Bosch  
 Servicing Rectifier mounting kit  
 M4 x 44 mm



**AL 112**

Replacing Fiat/Marelli  
 Servicing Positive  
 output stud for  
 633041... 633048...




**AL 970**

Replacing Hitachi L170-4350  
 Servicing LR165-704B  
 Disc



**AL 1398**

Replacing Bosch  
 Servicing Rectifier mounting kit  
 M5 x 45 mm




**AL 115**

Replacing Fiat/Marelli  
 Servicing Rectifier  
 Bridge fixing brackets  
 633041... 633048...



**AL 1399**


Replacing Bosch  
 Servicing Rectifier mounting stud  
 M8 x 48 mm.  
 B + Terminal



**AL 632**


Replacing Fiat/Marelli  
 Servicing Rectifier  
 plug for 63321501 Rectifiers






**AL 48**

Replacing Bosch 1121 038 018  
Servicing 0120 469...  
Bearing retainer plate



**AL 647**

Replacing Bosch 1121 136 000  
Servicing 0120 469...  
Bearing Plate



**AL 1202**

Replacing Bosch 1120 591 102,-116  
Servicing 0120 335 006,-007,-011,-012  
Bearing Cap




**AL 189**

Replacing Bosch 1120 591 082  
Servicing 0120 469...  
6201 Bearing Cap S.R.E.




**AL 936**

Replacing Bosch 1120 591 075  
Servicing 6201  
0120 468 001,-007,-017,-019,-020  
Bearing Cap S.R.E.




**AL 9358**

Replacing Bosch FOOM 146 900  
Servicing 0124 215 001,-002,-003,-004,  
-005, 0124 220 002, 0124 225 001,-002,  
Bearing Cap S.R.E. for 6003




**AL 587**

Replacing Bosch 1120 591 076  
Servicing 0120 485 005,-006,-007,-008,  
-026,-039,-044,-048  
Alternator w/Internal fan




**AL 997**

Replacing Bosch 2120 516 011  
Servicing 0120 600 515,-525,-544,-562,  
-563,-565,-567,-570,-571,-574,-579  
Bearing Plate




**AL 1372**

Replacing Bosch 1121 038 016  
Servicing 0120 468 028,-054,-055,-136,-137  
Bearing Plate




**AL 588**

Replacing Bosch 1120 591 060  
Servicing 62201  
Bearing Cap




**AL 998**

Replacing Bosch 1120 033 009  
Servicing 0120 689 520,-522,-523  
Bearing Plate




**AL 1612**

Replacing European Delco  
Servicing Alternator Bearing tolerance ring  
37 x 35 x 11.5 mm




**AL 593**

Replacing Bosch  
 Servicing Bearing Cap  
 over size only for rebuilders




**AL 1559**

Replacing Bosch 1121 038 020  
 Servicing Bearing retainer




**AL 1243**

Replacing Lucas & Marelli  
 Servicing A127IR  
 Alternators  
 54022543, 54022459




**AL 1366**

Replacing Bosch 1121 038 500  
 Servicing 0120 469...  
 Bearing retainer plate




**AL 260**

Replacing European Delco  
 Servicing 1101551  
 Bearing Cap



**AL 1244**

Replacing Lucas & Marelli  
 Servicing A115i Alternators  
 63320279, 63320280  
 63321238, 63321244




**AL 1374**

Replacing Bosch 1121 038 015  
 Servicing 0120 465...  
 Bearing retainer plate




**AL 183**

Replacing Lucas 542 193 10  
 Servicing ACR 15-16  
 Type Alternators  
 Bearing 6302



**AL 185**

Replacing Fiat/Marelli  
 Servicing 633031...  
 Bearing Plate Shaft Hole Ø15



**AL 1379**

Replacing Bosch  
 Servicing Bearing plate




**AL 184**

Replacing Lucas 54219310  
 Servicing ACR 17-18  
 Type Alternators  
 Bearing 6202



**AL 193**

Replacing Fiat/Marelli  
 Servicing 633040...  
 Bearing Plate Shaft Ø17




**AL 1187**

Replacing Fiat / Marelli  
 Servicing 633200...  
 633210...Alternators  
 Bearing Plate




**AL 154**

Replacing Paris Rhone 105299  
 Servicing A14N..  
 6201 bearing cap S.R.E.



**AL 590**

Replacing Paris Rhone  
 Servicing Bearing Cap A13VI  
 Alternators w/ internal fan




**AL 1242**

Replacing Fiat / Marelli  
 Servicing 633200...  
 633210...Alternators  
 Bearing Plate




**AL 155**

Replacing Paris Rhone 104809, 590629  
 Servicing A13N  
 6200 bearing cap S.R.E.




**AL 591**

Replacing Paris Rhone  
 Servicing A11, 13VI  
 6201 Bearing Cap  
 Alternators w/ internal fan




**AL 188**

Replacing Paris Rhone 77973  
 Servicing A14R  
 6201 bearing cap S.R.E.



**AL 592**


Replacing Paris Rhone  
 Servicing A14  
 Bearing Cap



**AL 595**


Replacing Lada 0094.3701302  
 Servicing 2112-3701010, 9402, 3701  
 Lada Samara  
 Bearing Cap

*ALDEA  
Vobis*




**AL 589**

Replacing Paris Rhone  
 Servicing A13VI..  
 6202 bearing cap



**AL 931**


Replacing Paris Rhone  
 Servicing 294..  
 6200 bearing cap



**AL 1358**


Replacing Paris Rhone  
 Servicing Bearing retainer plate A13 VI  
 (41 mm)

**Regulator Parts**




**AL 203**

Replacing Bosch 1121015003  
 Servicing Gasket for regulator  
 1197 336 010




**AL 1395**

Replacing Bosch 1121 015 015  
 Servicing 0120 468 054, 0120 469 549,  
 -634, -673, -797, 0120 484 011  
 Gasket for regulators




**AL 1361**

Replacing Paris Rhone  
 Servicing Bearing retainer plate A 13 VI  
 (44 mm)



**AL 1383**

Replacing Bosch  
 Servicing 0120468..., 0120469...,  
 Gasket for regulator



**AL 1555**


Replacing Lucas  
 Servicing Bearing plate



**AL 1388**

Replacing Bosch 1190 591 104  
 Gasket for regulators 1197 311 032, -033,  
 -044, -045, -310, -313, -314, -323,  
 9191 339 310


75/90 Amp



**AL 70**

Replacing Bosch  
 Servicing B+ and D+ insulator  
 120 489 362, -364, -365, -369, -370  
 BMW, FORD


75/90 Amp



**AL 89**

Replacing Bosch  
 Servicing B+ insulator  
 0120469...  
 AUDI, BMW


80 Amp



**AL 124**

Replacing Bosch  
 Servicing B+ insulator  
 0120 489...  
 MERCEDES BENZ


75/90 Amp



**AL 71**

Replacing Bosch  
 Servicing B+ and D+ insulator  
 0120 469 661, 662  
 BMW, FORD


90 Amp



**AL 96**

Replacing Bosch  
 Servicing B+ insulator  
 0120450...  
 CHRYSLER


75/90 Amp



**AL 159**

Replacing Bosch  
 Servicing B+ insulator  
 0120450... 0120469...  
 AUDI - VW


75/90 Amp



**AL 87**

Replacing Bosch  
 Servicing B+ and D+ insulator  
 0120 468... 0120469...  
 0120 489...


75/90 Amp



**AL 101**

Replacing Bosch  
 Servicing B+ and D+ insulator  
 0120 468...  
 PORSCHE


80/90 Amp



**AL 163**

Replacing Bosch  
 Servicing B+ and D+ insulator  
 0120 469...  
 BMW


80/90 Amp



**AL 164**


Replacing Bosch  
 Servicing B+ and D+ insulator  
 0120 469...  
 BMW

90/140 Amp



**AL 1203**


Replacing Bosch 1120 591 109  
 Servicing 0120 465 031, 0120 485 048  
 BMW



**AL 97**


Replacing European Delco 3493057  
 Servicing 3472104, -105, -106, -112, -119  
 -120, -121, -134, -135, -136, -137, -139  
 insulator

90 Amp



**AL 169**

Replacing Bosch  
 Servicing B+ insulator  
 0120 450... CHRYSLER



**AL 258**


Replacing European Delco  
 Servicing 1101551  
 insulator for B+ and D+

45/65 Amp




**AL 172**

Replacing 1127 011 050  
 Servicing B+ insulator  
 0120 489..  
 BMW




**AL 127**

Replacing Fiat/Marelli 749 903 90  
 Servicing 633 036..., 633 037...,  
 633 040...,  
 Connection




**AL 12**

Replacing Hitachi  
 Servicing Internal Fan  
 Alternators Bore 6 mm




**AL 11**

Replacing Mitsubishi  
 Servicing Internal Fan  
 Alternators Bore 6 mm




**AL 54/A**

Replacing Mitsubishi  
 Servicing I.C. alternators w/ internal fan  
 insulator




**AL 13**

Replacing Hitachi  
 Servicing Internal Fan  
 Alternators Bore 6 mm




**AL 18**

Replacing Mitsubishi  
 Servicing Internal Fan  
 Alternators



**AL 54/B**

Replacing Mitsubishi  
 Servicing I.C. alternators w/ internal fan  
 Cover for Slip ring




**AL 19**

Replacing Mitsubishi  
 Servicing Internal Fan  
 Alternators




**AL 55**

Replacing Mitsubishi  
 Servicing Internal Fan  
 Alternators repair plug




**AL 4**

Replacing Nippondenso 21605-2290  
Servicing Internal Fan  
battery terminal  
Chrysler



**AL 61**

Replacing Nippondenso 021605-1150  
Servicing I.C. alternators w/internal fan  
M6 x 25 mm  
insulator for rectifier output terminal




**AL 88**

Replacing Nippondenso  
Servicing internal fan  
alternators battery terminal  
insulator Chrysler




**AL 10**

Replacing Nippondenso  
Servicing Rectifier  
terminal insulator  
8.3 mm Bore




**AL 69**

Replacing Nippondenso  
Servicing External Fan  
Alternator insulator for rectifier




**AL 204**

Replacing Nippondenso  
Servicing internal fan Alternators  
75/90/120 Amp. Terminal Block



**AL 60**


Replacing Nippondenso 021605-1850  
Servicing insulator for rectifier



**AL 74**


Replacing Nippondenso 021605-0710  
Servicing 021000-7971, -7990, -8011,  
-8021, -8231, -8311, -8330, 100211-0142,  
-0322, -0581, -0630, -0731, -0761, -0870  
5 mm bore  
Insulator for rectifier






**AL 25**

Replacing Lucas  
Servicing A127, 24257, 24271, 24288  
Terminal block 55/70 Amp.



**AL 259**

Replacing Lucas  
Servicing A127 24188  
24230, 24264  
Used w/terminal/plug AL 965




**AL 965**

Replacing Lucas 60601042  
Servicing A127, 24188  
Terminal plug block with leader




**AL 46**

Replacing Lucas  
Servicing A127, 24217, 24334, 24404  
Terminal insulator




**AL 957**

Replacing Lucas  
Servicing A127  
24293, 24316, 24374, 24396, 24406  
540 223 73 Terminal Block




**AL 968**

Replacing Lucas 542 085 58  
Servicing A127 24188  
24230, 24264  
Terminal plug block with AL 259




**AL 47**

Replacing Lucas  
Servicing A127  
24216, 24220, 24221, 24223, 24257, 24295,  
24348, 24350, 24351, 24352, 24382, 24384,  
24385, 24392, 24403, 24414, 24415,  
54022305, - 307, -450, -559  
D+ Insulator




**AL 961**

Replacing Lucas 54208486  
Servicing A127, 54022394, -396, -425,  
-429, -495, -547  
Insulator B+, D+ (Cover)



**AL 975**

Replacing Lucas  
Servicing A127, Rectifier  
Bridge fixing brackets




**AL 1170**

Replacing Lucas  
Servicing A127, B+  
Insulator kit



**AL 5472**

Replacing Paris Rhone  
Servicing  
6 x 15.1 x 16.1 mm  
B+ Insulator




**AL 1237**

Replacing Lucas  
Servicing A127, 24295, 24384, 24385,  
24414, 24415  
Terminal Block




**AL 5473**

Replacing Paris Rhone  
Servicing  
5 x 13.25 x 5.6 mm  
D+, W Insulator



**AL 35**

Replacing Bosch  
Servicing Bushing for S.R.E.  
19D x 9d x 19h




**AL 41**

Replacing Bosch  
Servicing Bushing for D.E.  
15.5D x 10.2d x 14h




**AL 83**

Replacing Bosch 1120 323 000  
Servicing BMW  
Mounting bushing  
Rubber. Long




**AL 37**

Replacing Bosch  
Servicing Bushing for D.E.  
15.5D x 8d x 13.2h




**AL 42**

Replacing Bosch  
Servicing Bushing for D.E.  
146.5D x 10.2d x 13h




**AL 84**

Replacing Bosch  
Servicing BMW 85-90 Amp. alternators  
Thick ear, 56 mm  
Mounting bushing kit




**AL 39**

Replacing Bosch  
Servicing Bushing for D.E.  
14D x 10d x 12.5h




**AL 66**

Replacing Bosch  
Servicing Bushing for D.E.  
16.5D x 10.2d x 13h



**AL 85**

Replacing Bosch  
Servicing 0120 469 538, -539, -593,  
-594, -595, -617, -618, -619  
BMW 45, 55, 65 Amp. alternators  
Thin ear, 25 mm.  
Mounting bushing kit




**AL 40**

Replacing Bosch  
Servicing Bushing for D.E.  
14D x 8d x 12.5h




**AL 82**

Replacing Bosch 1120 321 000  
Servicing BMW  
Mounting bushing  
Rubber. Short




**AL 86**

Replacing Bosch  
Servicing 0120 489 036, -038, -039, -045,  
-046, -533, -534, -537, -538, -543, -544  
BMW 45, 55, 65 Amp. alternators  
Thick ear, 51 mm  
Mounting bushing kit




**AL 176**

Replacing Bosch  
Servicing 0120 489 030,-031,-040,-717,-718  
BMW 65 Amp. alternators  
56 mm Thick ear




**AL 1254**

Replacing European Delco  
Servicing 3472170, 171  
Bushing for S.R.E.



**AL 78**

Replacing Fiat / Marelli  
Servicing Bushing for S.R.E.  
21D x 12.2d x 25h




**AL 633**

Replacing Bosch  
Servicing Bushing for D.E.  
12.4D x 19d x 18h




**AL 1255**

Replacing European Delco  
Servicing 3472170,-171  
Bushing for S.R.E.



**AL 131**


Replacing Fiat / Lada  
Servicing Bushing Kit  
for S.R.E. 633031 ...,633041...,633048...



(N)


**AL 1622**

Replacing Bosch 1120 300 041,-508  
Mounting Bushing, S.R.E.




**AL 205**

Replacing Ducellier  
Servicing 7549, 7550A, 7586, 7596, 7597,  
513008, 515094, 516094, 516007, 516038  
Bracket mounting bushing kit



**AL 629**

Replacing Fiat / Lada  
Servicing Mounting bushing rubber  
used AL 131




**AL 206**

Replacing Ducellier  
Servicing 7593, 516012, 515012, 516013  
Bracket mounting bushing kit




**AL 65**

Replacing Lucas  
Servicing Bushing for S.R.E.  
ACR & A127  
12.4D x 9d x 18h




**AL 43**

Replacing Mitsubishi  
 Servicing Bushing for S.R.E.  
 15D x 10.5d x 20h




**AL 265**

Replacing Paris Rhone 102035  
 Servicing A14R45  
 Mounting bracket




**AL 1248**

Replacing Paris Rhone  
 Servicing Bushing for mounting bracket  
 10.1 x 24.7/16.6 x 16 mm  
 Steel




**AL 38**

Replacing Nippondenso  
 Servicing Bushing for D.E.  
 14D x 10.2d x 13h




**AL 79**

Replacing Paris Rhone  
 Servicing A12R1, -3, -4, -11, A13N13, -29,  
 -49, -65, -81, A13R63, -120, -141, -154, -177,  
 -180, -189, -213, -228, -231  
 Mounting bushing kit




**AL 76**

Replacing Paris Rhone 104539  
 Servicing A14N63, -89, -99, -113, -117  
 Mounting bracket




**AL 81**

Replacing Paris Rhone 300709  
 Servicing A13N1M, -2M  
 Mounting bushing kit




**AL 80**

Replacing Sev  
 Servicing 702 20002, -20502,  
 712 27102, -27902, -30202,  
 Bracket mounting bushing kit




**AL 77**

Replacing Paris Rhone 101113  
 Servicing A13N...  
 Mounting bracket




**AL 650**

Replacing Paris Rhone  
 Servicing A14R3, -17, -27,  
 A14N1, -2, -55, -90, -91  
 Mounting bushing kit (M10 x 12.5 mm)




**AL 175**

Replacing Bosch 1126600500  
 Servicing O.D. 85 mm  
 Bore 17 mm Double




**AL 1332**

Replacing Bosch  
 Servicing O.D. 105 mm Bore 17 mm  
 Single




**AL 132**

Replacing Fiat/Marelli  
 Servicing AA124  
 12.7 Belt Bore 15 mm  
 Single




**AL 645**

Replacing Bosch 2126600030  
 Servicing 0120600562, 0120689503  
 O.D. 107 mm Bore 30 mm




**AL 1333**

Replacing Bosch  
 Servicing O.D. 105 mm  
 Bore 17 mm Double




**AL 149**

Replacing Lucas 54202390  
 Servicing ACR  
 9.5 Belt Single




**AL 985**

Replacing Bosch  
 Servicing O.D. 85 mm  
 Bore 17 mm 12.5 Belt




**AL 1530**

Replacing Bosch  
 Servicing Serpentine pulley  
 10 Grooves for 0120689...  
 alternators Euroclass (O.D. 90 mm)




**AL 1252**

Replacing Lucas 54206925  
 Servicing 54022415  
 A127 Alternators




**AL 987**

Replacing Bosch  
 Servicing O.D. 106 mm  
 Bore 17 mm 12.5 Belt



**AL 126**

Replacing Fiat/Marelli 74997110  
 Servicing AA124  
 9.5 Belt Bore 17 mm  
 Single




**AL 1236**

Replacing Paris Rhone 101054  
 Servicing A14N3T  
 O.D. 72 mm Bore 17 mm  
 Double 9.5 Belt



**AL 20**

Replacing Bosch 1126 610 065  
 Servicing 0120 450 012,-016,  
 0120 469 513,-517,-531,-549,-570,-572,  
 -574,-576,-578,-593,-595,-618,-619




**AL 1289**

Replacing Bosch  
 Servicing 0120 400 531,-534,-615,-625,  
 -650,-657,-745,-747,-810,-906,-928  
 Anti Rotation




**AL 995**

Replacing Fiat / Marelli 83639410  
 Servicing AA125R  
 633210...  
 Bore 15 mm



**AL 210**

Replacing Bosch  
 Servicing 0120 469...  
 0120 489...




**AL 1364**

Replacing Bosch 1126 610 075  
 Servicing 0120 689 516...  
 Iveco, 100 Amp.  
 (O.D. 177.3 mm)




**AL 996**

Replacing Fiat / Marelli  
 Servicing AA125R  
 633210...  
 Bore 17 mm




**AL 211**

Replacing Bosch 1126 610 052  
 Servicing 0120 623 052, 0120 689 502,  
 -503,-504,-505,-506,-507,-508,-510,-511,  
 -512,-513,-514,-517,-518,-520,-522




**AL 166**

Replacing Bosch & Marelli  
 1126 610 078-74987100  
 Servicing K1 & AA125R  
 Bore 17 mm



**AL 1186**

Replacing Lada / Katek 2101-3701051  
 Servicing 2101...,2105...,2108...,




**AL 994**

Replacing Bosch  
 Servicing 0120 600...




**AL 165**

Replacing Fiat / Marelli 748 771 00  
 Servicing AA124  
 633031... 633032  
 Bore 15 mm




**AL 1549**

Replacing Bosch 1126 610 108  
 Servicing 0120 468 143, 145,  
 6033 GB 3010




**AL 1553**

Replacing Bosch 2126 610 033  
 Servicing 0120389 599, -592, -567, -569,  
 -570, -571, -572, -573, -574, -576, -577  
 O.D. 210 mm Bore 30 mm




**AL 1589**

Servicing Paris Rhone / Valeo  
 A11Vi 91, 2541969  
 Bore 17 mm, 6 grooves




**AL 1499**

Replacing Bosch 1126601025  
 Servicing Mercedes Benz




**AL 1586**

Replacing Bosch 1126 601 524  
 Servicing 0120 485 046, 0123 310 001,  
 -002,-007,-019,-020, 0123 315 001,  
 -002  
 Bore 17 mm, 6 grooves




**AL 1583**

Replacing Paris Rhone / Valeo  
 Servicing A13VI62,-66  
 O.D. 55 mm, Bore 17 mm, 6 grooves




**AL 1655**

Replacing Paris Rhone / Valeo  
 Servicing A13VI72  
 O.D. 60 mm, Bore 17 mm, 6 grooves




**AL 1653**

Replacing Bosch 1126 600 569  
 Servicing 0120 469 746,-853,-855,-884,  
 -897, 0120 488 126,-133,-136, 0120 489 324,  
 -326,-332 (6 grooves)




**AL 1657**

Replacing Paris Rhone / Valeo  
 Servicing Renault Clio, Megane,  
 Kangoo Diesel  
 5 grooves (Aliminium)




**AL 1565**

Replacing Bosch  
 Servicing 0120689...  
 10 grooves (O.D. 104 mm)




**AL 1588**

Replacing European Delco 10475021  
 Servicing CS130D, 10479923,-947  
 Bore 17 mm, 6 grooves



**AL 1664**


Replacing Paris Rhone / Valeo  
 Servicing Renault Clio, Megane,  
 Kangoo Express, Petrol  
 6 grooves (Aliminium)



**AL 1656**

Replacing Delco U.S.A.  
 Servicing 21SI, 22SI  
 O.D. 66 mm, Bore 22 mm, 8 grooves





### AL 75

Replacing Bosch 1123 429 133  
Servicing 0120 400...  
(M5 x 100 mm)




### AL 1329

Replacing Bosch 1123 410 038  
Servicing M6 x 117 mm  
Thru Bolt




### AL 120

Replacing Fiat / Marelli  
Servicing AA125 R  
(M6 x 80 mm)




### AL 654

Replacing Bosch 1123 429 125  
Servicing 0120 689...  
(M6 x 105 mm)




### AL 1532

Replacing Bosch 1123 429 206  
Servicing M5 x 120 mm



### AL 113

Replacing Fiat / Marelli 74967690  
Servicing AA 124  
Thru Bolt




### AL 988

Replacing Bosch 1123 429 102  
Servicing 0120 469...  
(M5 x 110 mm)




### AL 1533

Replacing Bosch 1123 429 203  
Servicing M5 x 130 mm



### AL 1250

Replacing Fiat / Marelli  
Servicing AA 124  
Thru Bolt




### AL 1249

Replacing Bosch  
Servicing 0120 689...  
(M6 x 115mm)




**AL 137**

Replacing Lucas 60600864  
Servicing A127  
(M5 x 105 mm)




**AL 1523**

Replacing Paris Rhone / Valeo  
Servicing M5 x 90 mm




**AL 1382**

Replacing Lucas  
Servicing A133  
(M6x70 mm)




**AL 1524**

Replacing Paris Rhone / Valeo  
Servicing M5 x 96 mm




**AL 1525**

Replacing Paris Rhone / Valeo  
Servicing M5 x 115 mm




**AL 1526**

Replacing Paris Rhone / Valeo  
Servicing M5 x 80 mm




**AL 1520**

Replacing Paris Rhone / Valeo  
 Servicing Alternator B + Terminal  
 with insulator  
 M6 x 49 mm




**AL 1538**

Replacing Paris Rhone / Valeo  
 Servicing Alternator B + Terminal  
 with insulator  
 M6 x 49 mm




**AL 1529**

Replacing Bosch 1120140142  
 Servicing spacer for fan




**AL 1521**

Replacing Paris Rhone / Valeo  
 Servicing Alternator B + Terminal  
 with insulator M5 x 36 mm



**AL 1411**

Replacing  
 Servicing Spacer for pulleys thickness  
 3 mm Aliminium




**AL 1535**

Replacing Bosch 1120202008  
 Servicing spacer




**AL 1522**

Replacing Paris Rhone / Valeo  
 Servicing Alternator B + Terminal  
 with insulator M5 x 45 mm




**AL 1412**

Replacing  
 Servicing Spacer for pulleys thickness  
 1 mm sheet Iron




**AL 1578**

Replacing Bosch 1120 202 038  
 Servicing 0120 468 028,-054,-055,-136,-147




**AL 1536**

Replacing Paris Rhone / Valeo  
 Servicing Alternator B + Terminal  
 with insulator M5 x 36 mm



**AL 1413**

Replacing  
 Servicing Spacer for pulleys thickness  
 2 mm sheet iron




**AL 597**

Replacing Bosch 2912 212 207  
 Servicing 0120 689...  
 stud for cover



**AL 656**

Replacing Bosch  
 Servicing Rotor Shaft Key  
 for 1124037... 1124037...  
 ( 8 x 8.5 x 22 mm )



**AL 991**

Replacing Bosch  
 Servicing Rotor wire  
 separator for 0120 469...-0120 489... rotors.




**AL 643**

Replacing Bosch 1127 011 064  
 Servicing 0120 689 503, -504, -505, -506  
 -507, -508, -511, -512, -513, -514, -515, -516,  
 -517, -518, -524, -525, -532, -538, -539, -550,  
 Repair Kit



**AL 659**

Replacing Bosch 1120 283 000  
 Servicing 0120 689 502, -503, -504, -505,  
 -506, -507, -508, -510, -511, -512, -513  
 Oil seal S.R.E



**AL 992**

Replacing Bosch  
 Servicing Rotor wire  
 separator for 0120 689... rotors




**AL 644**

Replacing Bosch 1127 011 171  
 Servicing 0120 689 520, -523, -526, -528,  
 -530, -531, -533, -534, -535, -543, -545,  
 -546, -548, -549  
 Repair Kit



**AL 661**

Replacing Bosch 2120 283 000  
 Servicing 0120 600...  
 Oil seal D.E.



**AL 1184**

Replacing Bosch 1127 402 001.  
 Servicing 0120 623 052, 0120 689 503,  
 -504, -505, -506, -507, -508, -511, -512 Oiler



**AL 1221**

Replacing Bosch 1127 011 020  
 Servicing 0120400... 0120450...  
 0120468... 0120484  
 0120488... 0120489



**AL 989**

Replacing Bosch  
 Servicing Rotor shaft key  
 or 1124034... 1124035...  
 ( 4 x 5 x 65 mm )



**AL 1185**

Replacing Bosch 1127 402 000  
 Servicing 0120 623 052, 0120 689 502,  
 -503, -504, -505, -506, -507, -508, -511  
 Oiler




**AL 1164**

Replacing Bosch 1120 200 015  
 Servicing 0120 689...  
 Distance ring




**AL 1182**

Replacing Bosch 2912 452 191  
 Servicing 0120 689...  
 Screw for capasitor.




**AL 1189**

Replacing Bosch  
 Servicing 0120 689...  
 Rotor spacer (105 Amp)  
 O.D. 38 mm, Bore 29.96mm, Th. 12.70 mm




**AL 1165**

Replacing Bosch 2916 600 016  
 Servicing 0120 689...  
 Rotor Retainer




**AL 1163**

Replacing Bosch 1900 910 024  
 Servicing 0120 689...  
 S.R.E. Roller Bearing.




**AL 1393**

Replacing Bosch adaptation  
 Servicing Bearing kit for 0120468, 135, 144  
 Alternators Suitable to 1120 905 097  
 (17 x 62 x 20 mm) Scania, Volvo, Daf, Ford,  
 Iveco, Man, Mercedes Benz



**AL 1166**

Replacing Bosch 1120 114 002  
 Servicing 0120 689...  
 Rotor spacer




**AL 1167**

Replacing Bosch 1900 900 361.  
 Servicing 0120 689...  
 D.E. Roller bearing (95 & 105 Amp)



**AL 1181**

Replacing Bosch 1123 433 007  
 Servicing 0120 689...  
 Screw for regulator.




**AL 1188**

Replacing Bosch 2120 905 000.  
 Servicing 0120 689...  
 D.E. Roller Bearing. (120&140 Amp)




**AL 72**

Replacing Fiat/Marelli 12164011  
Servicing Rotor Shaft  
Nut (14 x 1.5 mm)




**AL 129**

Replacing Fiat/Lada  
Servicing River for  
D.E. Brackets  
( 5 x 21.5 mm )




**AL 1222**

Replacing Lucas  
Servicing A 127  
Rotor Shaft nut




**AL 73**

Replacing Fiat/Marelli 16101511  
Servicing Rotor Shaft  
Nut (10 x 1.25 mm)



**AL 134**

Replacing Fiat/Marelli  
Servicing Rivet for  
D. E. Brackets  
( 5 x 30 mm )



**AL 1280**

Replacing Lucas  
Servicing A 127, 54022415  
Rotor shaft nut




**AL 103**

Replacing Fiat/Marelli 10205810  
Servicing Rotor shaft key  
( 4 x 6.5 x 15 mm )



**AL 1575**

Replacing Bosch 1120 202 505  
Servicing 0123 320 057, 0123 325 500,  
0123 510 094, -096, 0123 512 501, -502,  
0123 515 500, 0123 520 500  
O.D.43,90 mm shaft 17 mm  
Spacer



**AL 1577**

Replacing Bosch 1123314003  
Servicing 0123 325 500, 501  
Nut




**AL 130**

Replacing Fiat/Marelli 10205710  
Servicing Rotor shaft key  
( 3 x 5 x 14.5 mm )




**AL 1576**

Replacing Bosch 1120591513  
Servicing 0123 325 500, 501  
O.D. 55 mm shaft 17 mm



**AL 104**


Replacing Paris Rhone  
Servicing A 13N  
Rotor shaft cap.



(N)

**AL 1604**


Replacing Bosch 1127 011 019  
 Servicing 0120 469 008,-019,-024,-506,  
 -509,-518,-526,-562,-585,-692,-761,  
 -891,-983, 0120 488 208,-232,-271,-289



(N)

**AL 1605**


Replacing Bosch 1127 011 020  
 Servicing 0120 400 635,-644,-648,-652,  
 -665,-680,-693,-707,-708,-709,-714,  
 -717,-723,-725,-743,-747,-755,-761



(N)

**AL 1606**

Replacing Bosch 1127 011 093  
 Servicing 0120 450 012,-014,-016,-017,  
 -020,-022,-023,-024,-025,-026,-027  
 B+ Terminal Kit



(N)

**AL 1607**


Replacing Bosch 1127 011 160  
 Servicing 0120 468 107,-113,-115,-116,  
 -117,-121,-124,-127,-128,-129,-130,  
 -131,-132,-134,-137,-143,-145,-149



(N)

**AL 1608**

Replacing Bosch 1123 502 000  
 Servicing M5 x 32 mm  
 Stud



(N)

**AL 1592**


Replacing Bosch 1123 527 036  
 Servicing 0120 468 143,-145,  
 0120 469 101,-102,-103,-113,-115,-116,  
 0120 488 252,-253,-288  
 M6 x 30 mm Stud



(N)

**AL 1624**


Replacing Bosch 1127 011 143  
 Servicing 0120 469 001,-013,-101,-686,-687,  
 -895,-982, 0120 488 256,-277,-278,-282,-291,  
 0120 489 315,-316, 6033 GB3 008




**AL 1200**  
 Replacing Lucas & Marelli  
 Servicing A127 24188  
 24230 Ford Transit Diesel



**AL 993**  
 Replacing Lucas  
 Servicing A 127  
 Oil Seal for S.R.E.




**AL 1256**  
 Replacing Fiat / Marelli  
 Servicing Oil Seal  
 for S.R.E.




**AL 1400**  
 Replacing Lucas & Marelli  
 Servicing Vacuum Pump Connector  
 M14 / 16 - 1.5



**AL 1401**  
 Replacing Lucas & Marelli 60601039  
 Servicing A 127 w/ vacuum pump  
 32 x 4 mm  
 O-ring




**AL 1402**  
 Replacing Lucas & Marelli  
 Servicing A 127  
 70 x 2 mm  
 O-ring




**AL 594**  
 Replacing Lucas 54215165  
 Servicing C40 R/H, 22700, 22704, 22705,  
 22715, 22721, 22742, 22744, 22747, 22748,  
 22749, 22767, 22775




**AL 598**  
 Replacing Lucas 54213670  
 Servicing C40 22703, 22733, 22735,  
 22780, 22786, 22787, 22788, 22791




**AL 636**  
 Replacing Lucas 54211125  
 Servicing C40 22700, 22704, 22705,  
 22715, 22721, 22742, 22744, 22747,  
 22748, 22749, 22767



**AL 642**  
 Replacing Lucas 54211099  
 Servicing C40 A, 22703, 22733, 22751,  
 22780, 22788




**AL 186**  
 Replacing 229400  
 Servicing C 40  
 Bearing plate kit




**AL 306**  
 Replacing Lucas 54216878  
 Servicing C 40  
 F terminal






Albi Number: AL 1600  
Replacing Bosch 0001416002  
Replacing Delco Remy: 19024010  
**POWER**  
24 Volt 5.4 KW. 9 Teeth




Item	Description	Albi No.	Replacing	Remarks
1	D.E. Bracket	AL 1278	2005 825 218	Without Bearing
2	Drive	AL 1291	2006 382 176	9 teeth
3	Key	AL 1224	1902 300 090	
4	Spring	AL 1279	2004 650 030	} New Our Design Spring & seal
5	Oil Seal	AL 1279	2000 212 000	
6	D.E. Bushing	AL 8962	2000 301 015	
7	Field Coil	AL 486	2004 125 080	
8	C.E. Bushing	AL 8961	2000 301 016	
9	C.E. Bracket	AL 1300	2005 855 298	New Design w/o Terminal
10	Terminal Set	AL 1281	2007 011 060	M10 Terminal
11	Terminal Set	AL 1282	2003 590 004	M12 Terminal
12	Brush Set	BSX 172-173	2007 014 079	
13	Solenoid	AL 1310	0331 101 006	Will be produced from 2002
14	Solenoid	AL 1309	0331 450 001	Will be produced from 2002
15	Gasket	AL 1276	2000 210 014	
16	Cover	AL 891	2000 580 127	
17	Cover Fasten Bolt	AL 1223	2003 527 040	
18	Pole Shoe Screw	AL 1220	2910 551 240	
19	Fixation Nut	AL 1197	2003 315 002	
20	Rod	AL 1286	2003 050 076	
21	Bracket	AL 892	2005 825 077	
22	Washer	AL 1273	2000 105 040	
23	Armature	AL 8112	2004 005 022	
24	Washer Set	AL 1272	2000 102 622	
25	Clutch	AL 1308	2006 401 527	Will be produced from 2002
26	Thru Bolt Set	AL 1198	2003 526 008, 32	(set 4 pices)

**Servicing**

MERCEDES-BENZ, MAN, KAEUBLE - GEMINDER, CLAAS,  
DRÖGMÖLLER



Albi Number: AL 1603  
Replacing Bosch 0001410088  
Replacing Delco Remy: 19024051  
**POWER**  
24 Volt 6.6 KW. 9 Teeth




Item	Description	Albi No.	Replacing	Remarks
1	D.E. Bracket	AL 1278	2005 825 218	Without Bearing
2	Drive	AL 1291	2006 382 176	
3	Key	AL 1224	1902 300 090	New Our Design Spring & seal
4	Spring	AL 1279	2004 650 030	
5	Oil Seal	AL 1279	2000 212 000	
6	D.E. Bushing	AL 8962	2000 301 015	New Design w/o Terminal
7	Field Coil	AL 488	2004 125 036	
8	C.E. Bushing	AL 8961	2000 301 016	New Design w/o Terminal
9	C.E. Bracket	AL 1300	2005 855 298	
10	Terminal Set	AL 1281	2007 011 060	M10 Terminal
11	Terminal Set	AL 1282	2003 590 004	
12	Brush Set	BSX 172-173	2007 014 079	M12 Terminal
13	Solenoid	AL 1310	0331 101 006	
14	Solenoid	AL 1309	0331 450 001	Will be produced from 2002
15	Gasket	AL 1276	2000 210 014	
16	Cover	AL 891	2000 580 127	Will be produced from 2002
17	Cover Fasten Bolt	AL 1223	2003 527 040	
18	Pole Shoe Screw	AL 1220	2910 551 240	Will be produced from 2002
19	Fixation Nut	AL 1197	2003 315 002	
20	Rod	AL 1288	2003 050 075	Will be produced from 2002
21	Bracket	AL 892	2005 825 077	
22	Washer	AL 1273	2000 105 040	Will be produced from 2002
23	Armature	AL 8114	2004 005 025	
24	Washer Set	AL 1272	2000 102 622	(set 4 pices)
25	Clutch	AL 1308	2006 401 527	
26	Thru Bolt Set	AL 1198	2003 526 021, 022	

**Servicing**

MERCEDES-BENZ, MAN, KAELEBLE - GEMINDER, CLAAS, KASSBOHRER  
DRÖGMÖLLER

24 v



**AL 486**


Replacing Bosch 2004125078,80  
Servicing FKB (Short)

0001414001, 002, 003 004, 005, 006, 007,  
008, 009, 010, 011, 013, 014, 015, 016, 017,  
018, 019, 020, 021, 022,

0001415001, 002, 003, 004, 005, 006, 007,  
010, 011, 013, 016, 017,018, 021, 023, 024,  
027,

0001416001, 002, 003, 004, 005, 006, 007,  
008, 009, 010, 011, 012, 013, 014, 015, 016,  
017, 018, 019, 020, 021, 022, 023, 024, 025,  
026, 027, 028, 029, 030, 031, 032, 033, 034,  
035, 036, 037, 038, 039, 040, 042, 043, 044,  
045, 046, 047, 048, 049, 050, 051, 052, 053,  
054, 055, 057, 058, 059, 060, 062, 063, 064,  
066, 068, 070, 071, 074, 076,

24 v




**AL 487**

Replacing Bosch 2004125076,83  
Servicing FKB (Middle)

0001417001, 002, 003, 004, 005, 006, 007,  
008, 009, 010, 011, 012, 013, 014, 015, 016,  
017, 018, 020, 022, 023, 024, 025, 026, 029,  
030, 031, 032, 033, 035, 036, 037, 038, 040,  
041, 042, 043, 044, 045, 046, 047, 048, 049,  
050, 051, 053, 054, 055, 057, 058,

24 v



**AL 488**


Replacing Bosch 2004125036  
Servicing FKB (Long)

0001410015, 016, 017, 019, 021, 022, 024,  
029, 032, 034, 035, 037, 041, 043, 044, 046,  
049, 050, 052, 058, 061, 062, 063, 065, 067,  
069, 073, 075, 077, 078, 081, 083, 086, 087,  
088, 090, 091, 092, 094, 097, 101, 102, 104,  
105, 106, 109, 111, 113, 115, 116, 117, 118,

0001411001, 002, 004, 005, 006, 007, 009,  
010, 012, 013, 014, 015, 016, 017, 018, 019,  
020, 021, 022, 023, 024, 025, 026, 027, 028,  
029, 030, 031, 032, 035,

0001417010, 014, 016, 020, 031, 036, 054,

24 v



**AL 8112**


Replacing Bosch 2004005022  
Servicing FKB (Short)

0001414001, 002, 003 004, 005, 006, 007,  
008, 009, 010, 011, 013, 014, 015, 016, 017,  
018, 019, 020, 021, 022,

0001415001, 002, 003, 004, 005, 006, 007,  
010, 011, 013, 016, 017,018, 021, 022, 023,  
024,027,

0001416001, 002, 003, 004, 005, 006, 007,  
008, 009, 010, 011, 012, 013, 014, 015, 016,  
017, 018, 019, 020, 021, 022, 023, 024, 025,  
026, 027, 028, 029, 030, 031, 032, 033, 034,  
035, 037, 038, 039, 040, 042, 043, 044, 045,  
046, 047, 048, 049, 050, 051, 052, 053, 054,  
055, 057, 058, 059, 060, 061, 062, 063, 064,  
065, 066, 067, 068, 069, 070, 071, 072, 073,  
074, 075, 076, 077, 078

24 v



**AL 8114**


Replacing Bosch 2004005025  
Servicing FKB (Long)

0001410016, 017, 019, 021, 022, 024, 035,  
037, 041, 044, 050, 058, 061, 063, 067, 068,  
069, 073, 075, 077, 078, 086, 087, 088, 090,  
091, 092, 098, 101, 102, 104, 105, 109, 111,  
113, 115, 116, 117, 118,

0001411001, 002, 004, 006, 007, 009, 010,  
012, 013, 014, 015, 016, 018, 019, 020, 022,  
023, 024, 025, 026, 027, 028, 029, 030, 031,  
032, 035, 036,

0001417003, 004, 009, 010, 011, 017, 020,  
031, 032, 033, 036, 054

**Clutches**




**AL 1308**

Replacing Bosch 2006 401 527  
Servicing FKB, 0001 410. . . ,

0001 411 . . .

Will be produced from 2002




**AL 892**

Replacing Bosch 2005 825 077

Servicing FKB  
Bracket


Brush holder use BSX 172-173 brushes



**AL 1296**

Replacing Bosch 2005 855 174  
 Servicing FKB 0001 410..., 0001 411...,  
 0001 413..., 0001 414..., 0001 415...,  
 0001.416..., 0001 417..., 0001 418...,  
 9000 084 019 Terminal 30M10, 31M10  
 without brushes (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1299**

Replacing Bosch 2005 855 378  
 Servicing 0001 411 025, -026, -027,  
 0001 416 038, -043, 062, -063,  
 0001417 005, -006, -007, -066,  
 Terminal 30M12, 31M10  
 with brushes complete (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1302**

Replacing Bosch 2005 855 373  
 Servicing 0001 416 010, 0001 417, 037,  
 Terminal 30M12, 31M10  
 Without brushes, with springs  
 (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1297**

Replacing Bosch 2005 855 378  
 Servicing 0001 411 025, -026, -027,  
 0001 416 038, 062, -063, 0001417005, 066  
 Terminal 30M12, 31M10  
 W/M 12 terminal without brushes (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1300**

Replacing Bosch  
 Servicing FKB, 0001 410..., 0001 411...,  
 0001 413..., 0001 414..., 0001 415...,  
 0001 416..., 0001 417..., 0001 418...,  
 Without terminal & without Brushes (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1303**

Replacing Bosch 2005 855 373  
 Servicing FKB,  
 Terminal 30M12, 31M10  
 Terminal 30 plastic covered  
 (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1298**

Replacing Bosch 2005 855 174  
 Servicing FKB, 0001 410..., 0001 411...,  
 0001 413..., 0001 414..., 0001 415...,  
 0001 416..., 0001 417..., 0001 418...,  
 Terminal 30M10, 31M10  
 with brushes complete (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1301**

Replacing Bosch 2005 855 174  
 Servicing FKB, 0001 410..., 0001 411...,  
 0001 413..., 0001 414..., 0001 415...,  
 0001 416..., 0001 417..., 0001418...,  
 Terminal 30M10, 31M10  
 Insulated return w/M10 terminal (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1304**

Replacing Bosch 2005 855 365  
 Servicing FKB, 0001416..., 0001417...,  
 W/M 10 Terminal. Without brushes  
 Terminal 30M10, 31M10  
 Terminal 30 plastic covered  
 (NEW TYPE)


Brush holder use BSX 172-173 brushes



**AL 1359**

Replacing Bosch 2005 855 378  
 Servicing FKB, 0001 410..., 0001 411...,  
 0001 413..., 0001 414..., 0001 415...,  
 0001 416..., 0001 417..., 0001 418...,  
 Terminal 30 M12 plastic covered  
 Terminal 31M10 (NEW TYPE)


Brush holder use BSX 131 brushes



**AL 1351**

Replacing Bosch 2005 855 199, -378  
 Servicing FKB, 0001 411 026,  
 0001 416 038, -043, -062, -063, -072  
 0001 417 005, -006, -007, -064, -066  
 -073, -074  
 Terminal 30 M12, 31M10


Brush holder use BSX 131 brushes



**AL 1354**

Replacing Bosch  
 Servicing FKB, 0001 410..., 0001 411...,  
 0001 413..., 0001 414..., 0001 415...,  
 0001 416..., 0001 417..., 0001 418...,  
 Without terminal & Brushes, with springs  
 (EARLY TYPE)


Brush holder use BSX 172-173 brushes



**AL 1360**

Replacing Bosch 2005 855 174  
 Servicing FKB  
 Terminal 30 M10 plastic covered  
 Terminal 31M10 (NEW TYPE)  
 without brushes, with springs


Brush holder use BSX 131 brushes



**AL 1352**

Replacing 2005 855 371, -373  
 Servicing FKB, 0001 416 010, -044  
 -045, 0001 417 037, -059  
 Insulated return, terminal 30 M12, 31 M10  
 without brushes, with springs


Brush holder use BSX 131 brushes



**AL 1356**

Replacing 2005 855 165, -166, -325, -365  
 Servicing FKB, 0001 410 015, -017,  
 -029, -032, 034, -035, -043, -044, -046,  
 -052, -058, -061, -62, -063, -065, -067,  
 -073, -081, -086, -088, -090, -094, -098  
 Terminal 30 M10, 31 M10


Brush holder use BSX 131 brushes



**AL 1350**

Replacing 2005 855 165, -166, -325, -365  
 Servicing FKB, 0001 410 015, -017, -029,  
 -032, -034, -035, -043, -044, -046, -052,  
 -058, -061, -062, -063, -065, -067, -073,  
 -081, -086, -088, -090, -094, -098  
 Terminal 30 M10, 31 M10


Brush holder use BSX 131 brushes



**AL 1353**

Replacing 2005 855 199, -378  
 Servicing FKB, 0001 411 026,  
 0001 416 038, -043, -062, -063, -072,  
 0001 417 005, -006, -007, -064, -066,  
 -073, -074  
 Terminal 30 M12, 31 M10


Brush holder use BSX 131 brushes



**AL 1357**

Replacing 2005 855 173, -174  
 Servicing FKB, 0001 410 019, -022,  
 -024, -037, -049, -050, -068, -069, -075,  
 -077, -078, -087, -092, -101, -109  
 0001 411 001, -002, -006, -007, -013  
 Insulated return, terminal 30 M10, 31 M10


Brush Holder use BSX 131 Brushes



**AL 1355**

Replacing Bosch 2005 855 376  
Servicing 0001417065, 069  
Terminal 30M12,  
Terminal 31M12


Brush BSX 134-144



**AL 759**

Replacing Bosch 2005 854 053 (12 v)  
Servicing 001 358 202, 0001 359 002,  
-003, -008, -010, -014, -016, -020, -023,  
-025, -027, -030, -031, -032, -033, -035,  
-041, -045, -051, -053, -054, -055, -057,  
Without springs & Brushes.


BNG 4 PS/12-24 V 1 Hole



**AL 815**

Replacing Bosch 2005 855 014,126  
Servicing 0001402011, 037, 040, 044, 053,  
054, 055, 058, 059, 061, 083,


Brush BSX 135-145



**AL 767**

Replacing Bosch 2005 854 052 (24 v)  
Servicing 0001 359 062, -065, -100,  
0001 360 002, -004, -005, -007, -008, -012,  
-018, -020, -026, -029, -030, -032, -033, -034,  
-035, -036, -037, -038, -040, -041  
Without springs & Brushes.


Brush BSX 134-144



**AL 1238**

Replacing Bosch 2005 854 088 (12 v)  
Servicing 0001 365 004, -005, -006, -007,  
-008,  
Without springs & Brushes


Brush BSX 135-145



**AL 1239**


Replacing Bosch 2005854 087 (24 v)  
Servicing 0001 364 100, -101, -102, -103,  
-104, -105, -108, -200, -203, -206,  
Without spring & Brushes.

BNG 4 PS/12-24 V 2 Hole



**AL 754**


Replacing Bosch 2005 854 094  
Servicing 0001 362 037, -040, -041, -042,  
-043, -045, -049, -050, -051, -052, -053, -057,  
-058, -059, -060, -061, -063, -064, -071, -075,  
-079, -081, -084, -085, -086, -093, -095, -097,  
-104, -302, -303, -304,



**AL 787**


Replacing Bosch 2005 855 040, 083  
Servicing 0001401005, 011, 028, 044, 050,  
052, 067, 069  
0001402001, 002, 050, 051

Brush BSX 131




**AL 1363**

Replacing Bosch 2005 855 296  
Servicing 0001417040, Plastic Insulated  
terminal set FKB grounded waterproof  
Terminal 30 M12  
Mercedes Benz




**AL 1551**

Replacing Bosch 6033 ADO 180  
 Servicing 0001231002, 016  
 Iveco, Mercedes Atego, Citaro, Vario




**AL 1560**

Replacing Bosch 2005854173  
 Servicing 0001372001, 006




**AL 1566**

Replacing Bosch 2005 854 181  
 Servicing 0001 371 006,- 008  
 Scania




**AL 1556**

Replacing Bosch 6033 ADO 175  
 Servicing 0001 230 006, 014  
 Magirus Deutz, KHD




**AL 1561**

Replacing Bosch 2005854163  
 Servicing 0001369007, 019, 025, 200, 201  
 Cummins, New Holland



**AL 1569**


Replacing Bosch 6033 ADO 056  
 Servicing 0001 223.002,-003,-004,-005,  
 -007,-008,-016  
 Iveco, Mercedes, Renault



(N)

**AL 1567**


Replacing Bosch 2000 034 000,-001  
 Servicing 0001 370 001,-002,-003,-004,-008,  
 -009,-010,-012,-013,-014,-015,-016,-017,  
 9000 453 029,-064,-065



(N)

**AL 1584**

Replacing Bosch 2005 854 176  
 Servicing 0001 370 001,-002  
 0001 371 001, 9000 453 029,-064,-065,-066,  
 -067,-068



(N)


**AL 1636**

Replacing Bosch 6033 ADO 325  
 Servicing 0001 223 013  
 Citroen, Fiat, Peugeot

(N)

**AL 1637**


Replacing Bosch 6033 ADO 141  
 Servicing 0001 231 007,-019,-023  
 Under Development



**AL 596**

Replacing Fiat/Marelli 721 639 06  
 Servicing MT 68RA, MT 71 RB,  
 MT 71 FB, 632 168 52,632 171 56, -63


Brush MASX25-26



**AL 758**

Replacing Fiat/Marelli 723 831 01  
 Servicing MT 71,632 171 04, -05, -06, -07,  
 -08, -10, -12, -16, -17, -18, -19, -20, -21, -25,  
 -38, -47, -73, -82  
 Without spring & Brushes


Brush MASX25-26



**AL 1326**


Replacing Fiat/Marelli 723 831 01  
 Servicing MT 71,632 171 04, -05, -06, -07,  
 -08, -10, -12, -16, -17, -18, -19, -20, -21, -25,  
 -38, -47, -73, -82  
 With Brushes & Springs

Brush JSX 16



**AL 727**


Replacing Fiat/Marelli 748 617 71  
 Servicing E84-0,8/12 v.  
 Without Brushes & springs



**AL 859**

Replacing Fiat/Marelli 721 639 01, -02  
 Servicing MTT71AB, -FB, -RB, -SB, -TA.


Brush MASX15-16



**AL 756**

Replacing Fiat/Marelli 723 627 01  
 Servicing MT68AB. AC. Q, QA  
 Without springs & Brushes  
 spring AL 8993

Brush MASX15-16




**AL 1327**

Replacing Fiat/Marelli 723 627 01  
 Servicing MT68AB. AC. Q, QA  
 With Brushes & Springs




Brush TAB 117



**AL 725**


Replacing Lucas 54243579, 54266922  
 Servicing M35J İntertia tupe  
 Without Brushes  
 With Springs

Brush LASX 15-16



**AL 728**


Replacing Lucas 60600032  
 Servicing M45 G, 26236, 26238, 26248,  
 26394, 26359, 26268, 26269, 26396, 26285,  
 26310, 26321, 26327, 26346, 26347, 26370,  
 26371, 26381, 26383, 26385,  
 W/o brush & springs  
 Brush spring AL52



**AL 749**

Replacing Lucas 54242829, 54244980  
 Servicing M50, M127


Brush TAB 117



**AL 795**


Replacing Lucas 60600616  
 Servicing M35J Pre-engaged type  
 Without Brushes  
 With Springs

Brush LASX 15-16



**AL 734**


Replacing Lucas 54250082  
 Servicing M45G, 26132, 26133, 26146,  
 26147, 26148, 26150, 26151, 26152, 26153,  
 26154, 26158, 26159, 26163, 26167, 26169,  
 26170, 26172, 26173  
 W/o Brushes & springs  
 Brush spring AL 52



**AL 752**

Replacing Lucas  
 Servicing M50 same AL 735 bracket  
 only brush holder used  
 LASX 15-16 Brushes  
 Bedford


Brush LASX15-16



**AL 726**


Replacing Lucas 54255957  
 Servicing M45G 26208, 26215, 26233,  
 26256, 26264, 26271, 26278, 26283, 26286,  
 26287, 26288, 26301, 26302, 26306, 26320,  
 26348, 26372, 26375, 26391  
 W/o Brush & springs  
 Brush spring AL 52

Brush LASX 36




**AL 735**

Replacing Lucas 54257605  
 Servicing M50 Band cover type  
 W/o brush & springs  
 Brush spring AL 52




**AL 700**

Replacing Lucas 54263852, 54265874  
Servicing 2M113, 27400, 27401, 27409,  
27411, 27412, 27413, 27415, 27416,  
27417, 27419, 27420, 27421, 27422,  
27423, 27424, 27425, 27426, 27427,  
27429, 27430, 27431, 27432, 27433




**AL 1341**

Replacing Lucas 54250082  
Servicing M45G, 26132, 26133, 26146,  
26147, 26148, 26150, 26151, 26152, 26153,  
26154, 26158, 26159, 26163, 26167, 26169,  
26170, 26172, 26173  
With Brushes & springs




**AL 8716**

Replacing Hitachi 2130 - 63015  
Servicing S13-200,-203,-204,-205,-205A  
-294,-302,-302A,-305,-307A,-317,-321,-322  
-326,-327,-331,-332,-S14-205,-206  
Nissan




**AL 757**

Replacing Lucas 54265875  
Servicing 2M113, 27403, 27414, 27470  
27474




**AL 1342**

Replacing Lucas 54257605  
Servicing M50 Band cover type  
With brush & springs Brush LASX 36




**AL 8717**

Replacing Hitachi 2130 -73014  
Servicing S13-106A,-106B,-106C,-127,  
-127C,-137A  
Nissan




**AL 1339**

Replacing Lucas 54255957  
Servicing M45G, 26208, 26215, 26233,  
26256, 26264, 26271, 26278, 26283, 26286,  
26287, 26288, 26301, 26302, 26306, 26320,  
26348, 26372, 26375, 26391  
With Brush & springs




**AL 1343**

Replacing Lucas  
Servicing M50 same AL 735  
only brush holder use LASX 15-16 Brushes




**AL 9338**

Replacing Mitsubishi M641B 10601,  
M644 x 21671  
Servicing M2T56181,-56182,-56185,-57271,  
-57771,-57871,-57881,-60171,-60172,-60185,  
-60671,-61071,-61072,-61171,-61271,-61771,  
-66871,-66872,-66873,-67871,-67872,-67873,  
-67881  
Mitsubishi, Hyundai




**AL 1340**

Replacing Lucas 60600032  
Servicing M45G, 26236, 26238, 26248,  
26394, 26359, 26268, 26269, 26396, 26285,  
26310, 26321, 26327, 26346, 26347, 26370,  
26371, 26381, 26383, 26385,  
With Brush & springs




**AL 8715**

Replacing Hitachi  
Servicing S13-62B,-S13-102,-S13-114,  
-114A,-S13-302  
Isuzu, Opel, Bedford




**AL 9404**

Replacing Mitsubishi M642 x 28771,  
MD618968  
Servicing M2T84071,-84171,-84571,-87071,  
-87171,-87371,-87571,-87971,-88071,  
-M8T8071,-80171,-80471,-80472,-80571,  
-85071,-85271




**AL 1241**

Replacing 2005 824 881  
Servicing 0001 359 055,-058,-060,-061,  
-062,-063,-064,-065,-067,-071,-072,-073,  
-074,-075,-076,-081,-082,-083,-084,-086,  
-087,-088,-090,-091,-094




**AL 748**

Replacing Lucas 54261382  
Servicing M50 & M127




**AL 9301**

Replacing Mitsubishi M640B12671,  
ME 700114  
Servicing M2T54271, -54371, -54372,  
-54471, -54572, -54771, -55571, -56171,  
-57671, -57671A, -57673, -57673A,  
-57673B, -57673C, -64271, -64372, -64373  
Mitsubishi, Hyundai




**AL 1593**

Replacing Bosch 2005 834 593  
Servicing 0001 372 001,-002,-003,-004,  
-005,-006,-008




**AL 771**

Replacing Lucas 54258129, 60600029  
Servicing 2M113, 27403, 27405,  
27406, 27414, 27424, 27425, 27427, 27428,  
27429, 27430, 27438, 37440, 27446, 27447,  
27448, 27452, 27457, 27458, 27460, 27461,  
27468, 27474




**AL 9415**

Replacing Mitsubishi M640B28771,  
ME700969  
Servicing M2T67881  
With Bearing



**AL 1595**

Replacing Bosch 2005 834 596  
Servicing 0001 371 004,-005,-006,-007,  
-008,-009,-012,-014,-017




**AL 9415 / D**

Replacing Mitsubishi M640B28771,  
ME700969  
Servicing Same M2T67881  
With Bearing and Extra Hole



**AL 856**


Replacing Fiat/Marelli 72364801  
Servicing MT67, MT68



**AL 9480**


Replacing Mando Melroe  
Servicing 36100 - 42011  
MG 120413 Starter I.M. Bracket  
Hyundai Grace, H100

N




**AL 1277**

Replacing Bosch 2005 825 087  
 Servicing FKB, 0001 410 029, -046, -050,  
 -067, -068, 0001 413 004, -005, -010, -011,  
 -012, 0001 414 011, -017, -018, -019,  
 0001 415 010, -013, -021, 0001 416 005,  
 -013, -017, -028, -043, -044, -063




**AL 743**

Replacing Bosch 1005 822 385  
 Servicing 0001 208 224  
 Opel




**AL 1321**

Replacing Bosch 2005 824 849  
 Servicing 0001 362 047, -600,  
 Mercedes - Unimog




**AL 1278**

Replacing Bosch 2005 825 218  
 Servicing FKB, 0001 410 088,  
 0001 411 009, -022, 0001 413 017,  
 0001 415 001, -037, 0001 418 014, -015,  
 -017




**AL 841**

Replacing Bosch 1005822321  
 Servicing Peugeot




**AL 1322**

Replacing Bosch 2005 834 100  
 Servicing 0001 367 039, 0001 368 028,  
 -045  
 Mercedes - Unimog - Kassbohrer




**AL 1347**

Replacing Bosch 2005 825 071  
 Servicing 0001410..., 0001413...,  
 0001414..., 0001415..., 0001416...,  
 0001417..., 0001418...




**AL 1320**

Replacing Bosch 2005 824 909  
 Servicing 0001 362 063, -300,  
 0001 367 001  
 Scania




**AL 1323**

Replacing Bosch 2005 834 061  
 Servicing 0001 367 027,  
 Volvo BM, AB




**AL 876**

Replacing Bosch 1005 823 472  
 Servicing 0001 314 037, -038  
 VW




**AL 1540**

Replacing Bosch 2005 834 064  
 Servicing 0001 367 026  
 0001368017, 063 Volvo




**AL 1544**

Replacing Bosch 9001 083 381  
 Servicing 9000 083 028, 054, 065  
 Ford New Holland




**AL 877**

Replacing Bosch 1005 822 373  
 Servicing 0001 208 709, -711, -713,  
 0001 211 504




**AL 1541**

Replacing Bosch 2005 834 035  
 Servicing 0001 368 016, 043, 056  
 Man



**AL 1545**

Replacing Bosch 1005 823 456  
 Servicing 0001 317 011, 016  
 Volkswagen Transporter




**AL 878**

Replacing Bosch 1005 823 314  
 Servicing 0001 311 113, -149  
 Ford, VW




**AL 1542**

Replacing Bosch 2005 834 315  
 Servicing 0001 369 001, 005  
 John Deere



**AL 1546**

Replacing Bosch 1005 823 451  
 Servicing 0001 317 007, 008, 024  
 Audi, VW




**AL 879**

Replacing Bosch 1007 010 036  
 Servicing 0001 208 220  
 Ford




**AL 1543**

Replacing Bosch 2005 824 704  
 Servicing 0001 364 100  
 Magirus Deutz, Iveco




**AL 1590**

Replacing Bosch 2005 834 825  
 Servicing 0001 372 001




**AL 799**

Replacing Fiat/Marelli 74872162  
Servicing E84-0.8/12v  
Fiat 124-131 (1300 cc)




**AL 846**

Replacing Fiat/Marelli 832 219 31  
Servicing E-80 1/12v  
63223031  
Tempra




**AL 774**

Replacing Lucas 54242188  
Servicing M50 & M127  
26265, 26341, 26431, 27511, 27554  
Iveco, Ford




**AL 800**

Replacing Fiat/Marelli 72332702  
Servicing MT64 AA  
Renault, Volvo, Daf




**AL 703**

Replacing Lucas 54258424  
Servicing M35G 25148  
Iveco, Ford




**AL 775**

Replacing Lucas 54242911  
Servicing M50, M127, 26246, 26304,  
26343, 26351, 26376, 27513, 27526,  
Leyland, Daf




**AL 814**

Replacing Fiat/Marelli 72332702  
Servicing E95-1/12v  
Fiat 131 (1600 cc)




**AL 704**

Replacing Lucas 54242326  
Servicing M35J 25148  
Ford




**AL 776**

Replacing Lucas 54264889  
Servicing M50, M127, 26349, 26416,  
27443, 27543, Bedford




**AL 786**

Replacing Fiat/Marelli 74872164  
Servicing MT68 AB, AC  
Iveco, Fiat, Ford




**AL 729**

Replacing Lucas 54253143  
Servicing M35G, 25079, 25085  
25088, 25138  
Rover, Blaw Knox




**AL 777**

Replacing Lucas 54249116  
Servicing M50 Starters  
Bedford




**AL 778**

Replacing Lucas 54249109, 54264664  
 Servicing M50, 26338, 26339, 26395,  
 27500, 27528, 27569  
 Ford Tractor




**AL 830**

Replacing Lucas 542 591 36  
 Servicing M45G, 26154  
 26200, 26220  
 Massey Ferguson




**AL 845**

Replacing Lucas 54265362  
 Servicing M45G, 2M113, 26400,  
 27431 Leyland / DAF




**AL 781**

Replacing Lucas 54265121  
 Servicing M50, M127, 26294, 26295, 26345,  
 26366, 26404, 26410, 27503, 27510, 27575,  
 27578, 27591, 27594, 27599  
 Massey Ferguson



**AL 838**


Replacing Lucas 54292157  
 Servicing M127 27564  
 Erf, Leyland Daf



N


**AL 1573**

Replacing Bosch 2005 825 183  
 Servicing 0001 410 065,  
 0001 411 025, 0001 417 005




**AL 782**

Replacing Lucas 54293053  
 Servicing M45, 2M113, 26264, 26412,  
 27409, 27432, 27459, 27469, 27470,  
 27474 Massey Ferguson



**AL 842**


Replacing Lucas 60600232  
 Servicing 3M100 PE  
 25684, 25742  
 Jaguar



N


**AL 1627**

Replacing Bosch 2005 834 155  
 Servicing 0001 3595 090  
 John Deere




**AL 807**

Replacing Lucas 54265243, 54293977  
 Servicing M50, M127, 26414, 27541,  
 27547, 27565, 27568 JCB




**AL 844**

Replacing Lucas  
 Servicing M50, M127, 26388, 26407,  
 27501, 27531,  
 Ford Transit




**AL 1596**

Replacing Bosch 6033 ADO 174,-231  
 Servicing 0001 231 00227501, 27531,  
 Under Development




**AL 242**

Replacing Bosch  
 Servicing 0331 303 107, 607  
 3 terminals. Crimp style  
 Contact AL 242



**AL 287**

Replacing Bosch  
 Servicing 0331 402 028  
 3 terminals. Crimp style  
 Contact AL 284




**AL 292**

Replacing Bosch  
 Servicing 0331 303 020, 108, 520  
 3 terminals. Crimp style  
 Contact AL 370




**AL 243**

Replacing Bosch  
 Servicing 0331 301 001, 005, 089  
 Unimog




**AL 288**

Replacing Bosch  
 Servicing 0331 401 008, 009, 016  
 3 terminals. Crimp style  
 Contact AL 371




**AL 296**

Replacing Bosch  
 Servicing 0331 303 105, 124, 125, 134  
 140, 164 2339.303227, F010 SHO 105  
 3 terminals. Crimp style  
 Contact AL 370




**AL 270**

Replacing Bosch  
 Servicing 0331 303 086,-089  
 3 terminals. Crimp style  
 Contact AL 370




**AL 289**

Replacing Bosch  
 Servicing 0331 302 040, 067  
 3 terminals. Crimp style  
 Contact AL 368



**AL 313**

Replacing Bosch  
 Servicing 0331 302 001, 002, 006,  
 009, 020, 070  
 3 terminals  
 Contact AL 368




**AL 286**

Replacing Bosch  
 Servicing 0331 303 014, 055, 076  
 3 terminals. Crimp style  
 Contact AL 370



**AL 290**


Replacing Bosch  
 Servicing 0331 302 003  
 4 terminals.  
 Contact AL 370



**AL 332**


Replacing Bosch  
 Servicing 0331 400 003, 009, 011  
 3 terminals.  
 Contact AL 371






**AL 339**

Replacing Bosch 1330 516 072  
 Servicing 0331 303 003,-007,-010,-015,-027,  
 4 terminals. Crimp style  
 Contact AL 370




**AL 348**

Replacing Bosch  
 Servicing 0331 303 026,-37,-042,-043,-046,-066,-101,-110,  
 3 terminals. Crimp style  
 Contact AL 370




**AL 352**

Replacing Bosch  
 Servicing 0331 303 005,-016,-028,-031,  
 4 terminals. Crimp style  
 Contact AL 370




**AL 340**

Replacing Bosch  
 Servicing 0331 402 001, 005, 006, 007, 008, 016, 030, 031, 035, 054, 073, 077, 078, 081  
 3 terminals. Crimp style  
 Contact AL 284




**AL 349**

Replacing Bosch  
 Servicing 0331 401 004,-007,-022,-025,-029,-033  
 3 terminals. Crimp style  
 Contact AL 371




**AL 353**

Replacing Bosch 1330 516 034  
 Servicing 0331 302 024,-027,-032,-034,-040,-043,-050,-067,-070,-524,-543,  
 3 terminals. Crimp style  
 Contact AL 368




**AL 344**

Replacing Bosch 1330 516 037  
 Servicing 0331 302 044,-045,-059,-062,-070,-081,-097,  
 4 terminals.  
 Contact AL 368




**AL 350**

Replacing Bosch  
 Servicing 0331 302 054,-063,-090,-091,  
 4 terminals.  
 Contact AL 368




**AL 354**

Replacing Bosch  
 Servicing 0331 401 001,-002,-003,-011,-014,-017,-026,-030,  
 Crimp style  
 Contact AL 371




**AL 347**

Replacing Bosch  
 Servicing 0331 402 015,-017,-021,-024,-055,-076  
 3 terminals.  
 Contact AL 284




**AL 351**

Replacing Bosch  
 Servicing 0331 402 010,-013,  
 3 terminals.  
 Terminal 50, 6 mm. Crimp style  
 Contact AL 284




**AL 355**

Replacing Bosch 1330 516 062  
 Servicing 0331 303 002,-004,-009,-013,-029,-071,-073,-094,  
 4 terminals.  
 Contact AL 370




**AL 376**

Replacing Bosch  
 Servicing 0331 303 005,  
 013, 024, 029, 041  
 4 terminals. Crimp style  
 Contact AL 370




**AL 390**

Replacing Bosch  
 Servicing 0331 303 060,-81,-082,-83,  
 -091,  
 3 terminals. Crimp style  
 Contact AL 370




**AL 394**

Replacing Bosch 1330 516 045  
 Servicing 0331 302 106, 570  
 4 terminals.  
 Contact AL 370




**AL 381**

Replacing Bosch  
 Servicing 0331 302 048,-050,-076,-087,  
 9330 691 003,  
 4 terminals.  
 Contact AL 368




**AL 391**

Replacing Bosch  
 Servicing 0331 303 033,-078,  
 4 terminals. Crimp style  
 Contact AL 370




**AL 395**

Replacing Bosch  
 Servicing 0331 303 019,  
 3 terminals.  
 Contact AL 370




**AL 387**

Replacing Bosch  
 Servicing 0331 303 117, 120  
 4 terminals. W / 30 terminal  
 Contact AL 370




**AL 392**

Replacing Bosch  
 Servicing 0331 303 048, 053, 061,  
 3 terminals.  
 Contact AL 370




**AL 3000**

Replacing Bosch  
 Servicing 0331 302 096,  
 3 terminals  
 Contact AL 368




**AL 388**

Replacing Bosch  
 Servicing 0331 303 070, 072,  
 Contact AL 368




**AL 393**

Replacing Bosch 1330 516 225  
 Servicing 0331 303 014,-055,-056,-057,  
 -076  
 3 terminals. Crimp style  
 Contact AL 370




**AL 3001**


Replacing Bosch  
 Servicing 0331 302 015, 018, 022, 055  
 3 terminals.  
 Contact AL 368




**AL 3002**  
 Replacing Bosch  
 Servicing 0331302084  
 5 terminals  
 Contact AL 368




**AL 3061**  
 Replacing Bosch  
 Servicing 0331303137  
 2339303208  
 3 terminals.  
 Contact AL 370




**AL 3076**  
 Replacing Bosch  
 Servicing 2339304001  
 3 terminals. Crimp style  
 for small body solenoids  
 Contact AL 3077




**AL 3003**  
 Replacing Bosch  
 Servicing 0331402089, 521, 549  
 Insulated return Cap  
 4 terminals.  
 Contact AL 284




**AL 3063**  
 Replacing Bosch  
 Servicing 0331402012  
 4 terminals Insulated return Cap 24 v  
 Contact AL 3058




**AL 3084**  
 Replacing Bosch  
 Servicing 2339303229  
 3 terminals. Crimp style  
 Contact AL3077




**AL 3015**  
 Replacing Bosch  
 Servicing 0331303065, 069, 086  
 4 terminals.  
 Contact AL 370




**AL 3064**  
 Replacing Bosch  
 Servicing 0331402535  
 Insulated return Cap  
 3 terminals.  
 Contact AL 3058




**AL 3085**  
 Replacing Bosch  
 Servicing 2339303...  
 3 terminals  
 Contact AL3077




**AL 3051**  
 Replacing Bosch  
 Servicing 0331303012, 035  
 4 terminals.  
 Contact AL 370




**AL 3066**  
 Replacing Bosch  
 Servicing 0331303030  
 4 terminals.  
 Contact AL370




**AL 3103**  
 Replacing Bosch  
 Servicing 2339304007  
 3 terminals  
 Contact AL 3077




**AL 3104**  
 Replacing Bosch  
 Servicing 2339304003  
 3 terminals.  
 Contact AL 3077




**AL 3119**  
 Replacing Bosch 1330516062  
 Servicing 0331303147  
 3 terminals VW




**AL 3109**  
 Replacing Bosch  
 Servicing 0331 303 133- 142  
 2339 303 201,-205  
 3 terminals Crimp style




**AL 3111**  
 Replacing Bosch  
 Servicing Modified cap for  
 2339304008 Solenoids  
 Citroen, Peugeot (3 terminals)




**AL 3121**  
 Replacing Bosch  
 Servicing Modified cap for  
 2339303210, 2339303221  
 (3 terminals)




**AL 3117**  
 Replacing Bosch  
 Servicing 2339 403 009  
 0001 371 010,-13, 0001 372 002,-003  
 Mobile contact AL 3114




**AL 3112**  
 Replacing Bosch  
 Servicing 2339403010  
 0001 371 001, 0001 372 001,-005,-006  
 Mobile contact AL 3114




**AL 3123**  
 Replacing Bosch  
 Servicing 0331303039, 062, 095, 109,  
 155, 165 2339303209, 311  
 3 terminals.




**AL 3129**  
 Replacing Bosch  
 Servicing 2339 402 117,-156  
 0001 231 002  
 Mobile contact AL 3098




**AL 3118**  
 Replacing Bosch  
 Servicing Modified cap for  
 2339304001 Solenoids  
 (4 terminals) BMW




**AL 3124**  
 Replacing Bosch  
 Servicing 2339303223  
 0001108180 Starters




**AL 3130**  
 Replacing Bosch  
 Servicing 2339 403 006  
 0001 371 004,-006,-008  
 Mobile contact AL 3114




**AL 3045**  
 Replacing Delco Remy  
 Servicing 10475646  
 4 terminals.  
 Contact AL 3046



**AL 308**  
 Replacing Evropean Delco  
 Servicing DR 901 3471144, 694  
 4 terminals.  
 Contact AL 372




**AL 3060**  
 Replacing Delco Remy  
 Servicing 1114578, 582  
 3 terminals.  
 Contact AL 3057




**AL 3016**  
 Replacing Evropean Delco  
 Servicing 3471169, 73, 74  
 3 terminals. Vaux hall  
 Contact AL 3013

24v




**AL 3086**  
 Replacing Delco Remy  
 Servicing 42 MT 12v  
 1115593




**AL 3017**  
 Replacing Evropean Delco  
 Servicing DR 903, 3471697  
 4 terminals low type  
 Contact AL 3013


12v




**AL 304**  
 Replacing Delco Remy  
 Servicing 30 MT 1115540  
 4 terminals.  
 Contact AL 328



**AL 3087**  
 Replacing Delco Remy  
 Servicing 37 MT, 42 MT, 24v 1115594,  
 1115595, 1115597, 111560, 1115608  
 Contact AL 328




**AL 272**  
 Replacing Ducellier  
 Servicing 583098, 681726  
 3 terminals




**AL 273**

Replacing Ducellier  
 Servicing 583262, 618511, 681217  
 681411,  
 4 terminals. Crimp style




**AL 299**

Replacing Ducellier  
 Servicing 583036  
 3 terminals. Crimp style




**AL 3008**

Replacing Femsa  
 Servicing MOK 12-1, MTS 12-48,  
 4 terminals




**AL 274**

Replacing Ducellier  
 Servicing 680559  
 3 terminals. Crimp style




**AL 379**

Replacing Ducellier  
 Servicing 534042, 534943  
 583333, 683457  
 3 terminals




**AL 3032**

Replacing Femsa  
 Servicing 21478-1  
 Contact AL 245 / A




**AL 275**

Replacing Ducellier  
 Servicing 583004, 683586  
 4 terminals. Crimp style




**AL 3009**

Replacing Ducellier  
 Servicing 583330, 583334, 681872,  
 683129, 683287, 683480, 683487,  
 133771  
 3 terminals




**AL 3037**

Replacing Femsa  
 Servicing MTA 12-30, P30,  
 MTS 12-P17-V12-V31  
 3 terminals.  
 Contact AL 245 / A




**AL 294**

Replacing Ducellier  
 Servicing 583079, 583080  
 3 terminals. Crimp style




**AL 3011**

Replacing Ducellier  
 Servicing 583302  
 3 terminals.




**AL 3038**

Replacing Femsa  
 Servicing MTA 12-2,-12-4,-12-40  
 MTA 12-H04,-08,-24,-30,  
 MTA 12-P03,-07  
 3 terminals.




**AL 255**

Replacing Fiat / Marelli  
 Servicing 855 404 71, 855 408, 91,  
 3 terminals.  
 Contact AL 3030




**AL 337**

Replacing Fiat / Marelli  
 Servicing 4189658, 636 004 00,  
 W / spade terminals.  
 Contact AL 245 A




**AL 3022**

Replacing Fiat / Marelli  
 Servicing 4073327, 4142558,  
 636 005 02,-04,-06,  
 W / bullet terminals.  
 Contact AL 245 A




**AL 324**

Replacing Fiat / Marelli  
 Servicing 4171104, 4171243, 4474964,  
 636 021 00, 636 022 00, 90, 636 333 01,  
 636 334 01




**AL 343**

Replacing Fiat / Marelli  
 Servicing 9932505, 99336770, 995705,  
 9986109, 636 335 01,-02, 636 336 01,  
 636 338, 25, 636 339, 01,-02,-25,  
 3 terminals. Crimp styles  
 Contact AL 396




**AL 3079**

Replacing Fiat / Marelli  
 Servicing 855 411 11  
 3 terminals.  
 Contact AL 3078




**AL 335**

Replacing Fiat / Marelli  
 Servicing 800863, 869066,  
 Contact AL 177




**AL 366**

Replacing Fiat / Marelli  
 Servicing 636 010 07, 855 404 61,  
 4 terminals.  
 Contact AL 244




**AL 3080**

Replacing Fiat / Marelli  
 Servicing 855 409 81,  
 3 terminals.  
 Contact AL 3078




**AL 336**

Replacing Fiat / Marelli  
 Servicing 636 004 08,-83,-93  
 855 300 10,-20,-30,-90,  
 855 302 20,-80,-90, 855 303 30,  
 855 404 72,  
 3 terminals.  
 Contact AL 310




**AL 3010**

Replacing Fiat / Marelli  
 Servicing 636 016 00, 636 017 00,  
 855 400 71, 855 403 71,  
 3 terminals.  
 Contact AL 3030




**AL 3081**

Replacing Fiat / Marelli  
 Servicing 855 410 03,  
 3 terminals.  
 Contact AL 3078




**AL 3035**

Replacing U.S.A. Ford  
 Servicing E90Z-11390-A, F02Z-11390-A,  
 PMGR Startes  
 12 v 3 terminals




**AL 238**

Replacing Hitachi  
 Servicing 211-7007,  
 3 terminals.




**AL 383**

Replacing Hitachi  
 Servicing 2114-17005, -17505, -27501,  
 -37005, -37503, -37504, -37505, -47005,  
 -57503, -57508, -67505, -67002,  
 23343-04E00,-01,M4900, V5301,  
 3 terminals. Crimp style  
 Contact AL 269




**AL 3122**

Replacing Ford / Visteon  
 Servicing F3 RZ - 11390A, B  
 Ford




**AL 247**

Replacing Hitachi  
 Servicing 2114-17005, -37504, -47005,  
 -57508, -77007, 2120-27002, -57002,  
 2130-6001,  
 3 terminals. Crimp styles  
 Contact AL 268




**AL 384**

Replacing Hitachi  
 Servicing 2114-17006, -27001, -37003,  
 -67006, -77001,  
 3 terminals. Crimp style  
 Contact AL 268




**AL 262**

Replacing Hitachi  
 Servicing 2114-47003,  
 4 terminals. Crimp style




**AL 3018**

Replacing Hitachi  
 Servicing 2114-27006  
 4 terminals. Crimp style  
 Contact AL 268



**AL 382**


Replacing Hitachi  
 Servicing 2114-47001, -57001, -57504,  
 -77004, 2130-47001  
 3 terminals. Crimp style



**AL 3024**


Replacing Hitachi  
 Servicing 2114-87508, 23343-17C00,  
 3 terminals. Crimp style  
 Contact AL 269






**AL 3025**

Replacing Hitachi  
Servicing 2114-77601,  
4 terminals. Crimp style  
Contact AL 269




**AL 3050/A**

Replacing Hitachi  
Servicing 2240-5700, 2250-22002,-37001,  
-37003,-47003,-57003,-87004, 2130-7705,  
-97004,  
3 terminals. Crimp style  
Contact AL 268




**AL 3026**

Replacing Hitachi  
Servicing 2114-77008  
3 terminals. Crimp style  
Contact AL 368




**AL 3053**

Replacing Hitachi  
Servicing 2130-97004,  
3 terminals. Crimp styles  
Contact AL 268




**AL 377**

Replacing Iskra  
Servicing 13.905-423,-524,  
3 terminals. Crimp style  
Contact AL 216




**AL 3039**

Replacing Hitachi  
Servicing 2114-27504,-47505,-77505,  
-87503,  
3 terminals. Crimp style  
Contact AL 269



**AL 3083**


Replacing Hitachi  
Servicing S114-850,-850A,-850B  
3 terminals.  
Contact AL 269



**AL 378**


Replacing Iskra  
Servicing 16.905.418,  
3 terminals. Crimp style  
Contact AL 216

\*(Screw hole in blade)\*




**AL 3050**

Replacing Hitachi  
Servicing 2240-8700, 2250-22002,-37001,  
-37003,-47003,-57003,-87004, 2130-7705,  
3 terminals. Crimp style  
Contact AL 268




**AL 3101**

Replacing Hitachi  
Servicing 2130-57005,-67005,-77005,  
3 terminals. Crimp style  
Contact AL 268




**AL 3036**

Replacing Iskra  
Servicing 16.905.426  
4 terminals.  
Contact AL 216




**AL 362**

Replacing Lada  
 Servicing 2108-370-8805  
 Lada Jet  
 3 terminals. Crimp style  
 Contact AL 249




**AL 215**

Replacing Lucas 54646689, TWB 108  
 Servicing M50, York, 76901, 76936,  
 76985, 76997, 77008, 7027, 77054,  
 77163, TOB 123,-125,




**AL 263**

Replacing Lucas 60600568, TWB 111  
 Servicing 76994, 77036, 77122, 77140,  
 77149, 77123, TOB 182,  
 Contact AL 300




**AL 363**

Replacing Lada  
 Servicing 2108-3708808  
 Samara  
 3 terminals.  
 Contact AL 249



**AL 218**

Replacing Lucas TWB 123  
 Servicing 77174, 77177, 77194, 77204,  
 TPB140,-146,  
 4 terminals.  
 Contact AL 329




**AL 264**

Replacing Lucas  
 Servicing Same AL 263  
 Stud M 8  
 3 terminals. Crimp style  
 Contact AL 300




**AL 3102**

Replacing Lada  
 Servicing 2101-3708805  
 Niva  
 W/Spade terminals  
 Contact AL 245 / A




**AL 219**

Replacing Lucas  
 Servicing 77171, 77192, TPB132  
 3 terminals.  
 Contact AL 329




**AL 301**

Replacing Lucas 60600645, TWB 113,  
 Servicing M418G, M45G, 76803, 76895,  
 76899, 76902, 76906, 76908, 76925,  
 TOB113,-119,-131,-134,  
 Contact AL 300




**AL 246**

Replacing Lucas 54643283  
 Servicing 76891  
 4 terminals.  
 Contact AL 325




**AL 312**

Replacing Lucas 54642436, TWB100  
 Servicing M45G, 76458, 76474, 76490,  
 76498, 76538, 76712, 76727, 76744,  
 76748, 76758, 76759, 76808, 76840,  
 TOB100,-153,  
 Contact AL 327




**AL 314**

Replacing Lucas 54642116  
 Servicing 76864, 76865  
 Late model




**AL 333**

Replacing Lucas 60600653, TWB 103  
 Servicing M35J, 76790, 76805, 76830,  
 76842, 76848, 76849, 76870, 76883, .  
 76893, 76898, 76954, 76980, 76995,  
 77002, 77003, 77009, TOB 191  
 Contact AL 329




**AL 346**

Replacing Lucas 60600162, TWB 110  
 Servicing 2M100, 3M100, 76878, 76880,  
 76970, 76923, 77092, 77179, TOB116,  
 Contact AL 300




**AL 320**

Replacing Lucas 54646683, TWB107  
 Servicing M50, 76833, 76834, 76835,  
 76836, 76854, 76862, 76864,  
 76865, 76869, 76881, 76900, 76910,  
 TOB110,-183




**AL 338**

Replacing Lucas 60600125, TWB114  
 Servicing M418G, M45G, M100, 76897,  
 76935, 77016, 77017, 77059, 77158,  
 TOB 162  
 Contact AL 300




**AL 386**

Replacing Lucas  
 Servicing 77129, 77135,  
 TPB 112, 122, Jaguar  
 Contact AL 300




**AL 323**

Replacing Lucas 54643283  
 Servicing 76755  
 Late model




**AL 341**

Replacing Lucas 54646009, TWB 117  
 Servicing 8M90, 9M90, 77031, 77093,  
 77094, TOB194, Ford,  
 Contact AL 375




**AL 3004**

Replacing Lucas 60600546, TWB 118,  
 Servicing M35J, TOB112  
 Contact AL 329




**AL 330**

Replacing Lucas 54646071  
 Servicing 76985, 77115, TOB 173




**AL 345**

Replacing Lucas TWB 124,-123  
 Servicing 8M90, 9M90, 77118, 77170,  
 77196, 77191, 77196 BLMC, TPB 138,-145,  
 Contact AL 375




**AL 3005**

Replacing Lucas 54647433,-8102, TWB121  
 Servicing 77094, 77180, 77182, 77185,  
 77186, 77190, 77193, 77231, TPB142,  
 -143,-144,-147,-148,-152  
 4 terminals  
 Contact AL 375




**AL 3006**

Replacing Lucas  
 Servicing 77174, 77194,  
 77204, TPB 140, 146, 154,  
 3 terminals  
 Contact AL 375




**AL 3033**

Replacing Lucas  
 Servicing 77034, 77118, 77164,  
 TOB 130, 135  
 Cold Start  
 Contact AL 375




**AL 315**

Replacing Lucas  
 Servicing Capof  
 54642116, 54642420  
 Contact AL 316




**AL 3007**

Replacing Lucas 54647433, TWB 121  
 Servicing 77094, 77180, 77182, 77185,  
 77186, 77190, 77193, 77231, TPB 142,  
 -142, -144, -147, -148, -152,  
 3 terminals  
 Contact AL 375




**AL 3055**

Replacing Lucas  
 Servicing TPB 114, TPB 115,  
 77136, 77138,  
 3 terminals  
 Contact AL 300




**AL 321**

Replacing Lucas  
 Servicing Capof  
 TWB 107, 54646683  
 Contact AL 322




**AL 3028**

Replacing Lucas  
 Servicing 77230 All Fords  
 Contact AL 375




**AL 3065**

Replacing Lucas  
 Servicing 77252,  
 3 terminals  
 Contact AL 375




**AL 330/A**

Replacing Lucas  
 Servicing Capof  
 54646071  
 Contact AL 330/B




**AL 3029**

Replacing Lucas  
 Servicing 77110, 77156, 77161,  
 TOB167, 172, 196  
 Screw on connection  
 Contact AL 300




**AL 3115**

Replacing Lucas 54648338  
 Servicing 77207, TPB157  
 3 terminals




**AL 3110**


Replacing Lucas TWB123  
 Servicing 77174 Same  
 AL 218 cap but different terminal




**AL 252**  
 Replacing Mitsuba  
 Servicing 31210-PC2-026,  
 31210, PE1-671, 31210-PC2-016,  
 -PD2-006,-016  
 3 terminals Crimp style




**AL 237**  
 Replacing Mitsubishi  
 Servicing M371 x 00171,-16171,-16371,  
 -16471,-33071,-53072,-58771,-58871,  
 3 terminals Crimp style  
 Contact AL 3014




**AL 3090**  
 Replacing Magneton 443 930 157 540  
 Servicing 443 937 150 241  
 Skoda 105, 110, 120  
 12 v. 4 terminals  
 Contact AL 3092




**AL 3012**  
 Replacing Mitsuba  
 Servicing SM 302-19  
 SM 402-04N 105/05 N  
 SM 402-11/11 N




**AL 250**  
 Replacing Mitsubishi  
 Servicing M 371 X 00272,-17271,-34471,  
 -35071,-54671,-36271,  
 3 terminals Crimp style  
 Contact AL 3014




**AL 3091**  
 Replacing Magneton 443 930 157 940,-941  
 Servicing 443 930 157 971,  
 Skoda Formen, Favorit  
 3 terminals  
 Contact AL 3092




**AL 3019**  
 Replacing Mitsubishi  
 Servicing M371 x 66571  
 PMGR Startes  
 3 terminals  
 Contact AL 3014




**AL 3019/A**  
 Replacing Mitsubishi  
 Servicing Same AL 3019 but deep version  
 Contact AL 3014




**AL 3034**  
 Replacing Mitsubishi  
 Servicing M 371 x 41971  
 3 terminals  
 Contact AL 3014




**AL 3043**  
 Replacing Mitsubishi  
 Servicing M 371 x 33371,  
 4 terminals Crimp style  
 Contact AL 3014




**AL 3073**  
 Replacing Mitsubishi  
 Servicing M1 T 50172  
 Contact AL 3014




**AL 3040**  
 Replacing Mitsubishi  
 Servicing M371 x 61371  
 4 terminals Crimp style  
 Contact AL 3014




**AL 3044**  
 Replacing Mitsubishi  
 Servicing M371 x 62571  
 3 Terminals  
 Contact AL 3014




**AL 3074**  
 Replacing Mitsubishi  
 Servicing M371 x 60271  
 3 Terminals Crimp style  
 Contact AL 3014




**AL 3041**  
 Replacing Mitsubishi  
 Servicing M 373 x 2988  
 Contact AL 3014




**AL 3047**  
 Replacing Mitsubishi  
 Servicing M 371 x 68771,  
 3 terminals Crimp style  
 Contact AL 3014




**AL 3113**  
 Replacing Mitsubishi  
 Servicing  
 M372 X 10171, 10271  
 Mitsubishi Canter  
 Contact AL 3126




**AL 3042**  
 Replacing Mitsubishi  
 Servicing M 371 x 64273, -64471, -64971,  
 3 terminals Crimp style.  
 Contact AL 3014



**AL 3048**  
 Replacing Mitsubishi  
 Servicing M 371 x 69171, -76275, -76371  
 3 terminals Crimp style  
 Contact AL 3014




**AL 3125**  
 Replacing Mitsubishi  
 Servicing  
 M372 X 10471, MD607634  
 HYUNDAI H100, Mitsubishi  
 Contact AL 3126




**AL 251**

Replacing Nippondenso  
 Servicing 053400-3840, 3932,  
 4432, 5050, 5240  
 Contact AL 3059




**AL 3062**

Replacing Nippondenso  
 Servicing 053400-1150,-1151,-2160,  
 -2550,-3340,  
 4 terminals




**AL 239**

Replacing Paris Rhone  
 Servicing CED 501, 539, 073302, 182438,  
 3 terminals  
 Contact AL 235




**AL 267**

Replacing Nippondenso  
 Servicing 028000-7110, 7112,-7120,  
 -7121, Ford,  
 4 terminals Crimp style




**AL 3027**

Replacing Nippondenso  
 Servicing Modified type  
 Universal Applications  
 4 terminals  
 Contact AL 3059




**AL 240**

Replacing Paris Rhone  
 Servicing CED 529, 102217  
 Crimp style 3 terminals  
 Contact AL 297




**AL 3020**

Replacing Nippondenso  
 Servicing 053400-3931,  
 3 terminals Crimp style  
 Contact AL 1212




**AL 3052**

Replacing Nippondenso  
 Servicing Modified type  
 Universal Applications  
 4 terminals  
 Contact AL 3059




**AL 253**

Replacing Paris Rhone  
 Servicing 182428, CED 67,  
 3 terminals  
 Contact AL 232




**AL 3021**

Replacing Nippondenso  
 Servicing 028000-7110,-7112,-7120,  
 -7121, Ford  
 3 terminals Crimp style.




**AL 254**

Replacing Paris Rhone 182 148  
 Servicing D 13E 76,-77,-86TE,-87TE,  
 -93TE,-94TE,-96TE,  
 Deep of the cap 18.5 mm  
 3 terminals. Contact AL 232




**AL 291**

Replacing Paris Rhone  
 Servicing CED 502, 504, 510, 512, 74764  
 3 terminals  
 Contact AL 374




**AL 311/A**

Replacing Paris Rhone  
 Servicing Same AL 311  
 only bridge different side  
 Contact AL 241




**AL 358/A**

Replacing Paris Rhone  
 Servicing 594048, 594119  
 3 terminals  
 Contact AL 297




**AL 291/A**

Replacing Paris Rhone  
 Servicing CED 502, 504, 510, 512  
 74764, Same AL 291 only  
 bridge different side  
 Contact AL 374




**AL 356**

Replacing Paris Rhone  
 Servicing CED 437, 446, 448, 454, 458  
 460, 468  
 4 terminals  
 Contact AL 280




**AL 359**

Replacing Paris Rhone  
 Servicing CED 521, 101062,  
 Crimp style  
 3 terminals  
 Contact AL 297




**AL 295**

Replacing Paris Rhone 182152  
 Servicing D 15 E 29,-29TE,-30,-30 TE,  
 3 terminals  
 Contact AL 293




**AL 357**

Replacing Paris Rhone  
 Servicing CED 436, 444  
 Contact AL 280




**AL 360**

Replacing Paris Rhone  
 Servicing CED 517, 99378,  
 3 terminals Crimp style  
 Contact AL 297




**AL 311**

Replacing Paris Rhone 182148  
 Servicing D 13 E 76, 77, 86TE 87TE 93TE,  
 94TE, 96TE  
 Dept of the cap 18.5 mm  
 3 terminals  
 Contact AL 241



**AL 358**


Replacing Paris Rhone  
 Servicing CED 518, 528, 099932,  
 102190, 182464,  
 3 terminals Crimp style  
 Contact AL 297



**AL 361**


Replacing Paris Rhone  
 Servicing CED 533, 537, 538, 540, 541,  
 544, 546, 548, 550, 102849, 103794,  
 104594, 104604, 105489, 106142, 106143,  
 3 terminals Crimp style  
 Contact AL 297






**AL 364**

Replacing Paris Rhone  
 Servicing CED519 100427  
 D 11 E 172 Startes  
 3 terminals  
 Contact AL 282




**AL 3049**

Replacing Paris Rhone  
 Servicing 182460, 182461,  
 182463, 594045  
 Contact AL 297




**AL 342**

Replacing Romania  
 Servicing DM2130, 2134  
 Contact AL 248




**AL 380**

Replacing Paris Rhone  
 Servicing CED 41, 42, 401, 402, 403,  
 404, 406, 407, 408, 409, 410, 413, 414,  
 415, 443,  
 3 terminals, Contact AL 235




**AL 3067**

Replacing Paris Rhone  
 Servicing 594054  
 4 Terminals  
 Contact AL 297




**AL 389**

Replacing Paris Rhone  
 Servicing CED 5,53, 506, 527,  
 3 terminals Contact AL 282




**AL 3068**

Replacing Paris Rhone  
 Servicing CED 504, 510, 512, 543,  
 105254, 182462,  
 4 terminals. Crimp style  
 Contact AL 297




**AL 3093**

Replacing Sawafuji  
 Servicing  
 1350-097-00X9  
 1350-098-00X9  
 1350-101-00X9  
 1350-101-11X9




**AL 399**

Replacing Paris Rhone  
 Servicing 182424  
 Dept of the cap 17 mm  
 3 terminals




**AL 3075**

Replacing Paris Rhone  
 Servicing 182563  
 D 6 RA 32, 62  
 Contact AL 297



### AL 298

Replacing Turkish / Marelli  
Servicing 63692803  
63693902 Fiat İvego  
Contact AL 396




### AL 334

Replacing Turkish / Marelli  
Servicing 63600301, 501  
MF, Fiat, Ford, Steyr  
Contact AL 318 / A




### AL 365

Replacing Turkish / Marelli  
Servicing 63600995  
Murat 131 ( 1600 cc)  
Contact AL 244




### AL 385

Replacing Turkish / Marelli  
Servicing 63609504  
Renault R9 - R11 - R19  
3 terminals  
Contact AL 244




**AL 283**

Replacing Bosch  
 Servicing 0331 402...  
 Plate 39.5 x 18 x 4 mm  
 Shaft 31.6 mm




**AL 368**

Replacing Bosch  
 Servicing 0331 302...  
 Plate 30 x 15 x 2 mm




**AL 3058**

Replacing Bosch  
 Servicing 0331402 055  
 Plate 39.2 x 17.7 x 4 mm  
 Shaft 52.8 mm




**AL 284**

Replacing Bosch  
 Servicing 0331 402...  
 Plate 39.5 x 18 x 4 mm  
 Shaft 32.1 mm




**AL 369**

Replacing Bosch  
 Servicing 0331 402...  
 Plate 39.5 x 18 x 4 mm  
 Shaft 32.1 mm




**AL 3072**

Replacing Bosch  
 Servicing 0331 402 054,-031,-089,  
 Plate 39.5 x 18 x 4 mm




**AL 285**

Replacing Bosch  
 Servicing 0331 402...  
 Plate 39.5 x 18 x 4 mm  
 Shaft 31.5 mm




**AL 370**

Replacing Bosch  
 Servicing 0331 303...  
 Plate 32 x 15 x 2 mm  
 Shaft 31.6 mm




**AL 3077**

Replacing Bosch  
 Servicing 2339 303...  
 2339 304...



**AL 367**

Replacing Bosch  
 Servicing 0331 402...  
 Plate 36 x 15 x 2 mm  
 Shaft 31.5 mm




**AL 371**

Replacing Bosch  
 Servicing 0331 401...  
 Plate 35 x 18 x 4 mm




**AL 3098**


Replacing Bosch  
 Servicing  
 Moving contact




**AL 276/A**  
 Replacing Bosch  
 Servicing 0331 303...  
 M8 x 26 mm  
 Fixed contact




**AL 278/A**  
 Replacing Bosch  
 Servicing 0331 303...  
 M8 x 26 mm  
 Fixed contact




**AL 276/B**  
 Replacing Bosch  
 Servicing 0331 303...  
 M8 x 31 mm  
 Fixed contact




**AL 278/B**  
 Replacing Bosch  
 Servicing 0331 303...  
 M8, 36 mm  
 Fixed contact




**AL 277/A**  
 Replacing Bosch  
 Servicing 0331 402...  
 Fixed contact




**AL 7**  
 Replacing Bosch 1004 483 002  
 Servicing 0001.107 031,-032,-049  
 Terminal



**AL 277/B**  
 Replacing Bosch  
 Servicing 0331 402...  
 M10 x 41 mm  
 Fixed contact




**AL 3114**  
 Replacing Bosch  
 Servicing 2339403010  
 Mercedes Actros




**AL 372**

Replacing Evropean Delco  
Servicing DR 901 - 902




**AL 328**

Replacing Delco U.S.A.  
Servicing 1115540




**AL 398**

Replacing Ducellier  
Servicing 583099, 583161, 583333,  
682038, 683099, 683129, 683457, 683487




**AL 3013**

Replacing Evropean Delco  
Servicing 3471169, 73, 74



**AL 3046**

Replacing Delco U.S.A.  
Servicing 10475646, 1114583




**AL 3070**

Replacing Evropean Delco  
Servicing DR 903 - 904




**AL 3057**

Replacing Delco U.S.A.  
Servicing 1114578, 10469039




**AL 177**

Replacing Fiat / Marelli  
Servicing 800863 - 869066




**AL 318/A**

Replacing Fiat / Marelli  
Servicing 63602290  
63303301




**AL 244**

Replacing Fiat / Marelli  
Servicing 632 213 00, 30, 632 214 01,  
-31




**AL 396**

Replacing Fiat / Marelli  
Servicing 636 335 01, 636 336 01,  
636 338 01, 636 339 01




**AL 245/A**

Replacing Fiat / Marelli  
Servicing 63600400,  
63600504, 06, 07




**AL 3030**

Replacing Fiat / Marelli  
Servicing 636 016 00, 636 017 00,  
855 400 71, 855 403 71



**AL 310**

Replacing Fiat / Marelli  
Servicing 855 300 10, 855 303 30,  
855 302 20, -90




**AL 3078**

Replacing Fiat / Marelli  
Servicing 85540981, -855 410 10




**AL 268**

Replacing Hitachi  
 Servicing Short body  
 Plate 24.2 x 2 mm  
 Shaft 40.5 mm




**AL 216**

Replacing Iskra  
 Servicing 16, 905, 423 - 426  
 Plate 15.1 x 36.1 x 2 mm  
 Shaft 44.5 mm




**AL 300**

Replacing Lucas  
 Servicing  
 TOB 109, 121, 128, 134, 159,  
 162, 167, 172, 196, TPB 103,  
 104, 106, 109, 118, 119, 131




**AL 269**

Replacing Hitachi  
 Servicing Long body  
 Plate 24.2 x 2 mm  
 Shaft 40.5 mm




**AL 316**

Replacing Lucas  
 Servicing 76753, 76781,  
 76864 Early Type




**AL 522**

Replacing Nippondenso  
 Servicing 1.0, 1.2, 1.4, 2.0 KW  
 Gear Reduction Contact Kit  
 Toyota vehicles with petrol engines




**AL 249**

Replacing Lada  
 Servicing 2108 - 370 - 8805




**AL 322**

Replacing Lucas  
 Servicing M 50, 76833, 76834, 76835,  
 76836, 76854, 76862, 76864,  
 76865, 76869, 76881, 76900,  
 76910, TOB110, - 183




**AL 528**

Replacing Nippondenso  
 Servicing 1.2, 1.4 KW Gear  
 Gear Reduction Contact Kit  
 Subaru vehicles with petrol engines



**AL 325**


Replacing Lucas  
 Servicing 76755, 76976, 76981,  
 Early type




**AL 326**  
 Replacing Lucas  
 Servicing Used with  
 54640364 Cap  
 76474, 76490, 76727




**AL 375**  
 Replacing Lucas  
 Servicing TOB130,-135,-140,-157,-171,  
 -181,-184,-77252




**AL 3092**  
 Replacing Magneton 443930157560  
 Servicing 443937150241  
 443930157971 Skoda




**AL 327**  
 Replacing Lucas TWB 100  
 Servicing Used with  
 (54330169 - AL 312)  
 TOB 100, 151, 153




**AL 500**  
 Replacing Nippondenso  
 Servicing 1.4 KW Gear  
 Reduction Contact Kit  
 Toyota vehicles with petrol engines




**AL 501**  
 Replacing Nippondenso  
 Servicing 1.4 KW Gear  
 Reduction Contact Kit  
 Honda vehicles with petrol engines




**AL 329**  
 Replacing Lucas 54647861  
 Servicing 77171, 77177, 77192, 77194,  
 77204, TBP 132, -140, -146




**AL 503**  
 Replacing Nippondenso  
 Servicing 2.0, 2.5 KW  
 Contact Kit  
 Toyota vehicles with petrol engines



**AL 504**  
 Replacing Nippondenso  
 Servicing 1.2, 1.4, 2.0 KW  
 Contact Kit  
 Toyota vehicles with petrol engines



**AL 330/B**  
 Replacing Lucas  
 Servicing M 50, York, 76901, 76936,  
 76985, 76997, 77008, 77027, 77054,  
 77163, TOB123,-125




**AL 506**  
 Replacing Nippondenso  
 Servicing 1.0 KW Gear  
 Reduction Contact Kit  
 Daihatsu vehicles with petrol engines

PICTURE  
 NOT AVAILABE  
 AT THE TIME OF PRINTING.

**AL 508**  
 Replacing Nippondenso  
 Servicing Reduction Contact Kit  
 Caterpillar






**AL 3014**

Replacing Mitsubishi  
 Servicing  
 Shaft 26 mm  
 30 x 16 x 2.5 mm  
 All late short type




**AL 232**

Replacing Paris Rhone  
 Servicing CED 67,-601,-615,-616,-621,  
 18 x 46 x 3 mm.




**AL 279**

Replacing Paris Rhone  
 Servicing CED 417,-418,-421,-423,-427,  
 -428,-434,-435,-436,-437,-438,-439,-441,  
 -442,-444,-446,-448,-454,  
 Plate 28.3 x 14 x 2.5 mm.  
 Shaft 38.2 mm.




**AL 3054**

Replacing Mitsubishi  
 Servicing Mitsubishi  
 Mazda, Hyundai, Isuzu




**AL 235**

Replacing Paris Rhone  
 Servicing CED 443, 96573,  
 28 x 14 x 2.5




**AL 280**

Replacing Paris Rhone  
 Servicing CED 501, 510, 512, 513




**AL 3069**

Replacing Mitsubishi  
 Servicing  
 30 x 16 x 2.5 mm




**AL 241**

Replacing Paris Rhone  
 Servicing 182148,  
 18 x 46 x 5 mm.




**AL 281**

Replacing Paris Rhone  
 Servicing CED 52, 53, 506,  
 33.3 x 15 x 3 mm.




**AL 3126**

Replacing Mitsubishi  
 M372 x 00471  
 Mitsubishi, Hyundai




**AL 271**

Replacing Paris Rhone  
 Servicing CED 005,058,059,  
 33.3 x 15 x 3 mm.  
 Shaft 44 mm.




**AL 282**

Replacing Paris Rhone  
 Servicing CED 514,519,  
 33.3 x 15 x 3 mm.  
 Shaft 33.5 mm.




**AL 293**

Replacing Paris Rhone  
 Servicing CED 71, 046695, 182430,  
 25 x 52 x 5 mm.




**AL 397**

Replacing Paris Rhone  
 Servicing CED 529,-538,-541,-546,  
 102217, 103794, 104594, 104694  
 Plate 33.3 x 14 x 2.5 mm.  
 Shaft 27.8 mm.




**AL 248**

Replacing Romania  
 Servicing DM 2130,  
 DM 2134




**AL 297**

Replacing Paris Rhone  
 Servicing CED 517,-518,-521,-528,  
 -533,-540,099378,099932, 101062,  
 102190, 102849, 104327




**AL 3071**

Replacing Paris Rhone  
 Servicing 15 x 33 x 3 mm.



**AL 3094**

Replacing Sawafuji  
 Servicing 1350 - 097 - 00X9  
 135010100X9 / 1350 - 101 - 11X9




**AL 373**

Replacing Paris Rhone  
 Servicing CED 468  
 33.3 x 14 x 2.5 mm.  
 Shaft 33.2 mm.




**AL 1519**

Replacing Nippondenso  
 Servicing Isuzu vehicle  
 With diesel engine




**AL 374**

Replacing Paris Rhone  
 Servicing CED 514, 519,  
 Plate 33.3 x 15 x 3 mm.  
 Shaft 33.5mm.




**AL 1534**

Replacing Nippondenso  
 Servicing Toyota vehicle  
 With petrol engines




**AL 8**

Replacing Nippondenso  
Servicing 8 mm. 1.D.  
terminal insulatör  
1.0,1.4,2.0 kW.




**AL 1267**

Replacing Nippondenso  
Servicing 2.5 kW. Up  
I.D,14 mm, W.14.7 mm, 0.0.25,9/30.1 mm  
Insulator




**AL 256**

Replacing Nippondenso 28017-19502  
Servicing 1.4 kW. Gear reduction  
Contact kit




**AL 9**

Replacing Nippondenso  
Servicing 1.0, 1.4, 2.0 Kw  
Gear Reduction Starters  
1.0, 11.5 mm insulator



**AL 125**

Replacing Nippondenso  
Servicing Fixed with  
M8 Stud copper 2.5 mm.  
Gear reduction contact kit




**AL 257**

Replacing Nippondenso 28017-19500  
Servicing 1.4 kW. Gear reduction  
Contact kit




**AL 1213**

Replacing Nippondenso  
Servicing  
14 mm. I.D, insulatör inside terminal  
2.5, 3.0, 4.0, 4.5, 5.5 kW.




**AL 197**

Replacing Nippondenso  
Servicing  
Chrysler 3.0L- 3.3 Left & Right  
(Complete AL 197) 1.3, 1.4, 2.9 KW  
Left AL 197B Right AL 197 A




**AL 266**

Replacing Nippondenso  
Servicing Fixed with  
M 10 Stud copper 2.5 mm.  
Gear reduction contact kit




**AL 1214**

Replacing Nippondenso  
Servicing  
10 mm. I.D, insulatör external terminal  
2.5, 3.0, 4.0, 4.5, 5.5 kW.




**AL 207**

Replacing Nippondenso  
Servicing 128000 - 7380,  
128000 - 7381, 28100 - 50020  
Lexus




**AL 1205**

Replacing Nippondenso  
Servicing 128000 - 2570  
128000-9300, 22800-0220  
Late model with short  
field case Chrysler



**AL 1206**

Replacing Nippondenso  
 Servicing 128000 - 8500  
 228000-0360, 1700  
 Chrysler, Dodge




**AL 1210**

Replacing Nippondenso  
 Servicing 028000 - 8230,  
 8380, 9820, 9830  
 128000 - 1050, 1770, 2690  
 Caterpillar




**AL 1216**

Replacing Nippondenso  
 Servicing 128000 - 7380,  
 7381, 28100-50020  
 Lexus




**AL 1207**

Replacing Nippondenso  
 Servicing 128000 - 7380  
 128000-7381, - 28100-50020  
 Lexus




**AL1211**

Replacing Nippondenso  
 Servicing 028000-6040,  
 7190, 8000, 9321  
 Kia, Acura




**AL1217**

Replacing Nippondenso  
 Servicing  
 128000-65750  
 TOYOTA COROLLA, HARLEY DAVIDSON



**AL 1208**

Replacing Nippondenso  
 Servicing 028000 - 7740, 8130,  
 8320, 8370, 8430, 9030  
 128000 - 0140, 0170, 0180, 0200  
 Isuzu, Toyota, Chreysler




**AL1212**

Replacing Nippondenso  
 Servicing 053400-3931  
 5120, 5150, 7270, 7650  
 Subaru, Daihatsu




**AL 1260**

Replacing Nippondenso  
 Servicing  
 Fixed with M10 stud, copper 3 mm.  
 Contact kit



**AL 1209**

Replacing Nippondenso  
 Servicing 028000 - 6040  
 7190, 8000, 9321  
 Honda, Toyota




**AL1215**

Replacing Nippondenso  
 Servicing 128000 - 5750  
 M8. Toyota



**AL 1261**

Replacing Nippondenso 28017-19511  
 Servicing 2.4 kW. Gear reduction  
 Contact kit



**AL 1262**

Replacing Nippondenso 28017-19512  
 Servicing 2.4 kW. Gear reduction  
 Contact kit



**AL 1266**

Replacing Nippondenso 028099-2790,  
 3780,-7100  
 Servicing 028000 -6870, 28100-54032  
 Toyota, Isuzu light trucks  
 2.5 kW. Contact Kit




**AL 1531**

Replacing Nippondenso  
 Servicing Solenoid contact set  
 2.5 mm Thick 8mm Hole  
 16 x 22 mm Wide




**AL 1263**

Replacing Nippondenso 028099-3160  
 Servicing 028000 -6870,- 5510  
 Isuzu, Toyota light trucks  
 2.5 kW. Contact kit




**AL 1269**

Replacing Nippondenso  
 Servicing  
 2.5, 4.5 kW Starters  
 TOYOTA



**AL 3059**

Replacing Nippondenso  
 Servicing 53400 - 3840,  
 3890, 3932, 4432, 5240, 5282, 5480, 7130




**AL 1264**

Replacing Nippondenso 128099-3170  
 Servicing 2.5, 4.5 kW.  
 Contact Kit




**AL 1385**

Replacing Nippondenso  
 Servicing  
 Late G/R Starters  
 128000 -7010, 500, 810, 8030  
 128000 -8400, 9710, 720, 730



**AL 3082**

Replacing Nippondenso  
 Servicing  
 Harley Davidson




**AL 1265**

Replacing Nippondenso 028099-2690  
 Servicing 2.5, 4.5 kW.  
 Contact Kit




**AL 1390**

Replacing Nippondenso  
 Servicing  
 1.2 kW Starters  
 128000 -5691, 7120, 21, 22, 40  
 128000 -8110, 8111, 9380  
 228000 - 0220




**AL 1291**

Replacing Bosch 2006 382 176  
 Servicing 0001 410 015,-021 -029,-041  
 -078,-090,-091,-117,-118,-0001 411 009,  
 -014,-022,-023,-029,-0001 413 001,-004  
 9 teeth Steel




**AL 1305**

Replacing Bosch 2006 382 154  
 Servicing 0001 410 035,-094,  
 0001 415 007, 0001 416 004,  
 0001 417 010  
 13 teeth Steel



**AL 1**

Replacing Bosch 4  
 Servicing Nylon washer  
 32.5 x 57 mm.




**AL 1292**

Replacing Bosch  
 Servicing 10 teeth  
 Special Application




**AL 1224**

Replacing Bosch 1902 300 090  
 Servicing Key for  
 FKB drives




**AL 2**

Replacing Bosch  
 Servicing Nylon washer  
 29 x 51 mm.




**AL 1293**

Replacing Bosch 2006 382 156  
 Servicing 0001 410 032,-037 -044,-046,  
 0001 411 005,-010,-012,-013,  
 0001 413 018,-0001 414 008,-019,-020  
 11 teeth steel




**AL 31**

Replacing Bosch  
 Servicing Nylon washer  
 32.5 x 43 mm.




**AL 1294**

Replacing Bosch 2006 382 162  
 Servicing 0001 410 092,-0001 411 001,  
 -002,-006,-020,-028,-031,-032,-035,  
 0001 415 024, 0001 416 018,-051  
 12 teeth Steel




**AL 32**

Replacing Bosch  
 Servicing Nylon washer  
 32.5 x 42 mm.




**AL 33**

Replacing Bosch  
 Servicing 2006 209 423,-450,-530,-532,  
 -537  
 32.5 x 43.02  
 Nylon washer




**AL 966**

Replacing Lucas 54293375  
 Servicing M78R, M80R  
 39 tooth  
 Outer gear




**AL 839**

Replacing Mitsubishi M135C00171  
 Servicing M1T70481,-70681,-70685,  
 -70686,-70687,-70881,-71081,-71281,  
 -71481,-71781,-71841,-71881,-72081,  
 -72086,-72181,-72182,-72581,-72981,  
 Internal gear




**AL 967**

Replacing Lucas 54293830  
 Servicing M 78R, M80R, 26803, 26911  
 26912, 26913, 26914, 26917, 26918,  
 26920, 26922, 26924, 26929  
 Plastic Gear  
 40 tooth




**AL 14**

Replacing Bosch  
 Servicing Nylon Insert Kit  
 2006209530, 531, 532,  
 533, 537, 538 Man, Volvo




**AL 1348**

Replacing Marelli 54294580  
 Servicing M70 R  
 Fiat Tempra, Tipo, Palio




**AL 34**

Replacing Bosch  
 Servicing 2006 209 333, 334, 335, 336,  
 -338,-341,-342,-343,-344,-345,-346,  
 -347,-348,-366,-372,-398,-425,-426,  
 -431,-435,-436,-437,-438,-440,-441,  
 -443,-444,-445,-447,-448,-457,-459  
 Nylon Insert Kit




**AL 1558**

Replacing Marelli  
 Servicing E70R  
 Fiat Uno, Siena, Bravo




**AL 62**

Replacing Bosch 1001 933 106  
 Servicing 0001 107... , 0001 108... ,  
 0001 113... , 0001 114... ,  
 Gear reduction starters




**AL 613**

Replacing Bosch 1001 933 104  
 Servicing 0001 317 007,- 008,- 013,-014,  
 -015,-020,-021,-022, -023,-024,-025




**AL 615**

Replacing Bosch  
 Servicing 0001 107..., 001 108...,  
 0001 110...  
 L. 29 mm.  
 Support Lever




**AL 160**

Replacing Bosch 2001 933 175  
 Servicing 0001 358..., 0001 359...,  
 0001 360... , 0001 362... ,




**AL 616**

Replacing Bosch  
 Servicing 0001 108..., 001 110...,  
 L. 33 mm.  
 Support Lever




**AL 611**

Replacing Bosch 101 933 103  
 Servicing 0001 312 108,-109




**AL 1550**

Replacing Bosch 1001 933 104  
 Servicing 0001 317...  
 Lever with support




**AL 617**

Replacing Bosch  
 Servicing 0001 218...  
 L. 31 mm  
 Support Lever




**AL 612**

Replacing Bosch 1001 933 101  
 Servicing 0001 208 513,- 521,-709,-710,  
 -711,-712,-0001 211 500,-501,-502,-503,  
 -504,-505,-510,-511,-512,-513,  
 0001 211 525,-526,-533,-535,-536,  
 0001 218... , 0001 219...



**AL 614**


Replacing Bosch  
 Servicing 0001 107...  
 L. 23.9 mm.  
 Support Lever



**AL 618**


Replacing Bosch  
 Servicing 0002 218...  
 L. 27.8 mm.  
 Support Lever






### AL 963

Replacing Delco Remy 10456464  
Servicing 28 MT  
1113266,-67,-73,-74,-75,  
1113276,-79,-81,-86,-87,-97



### AL 1240

Replacing Fiat Marelli 72139301  
Servicing MT67, MT68, MT71, MT72




### AL 187

Replacing Iskra 16.905.408  
Servicing 11.130.007,-029,-034,-085,  
-102,-155,-162,-166,-209,-217,-218  
AZE 0303,-0304,-0305,-0308,-3502,  
-3404,-3506,-3508,-3511,-3512,-3513




### AL 63

Replacing Fiat Marelli 748 812 80  
Servicing E95, 4392459, 4412878  
4470378, 632 213 00,-02,-03,-04,-05,-06,  
-07,-08,-09,-30,-32




### AL 962

Replacing Ford & Mitsubishi  
E5PZ - 11067 A  
Servicing M3T 90071,-72  
Ford 9,9, & 7,3 Diesel



### AL 116


Replacing Fiat Marelli 748 614 60  
Servicing 632207,,  
632208,,632209,,



**AL 118**

Replacing Lucas 60600861  
Servicing M127


27501 27502 27503 27504 27506  
27507 27508 27509 27510 27512  
27513 27514 27515 27516 27518  
27519 27520 27522 27523 27524  
27525 27526 27531 27533 27537  
27539 27540 27541 27542 27543  
27545 27547 27553 27556 27558  
27559 27563 27564 27565 27567  
27568 27570 27571 27572 27590  
27596



**AL 956**


Replacing Lucas 54268543  
Servicing M127

27500 27511 27528 27554 27569



**AL 53**


Replacing Paris Rhone  
Servicing D10E, D11E  
Spacer for lever



**AL 119**


Replacing Lucas 60600649  
Servicing M 50

27407 27409 27410 27411 27412  
27413 27414 27415 27416 27417  
27419 27420 27421 27422 27423  
27425 27426 27428 27431 27432  
27433 27435 27436 27446 27449  
27459 27460 27461 27463 27465  
27468 27470 27474 26400 26412  
26413



**AL 121**

Replacing Lucas 60600861  
Servicing M113, M50, M127  
Shift lever link



**AL 1201**


Replacing Paris Rhone  
Servicing D9E, D10E  
Shift lever link

(N)




**AL 151**

Replacing Lucas 54243847  
Servicing M50,  
Shift lever link



**AL 8205**


Replacing Paris Rhone / Valeo 594068  
Servicing D6 RA...  
Shift lever



**AL 140**


Replacing Lucas 54243847  
Servicing M 50

26274, 26294 26316 26329 26336  
26342 26343 26344 26345 26352  
26357 26358 26365 26366 26369  
26376 26388 26398 26404 26407  
26410 26411 26414 26416 26423  
26430




**AL 809**

Replacing Bosch 1004 336 125,-907,-954  
 Servicing 0001 108 001,-004,-007,-009,  
 -010,-011,-012,-013,-016,-018,-019,  
 -020,-023,-024,-025,-026,-028,-030,  
 -031,-032,-033,-035,-037,-038,-039  
 W/ springs and brushes




**AL 772**

Replacing Bosch 2004336027  
 Servicing  
 0001362034,035,036,037,038,039,040,041  
 042,043,045,046,047,048,049,050,051,052  
 053,057,058,059,060,061,062,063,064,067  
 069,070,071,072,073,074,075,076,077,079  
 081,082,083,084,085,086,088,089,090,092  
 093,094,095,097,100,102,602,603,606,607  
 Without brushes & springs  
 Brush BSx97




**AL 788**

Replacing Bosch 2004335070  
 Servicing BNG Starters  
 0001401041, 049, 052, 057, 060, 066  
 Without brushes & springs  
 Brush BSx35 (12v)




**AL 873**

Replacing Bosch 1004 336 846,-917,-928  
 Servicing 0001 112 003,-004,-010,-011,  
 0001 114 005,-006,-009,-010  
 12V.  
 W/ springs and brushes



**AL 816**

Replacing Bosch 2004336031  
 Servicing  
 001638001,002,003,005,007,009,010,011,  
 012,013,016,018,019,020,021,023,024,025,  
 026,027,028,030,034,036,038,060,  
 Without brushes & springs  
 Brush BSx135-145 (24v)




**AL 796**

Replacing Bosch 2004335004  
 Servicing BNG Starters  
 0001402054,055,057,058,059,060,  
 069,071,075,079,081,083,085  
 Without brushes & springs  
 Brush BSx34 (24v)



**AL 809/A**

Replacing Bosch  
 Servicing 0001 108...  
 Brush holder




**AL 1389**

Replacing Bosch  
 Servicing Terminal with  
 positive brushes BSX 159-160  
 0001108... starters




**AL 874**

Replacing Bosch  
 Servicing 0001 107...,0001 112...,  
 0001 113..., 0001 114...  
 Brush holder




**AL 817**

Replacing Bosch 2004336028  
 Servicing  
 0001367001,002,003,004,005,006,007,008,  
 009,010,011,012,013,014,015,016,018,021,  
 022,023,024,025,027,028,029,030,032,033,  
 034,036,039,044,045,046,048,050,055,056,  
 064,065  
 Without brushes & springs  
 Brush BSx134-144 (12v)




**AL 1391**

Replacing Bosch  
 Servicing Terminal with  
 negative brushes BSX 159-160  
 0001108... starters



**AL 8644**

Replacing Bosch 2004 336 051  
 Servicing 0001 420 001,-002,  
 -003,-005,-008,-009,-010,-015  
 With springs




**AL 900**

Replacing Ducellier  
 Servicing  
 534051 534052 534057  
 Without Brushes & springs  
 Brush US x 91 - 92




**AL 59**

Replacing Ducellier  
 Servicing  
 Insulator for brush gear AL 900




**AL 694**

Replacing Fiat / Marelli 832 212 41  
 Servicing E80-0.8/12, E80-1/12  
 632 228 31,-32,-33,-37, 632 230 33  
 Without brush & springs  
 Brush JS x 35 - 37




**AL 708**

Replacing Fiat / Marelli 748 811 51  
 Servicing E95-0.9/12, E95-1/12  
 Without Brushes & springs  
 Brush JS x 21 - 22




**AL 898**

Replacing Fiat / Marelli 721 641 01  
 Servicing MT71AB, DB, TA, MT74H, AA,  
 632 171 26,-48,-54, 632 174 07,-08,-10  
 Without Brushes & springs  
 Brush 12v MASX15-16




**AL 899**

Replacing Fiat / Marelli 721 641 02, 819 04 02  
 Servicing MT72AB, 632 172 26  
 Without Brush & springs  
 Brush 24v MASX27-28




**AL 1311**

Replacing Fiat Marelli 721 641 01  
 Servicing MT71AB, DB, TA, MT74H, AA  
 632 171 26,-48,-54, 632 174 07,-08,-10  
 With Brushes & springs  
 Brush MASX25-26




**AL 1312**

Replacing Fiat Marelli 721 641 02, 819 04 02  
 Servicing MT24AB, 632 172 26  
 632 171 26,-48,-54, 632 174 07,-08,-10  
 With Brushes & springs  
 Brush 24v MASX27-28




**AL 331**

Replacing Lucas  
 Servicing M35J, 5M90; 8M90,9M90  
 Brush LASX37-38-39  
 Spring AL 133




**AL 706**

Replacing Lucas TAT104  
 Servicing 619 24008  
 Without Brushes & springs  
 Brush LASX36




**AL 969**

Replacing Lucas  
 Servicing Insulating  
 Kit for M50 Brush holders




**AL 746**

Replacing Lucas 54245374  
 Servicing M50 & M127  
 Without brush & springs  
 Brush LASX36




**AL 747**

Replacing Lucas 54244775  
 Servicing M50  
 Without brush & springs  
 Brush LASX15-16




**AL 797**

Replacing Lucas 54266043  
 Servicing 2M113, 3M113, 27403, 27405  
 Without brush & springs  
 Brush LASX15-16




**AL 1314**

Replacing Lucas 54245374  
 Servicing M50 & M127  
 With brush & springs  
 Brush LASX36




**AL 1315**

Replacing Lucas 54244775  
 Servicing M50  
 With brush & springs  
 Brush LASX15-16




**AL 1316**

Replacing Lucas 54266043  
 Servicing 2M113, 3M113, 27403, 27405  
 With brush & springs  
 Brush LASX15-16




**AL 933**

Replacing Paris Rhone  
 Servicing D8E..., D9E...  
 Brush PSX 130




**AL 934**

Replacing Paris Rhone  
 Servicing D8E..., D9E...  
 Brush PSX 133




**AL 943**

Replacing Paris Rhone 101589  
 Servicing 432566  
 Renault R5 - R9 - R11  
 Brush PSX 133




**AL 948**

Replacing Paris Rhone 594070, 183957,  
 186381  
 Servicing D6RA5,-6,-12,-16,-18,-20,-61  
 Gear reduction starters  
 Brush PSX 144-145




**AL 949**

Replacing Paris Rhone 594072, 181961  
 Servicing D6RA8,-10  
 Gear reduction starters  
 Brush PSX 146-147




**AL 1152**

Replacing Paris Rhone 594070, 183957,  
 186381  
 Servicing D6RA5,-6,-12,-16,-18,-20,-61  
 Second Quality color black  
 Brush PSX 144-145




**AL 1153**

Replacing Paris Rhone 594072, 181961  
 Servicing D6RA8, -10  
 Second Quality color black  
 Brush PSX146-147




**AL 8630**

Replacing Hitachi 2114-79 001  
 Servicing S114-252,-252A,-253A,-254A,  
 -357A,-374B,-393  
 12 V  
 W/springs and negative brushes




**AL 8634**

Replacing Hitachi 2130-1306  
 Servicing S13-62,-62B,-64,-69,-83,-84,-89A,  
 -89B,-92A,-100,-104,-106B,-107A,-114,-121  
 12 V  
 W/springs and negative brushes




**AL 8637**

Replacing Hitachi 2114-23106  
 Servicing S114-750,-758,-762A,-765,-766A,  
 -775A,-780,-800,-A, B,-801A,-B,-C,-804,-805,  
 -808,-818A,-850  
 12 V  
 W/springs and negative brushes




**AL 951**

Replacing Mitsubishi M649T04972  
 Servicing M3T66071,-66072,-66073,-66074,  
 -67171,-67172,-Ford, Mazda, Yale  
 With brush & springs  
 Brush M648C25671 -72



**AL 986**

Replacing Mitsubishi  
 Servicing Same AL  
 AL 951 Brush holder  
 only Armature hole 34 mm




**AL 1259**

Replacing Mitsubishi M649T04972  
 Servicing M3T66071,-66072,-66073,  
 -66074,-67171,-67172, Ford, Mazda, Yale  
 Without brush & springs




**AL 8625**

Replacing Mitsubishi M649T02171  
 Servicing M2T60071,-60072,-60073,-60171  
 W/springs and negative brushes




**AL 8626**

Replacing Mitsubishi M649T05071  
 Servicing M2T54271, M2T65271  
 12 V  
 W/springs and negative brushes



**AL 8629**

Replacing Mitsubishi M649T04471  
 Servicing M2T50181,-50585,-51085,-52181,  
 -52681,-52881,-52882,-53181,-53781,-53785,  
 -58581  
 W/springs and negative brushes




**AL 8631**

Replacing Mitsubishi M649T01671  
 Servicing MIT74081,-74181,-74281,-74481  
 12 V. PMGR  
 W/ springs and negative brushes



**AL 8632**


Replacing Mitsubishi M649T01571  
 Servicing M2T40081  
 12 V  
 W/springs and negative brushes



(N)


**AL 8667**

Replacing Mitsubishi M649T20471  
Servicing M2T84071,-84171,-84271,-84371,  
-84571,-84671,-87071,-87171  
12 V  
W/springs and negative brushes



**AL 1580**


Replacing Nippondenso  
Servicing 228000 - 4960, 4961  
W/ springs and negative brushes



(N)

**AL 8627**


Replacing Nippondenso 028510 - 0500  
Servicing 028000 - 5510,-5860,-6290,-6870,  
-7240,-8070, 128000 - 1790,-3080  
12 / 24 V  
W/springs and negative brushes



(N)

**AL 8628**


Replacing Nippondenso 028510 - -0640  
Servicing 028000 - 7000,-7740,-7790,  
-8130,-9830, 128000-0570,-0960,-1040  
12 V  
W/springs and negative brushes



(N)

**AL 8635**

Replacing Nippondenso 028510 - 0660  
Servicing 028000 - 4550,-5900,-5910,  
-6001,-6362,-6620,-7191,-7351,-7560,-7620,  
-8050,-8220,-8290,-8320,-8432  
12 V  
W/springs and negative brushes



(N)

**AL 8636**


Replacing Nippondenso 028510 - 5190  
Servicing 128000 - 5210,-5211,-5680,  
-5682,-6420,-6422,-6720,-6721,-7400  
W/springs and negative brushes



(N)

**AL 8638**


Replacing Nippondenso 028510 - 0880  
Servicing 128000 - 2450,-2470,-2740,  
-3361,-4250,-4682,-4683,-4684,-4685  
24 V  
W/springs w/o brushes



(N)

**AL 8669**


Replacing Nippondenso 028514 - 5020  
Servicing 128000 - 2520,-2631,-2800,  
-2820,-2980,-3090,-3250,-3260,-3530  
W/o springs and brushes



(N)

**AL 8686**


Replacing Nippondenso 028510 - 5010  
Servicing 128000 - 0832,-5350,-5760,  
-9560, 228000 - 0200,-0391  
12 V  
W/springs and negative brushes



(N)

**AL 8645**


Replacing Sawafuji 1331 - 039 - 00X0  
Servicing 0350 - 552 - 0311,-0324,-0334,  
-0363,-0415, 0350 - 602 - 0091,-0114,  
-0135,-0144,-0211,-0220,-0232,-0260,  
-0314,-0320,-0330,-0335,-0510  
W/springs and negative brushes



(N)

**AL 8670**


Replacing Sawafuji 1331 - 039 - 10X0  
Servicing 0350 - 602 - 0250,-0258  
24 V 6 kW  
W/springs and negative brushes



(N)


**AL 8674**

Replacing Sawafuji 1331 - 043 - 00X0  
Servicing 0350 - 702 - 0224,-0234,-0245,  
-0265,-0273,-0284,-0293,-0314,-0324,  
-0334,-0350,-0360,-0370,-0351 - 702 - 0512  
W/springs and negative brushes




**AL 888**

Replacing Delco Remy 10456456  
 Servicing 28 MT  
 Without springs & brushes




**AL 8639**

Replacing Remy 1945849  
 Servicing 50 MT  
 12 brushes type  
 W/ springs, w/o brushes




**AL 8640**

Replacing Remy 1948515  
 Servicing 40 MT  
 8 brushes type  
 W/ springs, w/o brushes




**AL 8641**

Replacing Remy 10468705  
 Servicing 37 MT, 41 MT  
 W/ springs, w/o brushes




**AL 8642**

Replacing Remy 1987172, 1988323  
 Servicing 37 MT  
 W/ springs, w/o brushes




**AL 8649**

Replacing Nikko 0-23750-0120  
 Servicing 0-23000,-1031,-1033,-1050,  
 -1270,-11290,-1310,-1320,-1330,-1360  
 W/ springs, w/o brushes




**AL 8668**

Replacing Nikko 0-23750-0220  
 Servicing 0-23000-0081,-0091,-0120,-0172,  
 -0173,-0210,-0260,-0262  
 W/ negative brushes & springs



**AL 8675**


Replacing Nikko  
 Servicing 0-23000 - 6250  
 W/ springs  
 24v 7.5 KW starters



**AL 8689**


Replacing Nikko 0 - 23750 - 0250  
 Servicing 0-23000 - 3150,-3160,-3170,  
 -3180,-3200,-3230,-3240,-3250,-3270  
 With negative brushes & springs






**AL 1281**

Replacing Bosch 2004 632 026  
 Servicing FKB, 0001 410 088,  
 0001 411 012, -017, 0001 416 004, -007  
 Terminal 30 M10, Terminal 31 M10  
 Terminal Kit




**AL 1317**

Replacing Bosch  
 Servicing FKB, 0001 416 010,  
 0001 417 037  
 Terminal 30 M12  
 Terminal 31 M10  
 Terminal Kit




**AL 1335**

Replacing Bosch  
 Servicing FKB  
 Terminal 30: M10  
 Terminal 31: M10 insulated  
 New Type  
 Terminal kit




**AL 1282**

Replacing Bosch  
 Servicing FKB, 0001 416 002, -038, -040,  
 -043, -062, 0001 417 001, -007, -036  
 Terminal 30 M12  
 Terminal 31 M10  
 Terminal Kit




**AL 1324**

Replacing Bosch  
 Servicing FKB  
 Terminal 30 M10  
 Terminal 31 M10  
 New Type  
 Terminal Kit




**AL 1337**

Replacing Bosch  
 Servicing FKB, 0001 417 065, -069  
 Terminal 30 M12  
 Terminal 31 M12  
 New Type  
 Terminal Kit




**AL 1306**

Replacing Bosch  
 Servicing FKB, 0001 416 001, -014,  
 -018, -028, -031, -032, -033, -039, -049, .  
 -050, -051, -053, 0001 417 013, -014  
 Terminal 30 M10  
 Terminal 31 M10  
 Terminal Kit




**AL 1325**

Replacing Bosch  
 Servicing FKB  
 Terminal 30 M12  
 Terminal 31 M10  
 New Type  
 Terminal Kit




**AL 1257**

Replacing Bosch 2001 030 034  
Servicing FKB, 0001 416 001, 006, -014,  
-018, -028, -031, -032, -033, -035, -039, -049  
-050, -051, -053, -056, -065  
M10 Bolt, Terminal 30



**AL 1283**

Replacing Bosch 2007 011 029  
Servicing  
FKB, 0001 410..., 0001 411..., 0001 413...,  
0001 414..., 0001 415..., 0001 416...,  
0001 417..., 0001 418...,  
Terminal 50, Terminal Kit




**AL 1508**

Replacing Bosch 2007 011 060  
Servicing  
FKB Starters kit  
Terminal 30 M10 insulator  
Terminal 30 M12 insulator




**AL 1271**

Replacing Bosch 2001 030 032  
Servicing 0001 417 065, -069, -075, -076  
M12 Bolt  
Terminal 30




**AL 1295**

Replacing Bosch 2004 449 088  
Servicing FKB  
0001 417065, -069  
M12 negative connection cable  
Terminal 31




**AL 1384**

Replacing Bosch 2004 449 000  
Servicing FKB  
0001 1416...0001 1417 013, 014  
M10 negative connection cable




**AL 1284**

Replacing Bosch 2003590004  
Servicing  
FKB  
M12 Bolt  
Terminal 30




**AL 1328**

Replacing Bosch 2007011070  
Servicing FKB, 0001 410 029, -062,  
0001 416 001, -002, -003, -004, -005, -006,  
-007, -008, -009, -010, -011, -012, -013,  
Terminal 50, Terminal Kit




**AL 1602**

Replacing Bosch 2001 030 034  
Servicing FKB 0001 416 001, -006, -014, -018,  
-028, -031, -032, -033, -035, -039, -049, -050, -051,  
-053, -056, -065 M10 (Terminal 30)



**AL 1334**

Replacing Bosch  
Servicing  
FKB  
M10 Bolt  
Terminal 30




**AL 1346**

Replacing Bosch 2911 061 301  
Servicing FKB, M10 Bolt  
Terminal 31



**AL 307**

Replacing Lucas 54252850  
 Servicing M35J, M35G,  
 Field coil terminal complete




**AL 555**

Replacing Mitsubishi  
 Servicing M3T90071, 72,  
 Field coil bridge thin




**AL 309**

Replacing Lucas 256746  
 Servicing M45 / M50 / M127  
 Field coil terminal complete




**AL 556**

Replacing Mitsubishi  
 Servicing M3T90071 - 72  
 Field coil bridge tick



**AL 138**

Replacing Lucas  
 Servicing M35J  
 Insulator for terminal post




**AL 557**

Replacing Mitsubishi  
 Servicing M3T90071, -72,  
 Field coil terminal




**AL 139**

Replacing Lucas  
 Servicing M35G  
 Insulator for terminal post




**AL 5**

Replacing Nippondenso  
 Servicing Bottery terminal  
 Insulator cover  
 228000-0360, 3020




**AL 29**

Replacing Nippondenso  
 Servicing S & B+  
 terminal insulator  
 128000-3500, -7500, 8030  
 1.4 KW OSGR Starters




**AL 102**

Replacing Nippondenso 053480-0380, -7220  
 Servicing Gear reduction  
 Ignition switch terminal




**AL 6**

Replacing Nippondenso 053480-7100  
 Servicing Ignition \*S\* Terminal.  
 028000-3500, -7500  
 228000-0360  
 1.4 kw OSGR type starters




**AL 30**

Replacing Nippondenso  
 Servicing Ignition  
 Switch terminal  
 22800-  
 Gear Reduction Starters




**AL 234**

Replacing Nippondenso  
 Servicing 128000-0280,  
 Ignition switch terminal  
 Honda




**AL 28**

Replacing Nippondenso  
 Servicing S & B+  
 terminal insulator  
 128000-2570, -2580  
 1.0 / 1.2 kw OSGR Starters




**AL 92**

Replacing Nippondenso  
 Servicing Early & late tepy  
 Gear reduction  
 ignition switch terminal




**AL 143**

Replacing Nippondenso 949340-0660  
Servicing Gear reduktion starters  
Blue  
Terminal cap



**AL 958**

Replacing Nippondenso 053480-0081  
Servicing 128000-2570, -2580, -3500, -4960,  
-5270, -5280, -5670, -6320.  
R terminal (Short)




**AL 144**

Replacing Nippondenso 949340-0531, 0820,  
Servicing Gear reduktion starters  
Grey  
Terminal cap




**AL 959**

Replacing Nippondenso  
Servicing 128000-  
R terminal (Long)




**AL 209**

Replacing Bosch 2000 556 056  
Servicing 0001 362 008, -034, -035, -036,  
-038, -039, -040, -041, -042, -043, -045,  
-046, -047, -048, -049, -050, -051, -052,  
-053, -057, -058, -059, -060, -061, -062,  
End cover




**AL 1318**

Replacing Bosch 1000520034  
Servicing 0001 107..., 0001 108...,  
0001 109..., 0001 110..., 0001 121...,  
0001 124..., 0001 125  
End cover




**AL 619**

Replacing Fiat / Marelli  
Servicing E80, 632 230 31, -33, -35,  
C.E. Cover




**AL 890**

Replacing Bosch 2000 520 055  
Servicing 0001 358 200, 0001 359 002,  
-003, -010, -016, -019, -025, -031, -032,  
-033, -035, -040, -050, -054, -064, -067,  
-073, -075, -084, -088, -094, -095, -097,  
C.E. Cover




**AL 903**

Replacing Ducellier  
Servicing 6219, 6220, 6227, 6231, 6247,  
6185, 532002, 532009, 532010, 532014,  
532017, 532018  
CAP




**AL 658**

Replacing Fiat / Marelli  
Servicing E85, E 95, MT71TA




**AL 891**

Replacing Bosch 2000 580 121, -127  
Servicing FKB, 0001 410 016, -017, -019,  
-021, -022, -024, -029, -035, -037, -041, -044,  
-046, -049, -050, -052, -058, -061, -062, -063,  
-067, -068, -069, -073, -075,  
C.E. Cover




**AL 599**

Replacing Fiat / Marelli  
Servicing E84, E95, MT71TA  
Gasket for cover AL 658




**AL 695**

Replacing Fiat / Marelli  
Servicing MT 68, AB, AC, MT 71  
Cover C.E.  
Made of sheet-iron




### AL 56

Replacing Hitachi 2114-4862, 23470-M8001  
Servicing 44.5 mm O.D.  
S114-146,173, 182, 315, 396, 426, 556, 605T,  
607, 617, 630




### AL 57

Replacing Lucas 54246978  
Servicing 2M100, 3M100  
Dust cover




### AL 64

Replacing Paris Rhone  
Servicing D10E  
Dust cover




### AL 105

Replacing Paris Rhone 096473  
Servicing D11E, 163, 164, 169, 172, 173,  
176, 177, 178, 187  
O.D. 33 mm Brake cap




### AL 911

Replacing Paris Rhone 075953  
Servicing D8E, D9E, D10E,  
O.D. 28 mm Brake cap




**AL 902**

Replacing Ducellier 583388, 607093  
Servicing 6135E, 6155H,K,L,Q, 616H,  
6185A,B,C, 6202A,B, 6215B,C,D, 6217B,  
Brake kit



**AL 58**

Replacing Fiat Marelli  
Servicing MT67, MT68, MT71, MT72  
Washer kit




**AL 913**

Replacing Lucas 54243852  
Servicing M50  
Brake kit




**AL 109**

Replacing Lucas  
Servicing M50  
Washer kit



**AL 901**

Replacing Elmot / Fiat / Lada 4073420-  
Servicing  
Polski Fiat, Brake



**AL 157**


Replacing Iskra 16.905.411  
Servicing AZD.....,AZE....  
Brake kit



**AL 3**


Replacing Mitsubishi  
Servicing M3T90071,-90072  
Washer kit






**AL 56**

Replacing Hitachi 2114-4862, 23470-M8001  
Servicing 44.5 mm O.D.  
S114-146, 173, 182, 315, 396, 426, 556, 605T,  
607, 617, 630




**AL 57**

Replacing Lucas 54246978  
Servicing 2M100, 3M100  
Dust cover




**AL 64**

Replacing Paris Rhone  
Servicing D10E  
Dust cover




**AL 105**

Replacing Paris Rhone 096473  
Servicing D11E, 163, 164, 169, 172, 173,  
176, 177, 178, 187  
O.D. 33 mm Brake cap




**AL 911**

Replacing Paris Rhone 075953  
Servicing D8E, D9E, D10E,  
O.D. 28 mm Brake cap




**AL 902**

Replacing Ducellier 583388, 607093  
 Servicing 6135E, 6155H,K,L,Q, 616H,  
 6185A,B,C, 6202A,B, 6215B,C,D, 6217B,  
 Brake kit



**AL 58**

Replacing Fiat Marelli  
 Servicing MT67, MT68, MT71, MT72  
 Washer kit




**AL 913**

Replacing Lucas 54243852  
 Servicing M50  
 Brake kit




**AL 109**

Replacing Lucas  
 Servicing M50  
 Washer kit



**AL 901**

Replacing Elmot / Fiat / Lada 4073420-  
 Servicing  
 Polski Fiat, Brake




**AL 157**

Replacing Iskra 16.905.411  
 Servicing AZD.....,AZE....  
 Brake kit



**AL 3**

Replacing Mitsubishi  
 Servicing M3T90071,-90072  
 Washer kit




**AL 24**

Replacing Bosch  
Servicing 0001 108 ..., 0001 110 ...,  
001 112 ..., 0001 114 ...  
Commet




**AL 657**

Replacing Bosch  
Servicing 0001 13 58..., 0001 13 59...,  
0001 13 60...  
Retainer for Armature C.E.




**AL 1198**

Replacing Bosch 2003 526 008, 032  
Servicing Thru bolt  
set for FKB Short starters




**AL 117**

Replacing Bosch 2004 631 000  
Servicing 0001 395 ..., 0001 360 ...  
Star screw




**AL 1195**

Replacing Bosch 2003 526 021, 022  
Servicing Thru bolt  
set for FKB Long starters




**AL 1547**

Replacing Bosch  
Servicing 2004 005 023, -024, -026,  
-151, -153 For FKB Armature Clutch housing




**AL 179**

Replacing Bosch 2003 311 011  
Servicing BNG shaft  
nut set



**AL 1196**

Replacing Bosch 2003 526 015  
Servicing Thru bolt  
set for FKB Middle starters



**AL 192**

Replacing Bosch 2003 123 011  
Servicing BNG, 0001 401 ..., 0001 402 ...  
Grindling




**AL 1197**

Replacing Bosch 2003 315 002  
Servicing Fixation nut  
for FKB shaft assy.



**AL 1548**

Replacing Hitachi 2240-3615  
Servicing S24-03A, -03B, -03C, S25-161  
Bearing plate



**AL 1220**

Replacing Bosch 2910 551 240  
 Servicing FKB  
 Pole screw



**AL 1276**

Replacing Bosch 2000 210 014  
 Servicing FKB  
 Gasket for cover




**AL 1223**

Replacing Bosch 2003 527 040  
 Servicing Cover Fasten  
 bolt for FKB



**AL 1279**

Replacing Bosch 2000212000 & 2004650030  
 Servicing Dust seal  
 With spring for FKB




**AL 1286**

Replacing Bosch 2003 050 076  
 Servicing FKB short, 0001 418...  
 Rod 290 mm




**AL 1272**

Replacing Bosch 2000 102 622  
 Servicing FKB  
 Washer kit




**AL 1571**

Replacing Bosch  
 Servicing 0001 230 001,-002,-003,-004,  
 -005,-006,-007,-008,-009,-011,  
 0001 231 002,-003,-004,-005,-006,-007,  
 -009,-010,-011,-012  
 End Cap




**AL 1287**

Replacing Bosch 2003 050 040  
 Servicing FKB, 0001 417...  
 Rod 310 mm




**AL 1273**

Replacing Bosch 2000 105 040  
 Servicing Washer for  
 FKB




**AL 1572**

Replacing Bosch 6033 ADC 250  
 Servicing 0001 223 013, 0001 230 002,  
 -003,-008,-009,-013,-017,-006  
 0001231002, 016



**AL 1288**


Replacing Bosch 2003 050 075  
 Servicing FKB  
 Rod 325 mm



**BSX 172-173**

Replacing Bosch 2007 014 079  
 Servicing C.E. Brushes for New type  
 FKB


(N)



**AL 1406**


Replacing Bosch 1900 210 142  
 Servicing 0001 370 ..., 0001 371...  
 40 x 2.5 mm  
 O-ring

(N)




**AL 1407**

Replacing Bosch 2000 210 095  
 Servicing 0001 370 ..., 0001 371...  
 105 x 2 mm  
 O-ring




**AL 527**

Replacing Bosch  
 Servicing  
 Paper gasket for solenoid cap  
 0331 302... Series  
 0331 303...




**AL 523**

Replacing Nippondenso  
 Servicing  
 Rubber gasket for solenoid cap




**AL 231**

Replacing Nippondenso 028065-0010  
 Servicing 128000-7390, -8210, -8310,  
 -8311, -8320, -8321, -8400, -8460, -8480,  
 -9190, -9191, -9380,  
 Rubber drain



**AL 567**


Replacing Bosch  
 Servicing  
 Rubber gasket for solenoid cap  
 0331 401... & 0331402...



**AL 524**


Replacing European Delco  
 Servicing  
 Rubber gasket for solenoid cap  
 DR901, DR903

(N)




**AL 1570**

Replacing Bosch 2003 526 051  
 Servicing 0001 370 003,-004,  
 0001 371 004,-006,-008  
 M10 / M10 x 39 mm  
 Bolt



**AL 526**

Replacing Fiat/Marelli  
 Servicing  
 44.5 x 51.5 x 3 mm  
 Gasket for solenoid cap




**AL 558**

Replacing Paris Rhone  
 Servicing D13E  
 Rubber cap for solenoids


**AL 671**

Replacing Bosch  
 Servicing 0331 403 003,-004,  
 2339 403 006,-009,-010  
 Solenoid plunger boot




**AL 171**

Replacing Fiat Marelli 901 173 04  
 Servicing BMT67, MT68, MT71, MT72  
 M10-1.5 x 11 mm  
 Pole screw




**AL 689**

Replacing Lucas  
 Servicing 2 M100, 3M100  
 Paper strip




**AL 15**

Replacing Mitsubishi  
 Servicing M3T90071, 72  
 D.E. Housing seal  
 Ford Trucks




**AL 182**

Replacing Fiat / Marelli 883323, 747 511 10  
 M10-1.25 x 9 mm  
 Pole screw




**AL 141**

Replacing Lucas  
 Servicing M35, M45, M50, M418  
 Pole shoe screw




**AL 16**

Replacing Mitsubishi  
 Servicing M3T90071, 72  
 Field housing seal  
 Ford Trucks




**AL 1396**

Replacing Fiat Marelli  
 Servicing MT71E, T  
 632 17105, 18  
 Washer for brush gear




**AL 51**

Replacing Lucas 60600020  
 Servicing M50, M127  
 Sealing mit, Large




**AL 17**

Replacing Mitsubishi  
 Servicing M3T90071, 72  
 Field Housing seal  
 Ford Trucks




**AL 136**

Replacing Lucas 54244971,  
 Servicing M50, M127  
 Sealing kit, Large



**AL 621**

Replacing Mitsubishi  
 Servicing M3T90071, 72  
 Field Housing paper  
 strip




**AL 1109**

Replacing Bosch  
 Servicing 0001 112 . . . , 0001 113 . . . ,  
 0001 114 . . .  
 Brush spring




**AL 1410**

Replacing Bosch  
 Servicing FKB  
 Metal plate for negative brush holder



**AL 91**

Replacing Paris Rhone  
 Servicing D8E . . . , D9E . . .  
 Brush spring & spring cap



**AL 1115**

Replacing Bosch  
 Servicing 0001 108 . . .  
 Gear reduction starters  
 Brush spring




**AL 1511**

Replacing Bosch  
 Servicing Terminal cap  
 Plastic black for FKB brackets




**AL 91/C**

Replacing Paris Rhone  
 Servicing D8E, D9E  
 Brush spring cap




**AL 1116**

Replacing Bosch 2004 616 007, -009  
 Servicing 0001 367 . . . , 0001 368 . . .  
 Brush spring




**AL 91/S**

Replacing Ducellier & Paris Rhone  
 Servicing AL 900  
 Brush Holder Slipping




**AL 133**

Replacing Lucas  
 Servicing 8M90, 9M90, M35J  
 Brush spring




**AL 49**

Replacing Paris Rhone  
 Servicing D9R...  
 Rubber seal




**AL 696**

Replacing Bosch  
 Servicing Same  
 1125824575 Only  
 Bearing 6203




**AL 677**

Replacing Bosch  
 Servicing 24 V 70 Amp.  
 Scania




**AL 1285**

Replacing Bosch  
 Servicing 12 V 55 Amp.  
 Universal Applications




**AL 801**

Replacing Bosch  
 Servicing 12 V 55 Amp.  
 Opel




**AL 861**

Replacing Bosch  
 Servicing 24 V 70 Amp.  
 Volvo




**AL 1517**

Replacing Bosch  
 Servicing 0120469...  
 Volvo



**AL 806**

Replacing Bosch  
 Servicing 12 V 55 Amp.  
 Peugeot



**AL 863**


Replacing Bosch  
 Servicing 24 V 70 Amp.  
 Scania



**AL 701**


Replacing Eaton  
 Servicing Axle shift  
 Motor bracket





**AL 7252**

Servicing  
Adaptation for Bosch  
gear reduction starters  
Used Lada Samara



**AL 1563**

Replacing Universal  
Servicing Engine Pulley  
12 grooves Special Product